Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
District I Energy	Minerals and Natural Resources	March 4, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-025-36642
District III 1	220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	54114 1 6, 1 (1/1 6 / 5 6 5	V3349
87505	DODER ON WELL	
SUNDRY NOTICES AND RI (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PE		State "36"
PROPOSALS.)	· · · · · · · · · · · · · · · · · · ·	8. Well Number
1. Type of Well:		5
Oil Well 🔼 Gas Well 🗌 Other		-
2. Name of Operator		9. OGRID Number
OLSEN ENERGY, INC.		16482 10. Pool name or Wildcat
3. Address of Operator 19210 Huebner Road, Suite 200, San Antonio, T		Vacuum-Grayburg/San Andres
4. Well Location	CAAS 76236	vacuum-Grayourg/San Andres
4. Well Location		1
Unit Letter L : 2310 fe	et from theSouth line and66	0 feet from the West line
Section 36	Cownship 17-S Range 33-E	NMPM Lea County
11. Elevation	on (Show whether DR, RKB, RT, GR, etc.)	
4123 GR		A Section of the Control of the Cont
Pit or Below-grade Tank Application (For pit or below-gr		
Pit Location: ULSectTwpRng		
Distance from nearest surface water Below-g	rade Tank Location ULSectTwp_	Rng;
feet from theline andfeet from	n tha line	
teet from the the and teet from the	n thenne	
teet from theine andteet from	in thenne	
		eport or Other Data 15 16 17 70
12. Check Appropriate NOTICE OF INTENTION	Box to Indicate Nature of Notice, R TO: SUBS	eport or Other Date 15 16 17 78 79 EQUENT REPORT OF: 78 79
	Box to Indicate Nature of Notice, R TO: SUBS	eport or Other Date 15 16 17 78 79 ALTERING CASING
12. Check Appropriate NOTICE OF INTENTION	Box to Indicate Nature of Notice, R TO: SUBS ABANDON REMEDIAL WORK	ALTERING CASING \
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F	Box to Indicate Nature of Notice, R TO: SUBS ABANDON	LING OPNS ALTERING CASING LANG OPNS ABANDONMENT
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE	Box to Indicate Nature of Notice, R TO: SUBS ABANDON	LING OPNS ALTERING CASING LANG OPNS ABANDONMENT
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND	LING OPNS ALTERING CASING LANG OPNS ABANDONMENT
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE	Box to Indicate Nature of Notice, R TO: SUBS ABANDON	ALTERING CASING LING OPNS A PLUGAND LING OPNS ABANDONINENT
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER:	LING OPNS A PLUGIAND ABANDONMENT CON OCO
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operation	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and	ALTERING CASING DELING OPNS A PLUCYAND ABANDONMENT DELING OPNS ABANDONMENT DELING OF THE PROPERTY OF THE PROPE
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and	LING OPNS A PLUGIAND ABANDONMENT CON OCO
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operation	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and	ALTERING CASING DELING OPNS A PLUCYAND ABANDONMENT OF HOUSE OCD
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 1/4" hole	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Attacted to 1505'. Ran 37 jts 8-5/8", 24#, LS casing the completion of the comp	ALTERING CASING ABANDONMENT ABANDONMENT Give pertinent dates, including estimated date ch wellbore diagram of proposed completion ag and set at 1505'. Cement w/480 sxs 35/65
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 1/4" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Attacted to 1505'. Ran 37 jts 8-5/8", 24#, LS casing the completion of the comp	ALTERING CASING ABANDONMENT ABANDONMENT Give pertinent dates, including estimated date ch wellbore diagram of proposed completion ag and set at 1505'. Cement w/480 sxs 35/65
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 1/4" hole	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Attacted to 1505'. Ran 37 jts 8-5/8", 24#, LS casing the completion of the comp	ALTERING CASING ABANDONMENT ABANDONMENT Give pertinent dates, including estimated date ch wellbore diagram of proposed completion ag and set at 1505'. Cement w/480 sxs 35/65
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 1/4" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Attacted to 1505'. Ran 37 jts 8-5/8", 24#, LS casing the completion of the comp	ALTERING CASING ABANDONMENT ABANDONMENT Give pertinent dates, including estimated date ch wellbore diagram of proposed completion ag and set at 1505'. Cement w/480 sxs 35/65
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 ½" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM manifold.	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and get to 1505'. Ran 37 jts 8-5/8", 24#, LS casin on 6-6-04. Circ 89 sxs cement. WOC 12'.	ALTERING CASING PLUCIAND ABANDONMENT ABANDONMENT Give pertinent dates, including estimated date ch wellbore diagram of proposed completion ag and set at 1505'. Cement w/480 sxs 35/65 Test casing to 600#. NU BOP & choke
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 ½" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM manifold. I hereby certify that the information above is thus.	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and a LE 1103. For Multiple Completions: Attain to 1505'. Ran 37 jts 8-5/8", 24#, LS casin on 6-6-04. Circ 89 sxs cement. WOC 12'.	ALTERING CASING ABANDONIMENT ABANDONIMENT ABANDONIMENT Give pertinent dates, including estimated date ch wellbore diagram of proposed completion ag and set at 1505'. Cement w/480 sxs 35/65 Test casing to 600#. NU BOP & choke
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 ¼" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM manifold. I hereby certify that the information above is thus a grade tank has been/will be constructed or closed according	Box to Indicate Nature of Notice, R TO: SUBS ABANDON REMEDIAL WORK LANS COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and general permit conditions of the co	ALTERING CASING ABANDONIMENT ABANDONIMENT ABANDONIMENT Give pertinent dates, including estimated date ch wellbore diagram of proposed completion ag and set at 1505'. Cement w/480 sxs 35/65 Test casing to 600#. NU BOP & choke
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 ½" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM manifold. I hereby certify that the information above is thus.	Box to Indicate Nature of Notice, R TO: SUBS ABANDON COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and a LE 1103. For Multiple Completions: Attain to 1505'. Ran 37 jts 8-5/8", 24#, LS casin on 6-6-04. Circ 89 sxs cement. WOC 12'.	ALTERING CASING ABANDONIMENT ABANDONIMENT ABANDONIMENT Give pertinent dates, including estimated date ch wellbore diagram of proposed completion ag and set at 1505'. Cement w/480 sxs 35/65 Test casing to 600#. NU BOP & choke
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 ¼" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM manifold. I hereby certify that the information above is time a grade tank has been/will be constructed or losed accordin SIGNATURE	Box to Indicate Nature of Notice, R TO: SUBS REMEDIAL WORK LANS COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: ns. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Attained to 1505'. Ran 37 jts 8-5/8", 24#, LS casing on 6-6-04. Circ 89 sxs cement. WOC 12'. Indicate Nature of Notice, R SUBS REMEDIAL WORK CASING TEST AND CEMENT JOB OTHER: ns. (Clearly state all pertinent details, and general state of the best of my knowledge and complete to the best o	ALTERING CASING ABANDONMENT A
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 ¼" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM manifold. I hereby certify that the information above is time a grade tank has been/will be constructed or losed accordin SIGNATURE	Box to Indicate Nature of Notice, R TO: SUBS ABANDON REMEDIAL WORK LANS COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: Ins. (Clearly state all pertinent details, and general permit conditions of the co	ALTERING CASING ABANDONMENT A
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 1/4" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM manifold. I hereby certify that the information above is thue a grade tank has been/will be constructed or closed according SIGNATURE Type or print name Homer R. Olsen E-	Box to Indicate Nature of Notice, R TO: SUBS REMEDIAL WORK LANS COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: ns. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Attained to 1505'. Ran 37 jts 8-5/8", 24#, LS casing on 6-6-04. Circ 89 sxs cement. WOC 12'. Indicate Nature of Notice, R SUBS REMEDIAL WORK CASING TEST AND CEMENT JOB OTHER: ns. (Clearly state all pertinent details, and general state of the best of my knowledge and complete to the best o	ALTERING CASING ABANDONMENT A
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 ¼" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM manifold. I hereby certify that the information above is time a grade tank has been/will be constructed or losed accordin SIGNATURE	Box to Indicate Nature of Notice, R TO: SUBS ABANDON REMEDIAL WORK LANS COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: ns. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Attained to 1505'. Ran 37 jts 8-5/8", 24#, LS casing on 6-6-04. Circ 89 sxs cement. WOC 12'. Indicate Nature of Notice, R COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: ns. (Clearly state all pertinent details, and general state of the state of	ALTERING CASING PLUS AND ABANDONMENT ABANDONMENT ABANDONMENT Begive pertinent dates, including estimated date ch wellbore diagram of proposed completion ag and set at 1505'. Cement w/480 sxs 35/65 Test casing to 600#. NU BOP & choke and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan DATE 6-7-04 Telephone No. 210-496-2466
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 ¼" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM manifold. I hereby certify that the information above is time a grade tank has been/will be constructed or closed accordin SIGNATURE Type or print name Homer R. Olsen E- (This space for State use)	Box to Indicate Nature of Notice, R TO: SUBS ABANDON REMEDIAL WORK LANS COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: ns. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Attained to 1505'. Ran 37 jts 8-5/8", 24#, LS casing on 6-6-04. Circ 89 sxs cement. WOC 12'. Indicate Nature of Notice, R COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: ns. (Clearly state all pertinent details, and general state of the state of	ALTERING CASING PLUS AND ABANDONMENT ABANDONMENT ABANDONMENT Begive pertinent dates, including estimated date ch wellbore diagram of proposed completion ag and set at 1505'. Cement w/480 sxs 35/65 Test casing to 600#. NU BOP & choke and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan DATE 6-7-04 Telephone No. 210-496-2466
12. Check Appropriate NOTICE OF INTENTION PERFORM REMEDIAL WORK PLUG AND TEMPORARILY ABANDON CHANGE F PULL OR ALTER CASING MULTIPLE COMPLETI OTHER: 13. Describe proposed or completed operatio of starting any proposed work). SEE RU or recompletion. Spud well @ 6:00 PM on 6-3-04. Drill 12 ¼" hole Poz/C + 195 sxs Class C. Plug down at 9:45 AM manifold. I hereby certify that the information above is thus a grade tank has been/will be constructed or closed accordin SIGNATURE Type or print name Homer R. Olsen E- (This space for State use)	Box to Indicate Nature of Notice, R TO: SUBS ABANDON REMEDIAL WORK LANS COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: ns. (Clearly state all pertinent details, and LE 1103. For Multiple Completions: Attained to 1505'. Ran 37 jts 8-5/8", 24#, LS casing on 6-6-04. Circ 89 sxs cement. WOC 12'. Indicate Nature of Notice, R COMMENCE DRILL CASING TEST AND CEMENT JOB OTHER: ns. (Clearly state all pertinent details, and general state of the state of	ALTERING CASING ABANDONMENT ABANDONMENT ABANDONMENT By Hoops Give pertinent dates, including estimated date ch wellbore diagram of proposed completion ag and set at 1505'. Cement w/480 sxs 35/65 Test casing to 600#. NU BOP & choke and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan DATE 6-7-04