Submit 3 Copies To Appropriate District State of New Me Office Discourse Minorale and New	
District I District I District II District III District II District II District II Distri	WELL API NO. 30-025-21023
District III OIL CONSERVATION 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Frant District IV Santa Fe, NM 87	cis Dr. STATE FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	N/A
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS.) 1. Type of Well:	7. Lease Name or Unit Agreement Name
Oil Well 🖾 Gas Well 🗌 Other	3
2. Name of Operator John L. Cox	9. OGRID Number
3. Address of Operator P.O. Box 2217, Midland, TX 79702	10. Pool name or Wildcat Lovington (Paddock)
4. Well Location	
Unit Letter <u>D</u> : 660 feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line	
Section 33 Township 16S Range 37E NMPMLovingtocounty Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3798' DF 3798' DF	
<u>Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)</u> Pit Location: ULSectTwpRng Pit typeDepth to GroundwaterDistance from nearest fresh water well	
Distance from nearest surface water Below-grade Tank Location UL	-
feet from theline andfeet from theline	
12. Check Appropriate Box to Indicate N NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON	ature of Notice, Report or Other Data SUBSEQUENT REPORT OF: REMEDIAL WORK
TEMPORARILY ABANDON	
PULL OR ALTER CASING CMULTIPLE COMPLETION	ABANDONMENT
OTHER:	OTHER:
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1.5-26-04 Spot 25 sx cmt. @ 6100' WOC & tag @ 5865'. 2.5-27-04 Circ. vell so mud gel from 5865' to surface.3.5-27-04 Spot 25 sx cmt. from 3500' to 3162'.4. 5-27-04 Sqz. 100 sx from 2050', WOC & tag @ 1808'. 5. 5-28-04 Spot 50 sx cmt. on 4-1/2" stub & 8-5/8" shoe from 460' WOC & tag @ 218'. 6. 5-28-04 Spot 20 sx from 60' to surface. 7.5-28-04 RDMO	
Install dry hole marker, clean location.	Spot 20 sx from 60' to surface. 7.5-28-04 RDMO
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan .	
SIGNATURE	AgentDATE6-08-04
Type or print name Roger Massey E-mail ad	dress: Telephone No. (432) 530-0907
(This space for State use) OC FIELD REPRESENTATIVE II/STAFF MANAGER	
APPPROVED BY <u>Law</u> , <u>TITLE</u> Conditions of approval, if any	DATEJUN 3 0 2004
	Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.