Form 3160-5 (April 2004) UNITED STATES 1625 N. French Drive DEPARTMENT OF THE INTERIOR, NM 83240 BUREAU OF LAND MANAGEMENT 5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS (2) Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.		tee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions 1. Type of Well Gas Well Oil Well Gas Well 2. Name of Operator ConocoPhillips Company	ON reverse side. 7. If Unit or CA/A MCA Unit 8. Well Name and 24 9. API Well No. 30-025-08061 11266 10. Field and Pool, Maljamar; G 0' FEL 11. County or Pari Lea Lea	or Exploratory Area rayburg-San Andres sh, State
TYPE OF SUBMISSION TYPE OF ACTION Image: Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Subsequent Report Casing Repair Practure Treat Recomplete Other Final Abandonment Notice Convert to Injection Plug and Abandon Temporarily Abandon 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration theroof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BL/MBL. Required subsequent reports shall be filed days following completion of the involved operations. If the operation recompletion or recompletion in a recompletion on accompleted. Final Abandonment Notice shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) See Attached Procedure Image: Performed up of the performed up on the example on a new interval, a Form 3160/Stalla be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) See Attached Procedure Image: Performed up of the Individual days for final inspection.) GAPPPROVED <t< th=""></t<>		
14. Thereby certify that the foregoing is true and correct Name (Printed/Typed) Tim L. Chase Signature	Title Senior Engineer Technician Date 06/23/2004	<u> </u>
THIS SPACE FOR FEDERAL Approved by Image: Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter (Instructions on page 2)	t or se Office	ent or agency of the United

* 7

•



ConocoPhillips

Proposed Plugging Procedure

MCA Unit #24 Maljamar (Grayburg-San Andres) Field Lea County, New Mexico

See attached wellbore diagrams for wellbore configuration

TA'd (12/94) w/ $4\frac{1}{2}$ " OTIS Interlock Packer w/ plug @ 3,635'; $4\frac{1}{2}$ " casing perf'd & sqzd @ 650' w/ 240 sx cmt to repair csg leak 06/73. All perfs (3,709 – 3,764') are isolated.

- Notify OCD 48 hrs prior to move in, and 4 hrs prior to plugs
- Hold daily tailgate safety meetings w/ crews
- Contact NM Digtess (1-800-321-2537, Account # 6778) minimum 48 hrs prior to move-in
- 1. Set steel pit and flow down well as needed. Deliver 3,635' 2%" workstring.
- 2. MIRU plugging equipment. ND wellhead and NU 6" 3,000# manual BOP.
- 3. RIH w/ workstring, tag packer @ 3,635'. Circulate hole w/ plugging mud and pump 25 sx C cement on packer to 3,535'. POOH w/ tubing. **GBSA Plug**
- 4. RU lubricator and RIH w/ wireline, perforate 4½" casing w/ four 1-11/16" link-jet perforating gun @ 1,930'. POOH w/ wireline, RD lubricator.
- 5. RIH w/ AD-1 packer. Load hole w/ plugging mud. Set packer. Establish rate into perforations and squeeze 35 sx C cement w/ 2% CaCl2 @ 1,930 1,830'. *Base of Salt Plug WOC & TAG.* POOH w/ tubing.
- 6. RU lubricator and RIH w/ wireline, perforate 41/2" casing w/ four 1-11/16" link-jet perforating gun @ 1,000'. POOH w/ wireline, RD lubricator.
- RIH w/ AD-1 packer. Load hole w/ plugging mud. Set packer. Establish rate into perforations and squeeze 70 sx C cement w/ 2% CaCl2 @ 1,000 – 798'. Top of Salt Plug / Casing Shoe – WOC & TAG. POOH w/ tubing.
- 8. RU lubricator and RIH w/ wireline, perforate 4½" casing w/ four 1-11/16" link-jet perforating gun @ 50'. POOH w/ wireline, RD lubricator.
- 9. ND wellhead and NU BOP, establish circulation and circulate 25 sx C cement 50' to surface. *Surface plug*
- 10. Cut off wellhead and anchors, install dry hole marker. Level location. Leave location clean and free of trash.

CURRENT WELLBORE SKETCH ConocoPhillips Company – Permian Basin Business Unit

Date: May 16, 2004 RKB @ _ 4015 4014 DF @ GL @ 4012 Subarea : Maljamar Lease & Well No. MCA Unit No. 24 Legal Description : 660' FNL & 1980' FEL, Sec. 20, T-17-S, R-32-E 12-1/4" Hole 0'-710" County : State New Mexico ea Perf @ 650' Sqzd w/240 sx Field : Maljamar (GB-SA) Date Spudded June 15, 1944 IPP: 9/1/44 API Number : 30-025-08061 248 BO, 0 BW, 0 Mcf Perf @ 650' sqz'd w/240 sx Status: Drilled as Mitchell-A No. 18 10" Hole 710'-848' 8-5/8" OD @ 848' Stimulation History: 28#, H-40 Lbs. Max Max Cmt'd w/10 sx Aquagel Interval Date Туре <u>Gals</u> <u>Sand</u> Press ISIP Rate Down 50 sx cement DRILLED WITH CABLE TOOLS 4020-4060 3/6/46 Nitroglycerin Nitroglycerin 160 Quarts 3918-3950 3/7/46 105 Quarts Open hole 3659-4080' 5/1/63 Renamed MCA Unit Unit No. 24 (unitization) 1/19/66 Run rods and tubing 2/10/67 Converted to water injection 1600 BWPD @ 300# pressure 2/15/67 Test: 1107 BWIPD @ 0 psi 9/21/67 Run 117 jts 2-3/8" Cmt lined tbg 3602', Baker Pkr @ 3605' w/12 pts tension 6/24/73 Pulled cement lined tubing; jet wash & CO to 4106' Set 4-1/2" csg @ 3992' Perf 3709'-3764' 6/28/73 6/30/73 3752-3764 7/1/73 15% NE 500 5 BS 5000 3.0 ball out 3709-3718 7/1/73 15% NE 500 4 BS 4000 4.0 3709-3764 7/1/73 TFGW 10,000 20,000 4100 1800 13.4 6/29/83 Chemical Cleanout 6/1/88 Shut-in because of pkr or casing leak 8/9/88 POH w/Guiberson pkr. RIH w/Interlock pkr 8/11/88 Placed back on injection TOC 2700' 5/21/91 Perf 4-1/2" csg @ 650' and sqz w/240 sx cmt to shut off wtr flow and communication 10/1/92 Casing Integrity Test 12/15/94 Lay down tubing on racks, load well with packer fluid 4-1/2" Otis Interlock pkr w/plug @ 3635' TEMPORARILY ABANDONED 5/14/04 Recommendation to recomplete in Yates or plug and abandon. Sundry Noticed expires 12/22/04 \boxtimes Otis Interlock Pkr @ 3635' w/plug 8" Hole 7"OD @ 3659" 20#, H-40 Cmt'd w/15 sx Aquagel and 150 sx cement Ī 3709 3713 3718 8 3752 3756 3760 == 3764 ---6-1/4" Hole 4-1/2" OD @ 3995' 9.5# Cmt'd 1st Stage w/25 sx Class C 2nd Stage: 50 sx Class C 3rd Stage: 75 sx Did not circulate TOC 2700* Formation Tops: OH 3995-4106 Yates 2125 2295' Red Bed Shale - show of gas Artesia Red Sand 3075 3689-3694 show oil and gas 3465 4035-4045 show of gas Grayburg San Andres 3825 4062 increase in gas PBTD: 3635

4080

4106

OTD

NTD

PROPOSED WELLBORE SKETCH ConocoPhillips Company -- Permian Basin Business Unit

