State of New Mexico Form C-103 Submit 3 Copies To Appropriate District Office Energy, Minerals and Natural Resources March 4, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-34353 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III STATE \square FEE 🗴 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A 7. Lease Name or Unit Agreement Name: E. O. Carson DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well X Other 2. Name of Operator 9. OGRID Number Stephens & Johnson Operating Co. 019958 3. Address of Operator 10. Pool name or Wildcat P.O. Box 2249, Wichita Falls, TX 76307-2249 Blinebry Oil & Gas (Oil) 4. Well Location line and _ Unit Letter feet from the __ feet from the line Section Township Range **NMPM** 28 21S County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached) Pit location: UL _____ Sect ____Twp ____ Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _ ___Below-grade Tank Location UL _____ Sect ____ Twp ____ Rng __ Distance from nearest surface water____ feet from the _____ line and _____ feet from the _____ line 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data SUBSEQUENT REPORT OF: NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK X PLUG AND ABANDON 🔲 REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON **CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND **ABANDONMENT** PULL OR ALTER CASING CASING TEST AND MULTIPLE COMPLETION **CEMENT JOB** 1213147576 OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. Pull rods, pump, NU BOP and pull tubing. Clean out. 2. Perforate additional Blinebry 5548' to 5922'. 3. Treat with 10,000 gal. 15% Ferchek and frac w/150,000# sand and 50,000# coated sand 4. Clean out and place on production. 5. Work is planned for August, 2004. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-