Submit 3 Copies To Appropriate District Office  State of New	Mexico Form C-103
<u>District I</u> Energy, Minerals and	
1625 N. French Dr., Hobbs, NM 88240  District II	WELL API NO. 30-025-04325
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVAT District III	IUN DIVISIUN 5 Indicate Type of Lease
1000 Rio Brazos Rd. Aztec NM 87410	Francis Dr. STATE 7 FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	M 8/505 6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WI (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN O	ELLS 7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-1 PROPOSALS.)	01) FOR SUCH Eunice Monument South Unit
1. Type of Well: Oil Well Gas Well Other Injector	8. Well Number
2. Name of Operator	9. OGRID Number
Chevron USA Inc 3. Address of Operator	10. Post serve a William
15 Smith Rd, Midland, TX 79705	10. Pool name or Wildcat
4. Well Location	
Unit Letter O: 660 feet from the South line and 1980 feet from the East line	
Section 25 Township 20-S	Range 36-E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: UL O Sect 25 Twp 20S Rng 36E Pit type Steel Depth to Groundwater 148 Distance from nearest fresh water well Over 1000	
Distance from nearest surface water Below-grade Tank Location ULSectTwpRng;	
660 feet from the South line and 1980 feet from the East line (Steel Tank)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK  ALTERING CASING	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. ☐ PLUG AND ☑
PULL OR ALTER CASING MULTIPLE COMPLETION	ABANDONMENT CASING TEST AND CEMENT JOB
OTHER:	OTHER:
13. Describe proposed or completed operations. (Clearly state	all pertinent details, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
1. Set 5 1/2 CIBP at 3650, spot 25sx from 3650-3500 (Grayburg) Tag	at 3418.
<ol> <li>Displace hole w/MLF 9.5# Brine w/12.5# gel P/BBL.</li> <li>Spot 35sx, plug from 2607-2300 (B-Salt, Yates) WOC Tag at 2295.</li> </ol>	© 03 % % 3\
<ol><li>Perf 4 holes at 1200, sqz 50sx from 1200-1000 (7 5/8 Shoe, T-Salt)</li></ol>	Tag at 969. Fag at Surf.
<ol> <li>Perf 4 holes at 330, Circ cmt from 330-Surf w/133sx (10 3/4 Shoe)</li> <li>Install dry hole marker 5-20-04.</li> </ol>	Fag at Surf.
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit of below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.	
SIGNATURETITL	E Field Supervisor DATE 5-20-04
Type or print name E-ma	uil address: Telephone No. 432-561-8600
(This space for State use)	
APPROVING THE WASHAGE WASHAGE	
APPPROVED BY HOU W. WWATITLE Conditions of approval, if any	DATE
Approved as to plugging of the Well Borell 1 1 4 200	
Liability under bond is retained until surface restoration is completed.	
	- witherer