Submit 3 Copies To Appropriate District Office District I State of New Me Energy, Minerals and Natu	aral Resources March 4, 2004
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION	WELL API NO. 30-025-04476
District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	ncis Dr. 5. Indicate Type of Lease STATE 7 FEE
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUS DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.) 1. Type of Well:	UG BACK TO A
Oil Well Gas Well Other Injector	203
Name of Operator Chevron USA Inc	9. OGRID Number
3. Address of Operator 15 Smith Rd, Midland, TX 79705	10. Pool name or Wildcat Grayburg - San Andres
4. Well Location	Grayburg - San Andres
Unit Letter H : 1913 feet from the North line and 660 feet from the East line	
Section 4 Township 21-S Range 36-E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: UL H Sect 4 Twp 21S Rng 36E Pit type Steel Depth to Groundwater 148 Distance from nearest fresh water well Over 1000	
Distance from nearest surface water Below-grade Tank Location ULSectTwpRng; 1913 feet from the North line and 660 feet from the East line (Steel Tank)	
(Steel Talik)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND
PULL OR ALTER CASING MULTIPLE COMPLETION	ABANDONMENT CASING TEST AND CEMENT JOB
OTHER:	OTHER: 122324250
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent details, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion. 1. RIH Tag 5 1/2 CIBP at 3574, spot 25sx from 3574-3400 (Grayburg-San Andres) Tag at 3354. 2. Displace hole w/MLF 9.5# Brine w/12.5# gel P/BBL. 3. Spot 25sx, plug from 2606-2400 (Yates, B-Salt) Tag at 2378. 4. Spot 25sx, plug from 1400-1200 (7 5/8 Shoe, T-Salt) Tag at 1525, re-spot w/35sx from 1525-1200, Tag at 1187 5. Perf 4 holes at 375, Circ cmt from 375-Surf w/142sx (10 3/4 Shoe) Tag at Surf. 6. Install dry hole marker 6-2-04.	
·	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.	
SIGNATURETITLE	Field Supervisor DATE 6-2-04
Type or print name Jimmy Bagley C E-mail ad	dress: Telephone No. 432-561-8600
(This space for State use)	
APPPROVED BY LOW TICKE FIELD REPRESENTATIVE II/STAFF MANAGE 1 4 2004	
Approved as to plugging of the Well Bore.	
~	Lb. o. or m to bringering or mic Mell Dole'

Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed.