Submit 3 Copies To Appropriate District Office District 1  State of New Mexico Energy, Minerals and Natural Resource	Form C-103 March 4, 2004
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210  District III  1220 South St. Francis Dr	5. Indicate Type of Lease
District IV Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name  Eunice Monument South Unit
PROPOSALS.)  1. Type of Well:	8. Well Number
Oil Well  Gas Well Other	447
2. Name of Operator Chevron USA Inc	9. OGRID Number
Address of Operator     15 Smith Rd, Midland, TX 79705	10. Pool name or Wildcat
4. Well Location	Eunice Monument Grayburg San Andres
Unit Letter G : 1980 feet from the North line and 2080 feet from the East line	
Section 22 Township 21-S Range 36-E NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: UL G Sect 22 Twp 21S Rng 36E Pit type Steel Depth to Groundwater 150 Distance from nearest fresh water well Over 1000'  Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng;	
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng;  1980 feet from the North line and 2080 feet from the East_line (Steel Tank)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
	WORK ALTERING CASING
	CE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TO COMPLETION CEMENT J	EST AND
OTHER: OTHER:	2021222324
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
2. Displace hole w/MLF 9.5# Brine w/12.5# gel P/BBL.	
<ol> <li>Spot 35sx, plug from 2900-2600 (8 5/8 Shoe, B-Salt) Tag at 2566.</li> <li>Perf 4 holes at 1600, sqz 75sx from 1600-1300 (T-Salt) Tag at 1190.</li> </ol>	(F) (S) (S)
5. Perf 4 holes at 410, Circ cmt from 410-Surf w/125sx (11 3/4 Shoe) Tag at Surf. 6. Install dry hole marker. 6/8/04	
	Some 2
I hereby certify that the information above is true and complete to the best of my kno grade tank has been/will be constructed or closed according to NMOCD guidelines , a general pe	owledge and belief. I further certify that any pit or below- rmit  or an (attached) alternative OCD-approved plan .
	d Supervisor DATE 6-8-04
Type or print name Jimmy Bagley E-mail address:	Telephone No. 432-561-8600
(This space for State use)	
- V	
APPPROVED BY	
Approved as to plugging of the Well Bore.	
Liability under bond is retained until	
S	urface restoration is completed.