Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

5. Lease Serial No. NMLC061155A

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an chandened well. Her form 2150.3 (APD) for each proposals

6. If Indian, Allottee or Tribe Name

abandoned well. Use form 3160-3 (APD) for such proposals.					O. II Malan, Inches of I		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No. NMNM71009A		
1. Type of Well ☐ Oil Well ☐ Gas Well ☑ Other: ☐ HNJECTION					8. Well Name and No. PEARSALL QN 08		
2. Name of Operator Contact: ROBERT CH			ASE mackenergycor	o.com	9. API Well No. 30-025-00842-00-S1		
3a. Address P O BOX 960 ARTESIA, NM 88211-0960 Ph: 50 Fx: 50				288 PEARSALL		ploratory	
4. Location of Well (Footage, Sec., T			11. County or Parish, and State				
Sec 5 T18S R32E NENE Trac			LEA COUNTY, NM				
12. CHECK APPE	ROPRIATE BOX(ES) TO	O INDICATE	NATURE OF	NOTICE, RI	EPORT, OR OTHER	DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	☐ Acidize	Deep	□ Deepen		ion (Start/Resume)	☐ Water Shut-Off	
Notice of Intent ■ Notice of Intent	☐ Alter Casing	☐ Frac	ture Treat	□ Reclam	ation	■ Well Integrity	
☐ Subsequent Report ☐ Casing Repair		■ New Construction		□ Recomp	olete	□ Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Change Plans ☑ Plug		□ Tempor	arily Abandon		
	☐ Convert to Injection	□ Plug Back		■ Water I	☐ Water Disposal		
testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Mack Energy Corporation Proposes to Plug well as follows: 1. Notify BLM 24 hours prior to starting plugging operations. 2. Set 100' cement plug from 3559-3459'. 3. Circulate hole w/mud gel. 4. Set 100' cement plug from 1010-910', 50' above and below 8 5/8" casing. 5. Perforate @ 60' circulate cement to surface. 6. Install dry hole marker ANERDA B.O. S. PLUG F/2900 – 2800 How well as follows: 1. Notify BLM 24 hours prior to starting plugging operations. 2. Set 100' cement plug from 1010-910', 50' above and below 8 5/8" casing. 3. Circulate hole w/mud gel. 4. Set 100' cement plug from 1010-910', 50' above and below 8 5/8" casing. 5. Perforate @ 60' circulate cement to surface. 6. Install dry hole marker ANERDA B.O. S. PLUG F/2900 – 2800 ANERDA B.O. S. PLUG F/2900 – 2800							
14. I hereby certify that the foregoing is true and correct. Electronic Submission #32437 verified by the BLM Well Information System For MACK ENERGY CORPORATION, sent to the Hobbs Committed to AFMSS for processing by LINDA ASKWIG on 06/28/2004 (04LA0216SE) Name (Printed/Typed) JERRY SHERRELL Title PRODUCTION CLERK							
							
Signature (Electronic S	Submission)		Date 06/28/	2004			
	THIS SPACE F	OR FEDERA	L OR STATE	OFFICE U	SE		
_Approved_By_GARY_GOURLEY			TitlePETROLEUM ENGINEER		EER	Date 07/09/2004	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Hobbs				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent					ake to any department or ag	gency of the United	