Submit 3 Copies To Appropriate District	State of New Mexico		Form C-	
Office	Energy, Minerals and Natural R	esources	March 4,	2004
District I 1625 N. French Dr., Hobbs, NM 88240	Differ By, 14 morals and 1 through 1	WE	LL API NO.	
District II	ON CONCEDUATION DIS	/ICION	30-025-36693	
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIV	1 7	Indicate Type of Lease	
District III	1220 South St. Francis I	Dr.	STATE FEE	
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	6.	State Oil & Gas Lease No.	
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM				
87505	•			
SUNDRY NOTICES	AND REPORTS ON WELLS		Lease Name or Unit Agreement Na	me
(DO NOT USE THIS FORM FOR PROPOSALS	TO DRILL OR TO DEEPEN OR PLUG BAC	CK TO A		
DIFFERENT RESERVOIR. USE "APPLICATIO	ON FOR PERMIT" (FORM C-101) FOR SUC		Scharbauer	
PROPOSALS.)		8.	Well Number	
1. Type of Well:	ther Water Injection Well		3	1
	mer water injection wen			
2. Name of Operator		9.	OGRID Number	
Seely Oil Company			020497	
3. Address of Operator		10.	Pool name or Wildcat	
815 W. 10 th St., Ft. Wort	h, TX 76102		EK Delaware	
4. Well Location				
	m the South line and 1980 feet from	the West line		
Section 20 Township 18S	Range 34E NMPM Lea	County		
Section 20 Township 100	I. Elevation (Show whether DR, RKI	B. RT. GR. etc.)		4.00
	3983 GL	,,,		
Pit or Below-grade Tank Application (For pit o		must be attached)	Borgers A. Const. Const	
			Distance from nearest fresh water well	-
Pit Location: ULSectTwp				
Distance from nearest surface water	Below-grade Tank Location UL	SectTwp	Rng;	
feet from theline and	feet from the line			
12 Check App	ropriate Box to Indicate Natur	e of Notice, Ren	ort or Other Data	
		CHRCE	QUENT REPORT OF:	
MOTICE OF INTE				
NOTICE OF INTE				· 🗆
NOTICE OF INTE		MEDIAL WORK		
PERFORM REMEDIAL WORK P	LUG AND ABANDON 🔲 RE	MEDIAL WORK	☐ ALTERING CASING	
PERFORM REMEDIAL WORK P	LUG AND ABANDON 🔲 RE		☐ ALTERING CASING	
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C	LUG AND ABANDON	MEDIAL WORK	☐ ALTERING CASING IG OPNS.☐ PLUG AND ABANDONMENT	
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND	☐ ALTERING CASING	
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M	LUG AND ABANDON	MEDIAL WORK	□ ALTERING CASING IG OPNS.□ PLUG AND ABANDONMENT	
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND	□ ALTERING CASING IG OPNS.□ PLUG AND ABANDONMENT	
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER:	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB THER:	□ ALTERING CASING IG OPNS.□ PLUG AND ABANDONMENT	
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and given	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT ABANDONMENT Properties of the perturbed dates, including estimates	□ □ ed date
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work)	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and given	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT ABANDONMENT Properties of the perturbed dates, including estimates	□ □ ed date
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and given	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT PLUG AND ABANDONMENT PLUG AND ABANDONMENT ABANDONMENT PROPOSED COMPAND ABANDONMENT ABANDONMENT PROPOSED COMPAND ABANDONMENT ABANDONMENT ABANDONMENT PROPOSED COMPAND ABANDONMENT AB	□ □ ed date
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion.	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and given the details and given the	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT PLUG AND ABANDONMENT PLUG AND ABANDONMENT PROPOSED TO THE PROPOSED COMPANY PROPOSED TO THE	□ □ ed date
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15.3	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and give completions: Attach	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Ve perturent dates, including estimate a wellfore diagram of proposed com-	
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15.3	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and give completions: Attach	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Ve perturent dates, including estimate a wellfore diagram of proposed com-	
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15.3	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and give completions: Attach	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Ve perturent dates, including estimate a wellfore diagram of proposed com-	
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15.3	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and give completions: Attach	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Ve perturent dates, including estimate a wellfore diagram of proposed com-	
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15.3	LUG AND ABANDON	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and give completions: Attach	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Ve perturent dates, including estimate a wellfore diagram of proposed com-	
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15.: Premium 50/ Tested csg to	HANGE PLANS CO CA CHULTIPLE CA COMPLETION CT d operations. (Clearly state all pertir. SEE RULE 1103. For Multiple Co S lb/ft & 17lb/ft csg to 6049'. Ceme 50 Pozmix w/ 6 lbs salt per sx & 3/4 cs 3500 psi. WOC	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and give completions: Attach ented with 500 sxs l of 1% CFR-III. Plu	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed company of proposed company o	d date pletion
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15 Premium 50/ Tested csg to	HANGE PLANS COMPLETION CACE OMPLETION CACE OT d operations. (Clearly state all pertin. SEE RULE 1103. For Multiple Complete to the best of the best of the best of the complete to the complete to the best of the complete to the c	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and give completions: Attach ented with 500 sxs I of 1% CFR-III. Plu of my knowledge an	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed company of proposed company o	d date pletion
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15.: Premium 50/ Tested csg to	HANGE PLANS CO CA CHULTIPLE CA COMPLETION CE d operations. (Clearly state all pertir. SEE RULE 1103. For Multiple Co S 1b/ft & 171b/ft csg to 6049'. Ceme 50 Pozmix w/ 6 lbs salt per sx & 3/4 a 3500 psi. WOC	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and giv ompletions: Attach ented with 500 sxs I of 1% CFR-III. Plu of my knowledge an	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed companies of proposed companies	ed date pletion
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15 Premium 50/ Tested csg to I hereby certify that the information aborgrade tank has been/will be constructed or close	HANGE PLANS CO CA CHULTIPLE CA COMPLETION CE d operations. (Clearly state all pertir. SEE RULE 1103. For Multiple Co S 1b/ft & 171b/ft csg to 6049'. Ceme 50 Pozmix w/ 6 lbs salt per sx & 3/4 a 3500 psi. WOC	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and giv ompletions: Attach ented with 500 sxs I of 1% CFR-III. Plu of my knowledge an	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed companies of proposed companies	ed date pletion
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15 Premium 50/ Tested csg to	HANGE PLANS CO CA CHULTIPLE CA COMPLETION CE d operations. (Clearly state all pertir. SEE RULE 1103. For Multiple Co S 1b/ft & 171b/ft csg to 6049'. Ceme 50 Pozmix w/ 6 lbs salt per sx & 3/4 a 3500 psi. WOC	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and giv ompletions: Attach ented with 500 sxs I of 1% CFR-III. Plu of my knowledge an	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed companies of proposed companies	ed date pletion
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15.: Premium 50/ Tested csg to I hereby certify that the information aborgrade tank has been/will be constructed or close SIGNATURE Mand Mand	HANGE PLANS CO CA CHULTIPLE CA COMPLETION CE d operations. (Clearly state all pertir. SEE RULE 1103. For Multiple Co S 1b/ft & 171b/ft csg to 6049'. Ceme 50 Pozmix w/ 6 lbs salt per sx & 3/4 a 3500 psi. WOC	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and giv ompletions: Attach ented with 500 sxs I of 1% CFR-III. Plu of my knowledge an	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed companies of proposed companies	ed date pletion
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15 Premium 50/ Tested csg to I hereby certify that the information aborgrade tank has been/will be constructed or close	HANGE PLANS CO CA CHULTIPLE CA COMPLETION CE d operations. (Clearly state all pertir. SEE RULE 1103. For Multiple Co S 1b/ft & 171b/ft csg to 6049'. Ceme 50 Pozmix w/ 6 lbs salt per sx & 3/4 a 3500 psi. WOC	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and giv ompletions: Attach ented with 500 sxs I of 1% CFR-III. Plu of my knowledge an	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed companies of proposed companies	ed date pletion
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15 Premium 50/ Tested csg to I hereby certify that the information aborgrade tank has been/will be constructed or close SIGNATURE CONSTRUCTED CONSTRUCTED CONSTRUCTED CONSTRUCTED CONSTRUCTED CONSTRUCTED CONSTRUCTED CONSTRUCTED CONSTRUCTED CONS	HANGE PLANS CO CA CHULTIPLE CA COMPLETION CE d operations. (Clearly state all pertir. SEE RULE 1103. For Multiple Co S 1b/ft & 171b/ft csg to 6049'. Ceme 50 Pozmix w/ 6 lbs salt per sx & 3/4 a 3500 psi. WOC	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and giv ompletions: Attach ented with 500 sxs I of 1% CFR-III. Plu of my knowledge an	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed companies of proposed companies	ed date pletion
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M C OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15.: Premium 50/ Tested csg to I hereby certify that the information aborgrade tank has been/will be constructed or close SIGNATURE Mand Mand	HANGE PLANS CO CA CHULTIPLE CA COMPLETION CE d operations. (Clearly state all pertir. SEE RULE 1103. For Multiple Co S 1b/ft & 171b/ft csg to 6049'. Ceme 50 Pozmix w/ 6 lbs salt per sx & 3/4 a 3500 psi. WOC	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and giv ompletions: Attach ented with 500 sxs I of 1% CFR-III. Plu of my knowledge an	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed companies of proposed companies	ed date pletion
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15.: Premium 50/ Tested csg to I hereby certify that the information aborgrade tank has been/will be constructed or close SIGNATURE Constructed or close SIGNATURE Constructed or close (This space for State use)	HANGE PLANS CO CA CHULTIPLE CA COMPLETION CE d operations. (Clearly state all pertir. SEE RULE 1103. For Multiple Co S 1b/ft & 171b/ft csg to 6049'. Ceme 50 Pozmix w/ 6 lbs salt per sx & 3/4 a 3500 psi. WOC	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and giv ompletions: Attach ented with 500 sxs I of 1% CFR-III. Plu of my knowledge an	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed companies of proposed companies	ed date pletion
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15 Premium 50/Tested csg to I hereby certify that the information aborgrade tank has been/will be constructed or close SIGNATURE	HANGE PLANS CO CA CHULTIPLE CA COMPLETION CE d operations. (Clearly state all pertir. SEE RULE 1103. For Multiple Co S 1b/ft & 171b/ft csg to 6049'. Ceme 50 Pozmix w/ 6 lbs salt per sx & 3/4 a 3500 psi. WOC	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and giv ompletions: Attach ented with 500 sxs I of 1% CFR-III. Plu of my knowledge an	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed companies of proposed companies	ed date pletion
PERFORM REMEDIAL WORK P TEMPORARILY ABANDON C PULL OR ALTER CASING M OTHER: 13. Describe proposed or completed of starting any proposed work) or recompletion. June 19, 2004: Ran 5½" 15.: Premium 50/ Tested csg to I hereby certify that the information aborgrade tank has been/will be constructed or close SIGNATURE Constructed or close SIGNATURE Constructed or close (This space for State use)	HANGE PLANS CO CA CHULTIPLE CA COMPLETION CE d operations. (Clearly state all pertir. SEE RULE 1103. For Multiple Co S 1b/ft & 171b/ft csg to 6049'. Ceme 50 Pozmix w/ 6 lbs salt per sx & 3/4 a 3500 psi. WOC	MEDIAL WORK MMENCE DRILLIN SING TEST AND MENT JOB HER: nent details, and giv ompletions: Attach ented with 500 sxs I of 1% CFR-III. Plu of my knowledge an	ALTERING CASING IG OPNS. PLUG AND ABANDONMENT Proposed company of proposed company o	ed date pletion