State of New Mexico Energy, Minerals and Natural Resources Department

	IC	

OIL CONSERVATION DIVISION

Santa Fe, New Mexico 87503	WELL API NO. 30-025-07438
Sana 16, New Mondo 67363	5. Indicate Type of Lease
	FED STATE FEE X
	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name NORTH HOBBS (G/SA) UNIT
(FORM C-101 FOR SUCH PROPOSALS.)	NORTH HOBBS (U/SA) UNIT
1. Type of Well: Oil Well X Gas Well Other	SECTION 29
2. Name of Operator OCCIDENTAL PERMIAM, LTD.	8. Well No. 231
3. Address of Operator 1017 W STANOLIND RD.	9. Pool name or Wildcat
	HOBBS (G/SA)
4. Well Location	1
Unit Letter K : 2310 Feet From The SOUTH Line and 1650 Fe	et From The WEST Line
Section 29 Township 18-S Range 38-	E LEA County
10. Elevation (Show whether DF, RKB, RT GR, etc.) 3650' GL	
11. Check Appropriate Box to Indicate Nature of Notice, Report,	
NOTICE OF INTENTION TO:	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND REMEDIAL WORK ABANDON REMEDIAL WORK	X ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING O	PNS. PLUG & ABANDONMENT
PULL OR ALTER CASING CASING TEST AND CEME	NT JOB
OTHER	
OTHER: OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incwork) SEE RULE 1103.	luding estimated date of starting any proposed
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incwork) SEE RULE 1103.	luding estimated date of starting any proposed
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incwork) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service.	luding estimated date of starting any proposed
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'.	83,025
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'.	83,025
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'.	83,025
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'.	83,025
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'.	83,025
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'.	83,025
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'.	83,025
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, inc work) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'.	83,025
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incwork) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'. RDPU. Clean Location Rig Up Date: 07/01/2004 Rig Down Date: 07/02/2004	15 15 15 15 15 15 15 15 15 15 15 15 15 1
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incwork) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'. RDPU. Clean Location Rig Up Date: 07/01/2004 Rig Down Date: 07/02/2004	Hobbs OCD CO
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incovers) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'. RDPU. Clean Location Rig Up Date: 07/01/2004 Rig Down Date: 07/02/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	hVED Hobbs OCD OCD mpl Specialist DATE 07/20/2004
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incomork) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'. RDPU. Clean Location Rig Up Date: 07/01/2004 Rig Down Date: 07/02/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE	The state of the s
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, incwork) SEE RULE 1103. RUPU. Pull ESP equipment. Cut off and replace wellhead for CO2 service. Stimulate perfs 4106-4210 and open hole 4220-55 w/3000 g 15% NEFE HCL acid RIH w/Reda ESP on 123 jts 2-7/8" tbg. Intake set @3857'. RDPU. Clean Location Rig Up Date: 07/01/2004 Rig Down Date: 07/02/2004 I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE ROBERT Gilbert TITLE Workover ConTYPE OR PRINT NAME Robert Gilbert	The state of the s