

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-22353

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
K4105

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name
State L

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Latigo Petroleum Inc.

8. Well No.
1

3. Address of Operator
415 W. Wall, Ste. 1900, Midland, TX 79701

9. Pool name or Wildcat
Lane Abo

4. Well Location
Unit Letter K : 1980 Feet From The South Line and 1980 Feet From The West Line

Section 2 Township 10S Range 33E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4249.8"

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-12-04 MIRU.
7-12-04 Set 5-1/2" CIBP @ 8968', cap w/ 35' of cement (dumbailer).
7-13-04 Set 5-1/2" CIBP @ 8725', cap w/ 35' of cement (dumbailer).
7-14-04 Circulate hole w/ 10# MLF.
7-14-04 Spot 25 sx cement @ 7700', calc. TOC @ 7500'.
7-15-04 Cut & pull 5025' 5-1/2" csg. (lost slip body down hole). Notified NMED.
Billy Pritchard, okayed stub plug.
7-16-04 Spot stub plug @ 5075' to 4890', WOC & tag @ 4886'.
7-16-04 Spot 75 sx @ 4040'.
7-16-04 Spot 30 sx @ 1900'.
7-16-04 Perf. @ 382', pressure test @ 700#. Spot 50 sx 432 to 244', WOC & tag.
7-19-04 Tag plug @ 251'. Spot 10 sx to surface.
7-19-04 RDMO. Install dry hole marker & clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Agent DATE 7-27-04

TYPE OR PRINT NAME Roger Massey TELEPHONE NO. (432) 530-0907

(This space for State Use)

APPROVED BY Hay W. Wink TITLE OC FIELD REPRESENTATIVE / STAFF MANAGER DATE AUG 02 2004

CONDITIONS OF APPROVAL, IF ANY: