Form 3160-5 * (August 1999)


UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0135
Expires: November 30, 2000

	SUREAU OF LAND MANA	JEMEN I	<u> </u>	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side.			5. Lease Serial No. NMLC063345	5
			6. If Indian, Allotte	e or Tribe Name
			7. If Unit or CA/Ag NMNM71009	7. If Unit or CA/Agreement, Name and/or No. NMNM71009A
Type of Well Gas Well Other: INJECTION			8. Well Name and N PEARSALL QN	
2. Name of Operator Contact: ROBERT CHASE MACK ENERGY CORPORATION E-Mail: jerrys@mackenergycorp.com			9. API Well No. 30-025-00839	9-00-S1
3a. Address P O BOX 960 ARTESIA, NM 88211-0960		3b. Phone No. (include area code Ph: 505.748.1288 Fx: 505.746.9539	10. Field and Pool, or Exploratory PEARSALL	
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description)	11. County or Paris	sh, and State
Sec 4 T18S R32E SWNW Tr	act 4A 1980FNL 660FWL		LEA COUNT	Y, NM
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR OTH	IER DATA
TYPE OF SUBMISSION	TYPE OF ACTION			
N. C.	Acidize	Deepen	Production (Start/Resume)	☐ Water Shut-Off
Notice of Intent	Alter Casing	Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Subsequent Report	Casing Repair	New Construction	☐ Recomplete	Other
Final Abandonment Notice	Change Plans	Plug and Abandon	☐ Temporarily Abandon	_
	Convert to Injection	Plug Back	☐ Water Disposal	
Mack Energy Corporation Pro 1. Notify BLM 24 hours prior 2. Set 100' cement plug from 3. Circulate hole w/mud gel. 4. Set 100' cement plug from 5. Perforate @ 60' circulate of 6. Install dry hole marker.	to starting plugging operat 3632-3532' or CIBP @ 36 1050-950', top of salt sect ement to surface.	ions. 30' w/35' cement cap. tion.	E ATTACHED FO TIONS OF APPR	OVAL
へ レックトバアルチョ いれりだっこ				
Solid Plug F/1286	1180'-TAC	T 100'CEM. PLUG F	-/378'-278 856	SGJHOE-TA
Perforate 52"Cus Solid Plug F/1286 14. Thereby certify that the foregoing	Electronic Submission # For MACK ENE	32458 verified by the BLM We ERGY CORPORATION, sent to	II Information System	SESHOE-TA
c	Electronic Submission # For MACK ENE	32458 verified by the BLM We ERGY CORPORATION, sent to cessing by LINDA ASKWIG on	Il Information System (*) the Hobbs 06/28/2004 (04LA0219SE) JCTION CLERK	
Name(Printed/Typed) JERRY S	# Electronic Submission For MACK ENE Committed to AFMSS for pro-	32458 verified by the BLM We ERGY CORPORATION, sent to cessing by LINDA ASKWIG on	Il Information System (1) the Hobbs (1) 06/28/2004 (04LA0219SE) JCTION CLERK	Segret
Name(Printed/Typed) JERRY S	Electronic Submission # For MACK ENE COMMITTED TO AFMSS FOR PRO- CHERRELL Submission)	32458 verified by the BLM We ERGY CORPORATION, sent to cessing by LINDA ASKWIG or Title PROD	Il Information System (1) the Hobbs (1) 06/28/2004 (04LA0219SE) JCTION CLERK	
Name(Printed/Typed) JERRY S	Electronic Submission # For MACK ENE COMMITTED TO AFMSS FOR PRO- CHERRELL Submission)	32458 verified by the BLM We ERGY CORPORATION, sent to cessing by LINDA ASKWIG on Title PRODUCE Date 06/28/2	Il Information System (1) the Hobbs (1) 06/28/2004 (04LA0219SE) JCTION CLERK	

BLM

MACK ENERGY CORP PEARSALL QUEEN UNIT #12 Sec 4 T18S R32E 1980 FNL 660 FWL



BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 (505) 627-0272

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

- 1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon. If you are unable to plug the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.
- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call (505) 627-0272, in Eddy County call (505) 361-2822; for wells in Lea County call (505) 393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
- 5. Cement Requirement: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

- 6. <u>Dry Hole Marker:</u> All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The well bore shall then be capped with a 4-inch pipe, 10 feet in length, 4 feet above the ground and embedded in cement. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date well was plugged.</u>

Following the submittal and approval of the Subsequent Report of Abandonment, surface restoration conditions of approval shall be developed and furnished to you.