Submit 3 Copies To Appropriate District	State of New Mexico		Form C-103			
Office District I	Energy, Minerals and Natural Resources		March 4, 2004			
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.			
District II	OIL CONSERVATION DIVISION		30-025-36785			
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Francis Dr.		5. Indicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410			STATE X FEE			
District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505						
			VA-1797			
SUNDRY NOTIC	7. Lease Name or Unit Agreement Name					
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						
PROPOSALS.)			Dempster State Unit			
1. Type of Well:			8. Well Number			
Oil Well Gas Well X Other			2			
2. Name of Operator			9. OGRID Number			
Yates Petroleum Corporation			025575			
3. Address of Operator			4. Pool name or Wildcat			
105 South Fourth Street, Artesia, NM 88210			Dempster Mill; Mississippian (Gas)			
4. Well Location						
Unit Letter N : 1	980 feet from the	South line and	1150 feet from the West line			
			·····			
Section 31		S Range 36E	NMPM Lea County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						
4067' GR						
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)						
Pit Location: ULSectTwpRngPit typeDepth to GroundwaterDistance from nearest fresh water well						
Distance from nearest surface water Below-grade Tank Location ULSectTwpRng;						
feet from theline andfeet from theline						
		• • • • • • • • • • • • • • • • • • • •				
3456789						
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INT	FINTION TO	SUF	BSEQUENT REPORT OF: S			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR	RK (ALTERING CASING			
	PLUG AND ABANDON					
	PLUG AND ABANDON CHANGE PLANS					
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOP COMMENCE DP				
	PLUG AND ABANDON CHANGE PLANS MULTIPLE	REMEDIAL WOR COMMENCE DR CASING TEST A	RILLING OPNS PLUG AND ABASCONMENT			
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOP COMMENCE DP	RILLING OPNS PLUG AND ABASCONMENT			
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING OTHER:	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPLETION	REMEDIAL WOR COMMENCE DR CASING TEST A CEMENT JOB OTHER:				

•

,

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7-31-04 Spudded well @ 9:00 a.m. (hole size = 12-1/4"). Drilled to 10'. Notified Sylvia Dickey w/Hobbs OCD via voice mail.

I hereby certify that t grade tank has been/will SIGNATURE:	be constructed or closed	according to NMOCD guide	the best of my knowledge and belief. I lines , a general permit or an (attached) Regulatory Compliance Technician	further certify that any pit or below- alternative OCD-approved plan . DATE: 8-4-04	
			Telephone No. 5(A set as a set of the set	
(This space for State APPPROVED BY Conditions of approv	Chus 100	Illem TITL	E Dist. Sup	DATE	