

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
May 27, 2004

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. <u>30-025-23215</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. <u>VO-5605</u>
7. Lease Name or Unit Agreement Name <u>How A State</u>
8. Well Number <u>1</u>
9. OGRID Number <u>17213</u>
10. Pool name or Wildcat <u>Lane Abo, Southeast</u>

Pit or Below-grade Tank Application ☐ or Closure ☐ will utilize steel pits  
Pit type \_\_\_\_\_ Depth to Groundwater \_\_\_\_\_ Distance from nearest fresh water well \_\_\_\_\_ Distance from nearest surface water \_\_\_\_\_  
Pit Liner Thickness: \_\_\_\_\_ mil Below-Grade Tank: Volume \_\_\_\_\_ bbls; Construction Material \_\_\_\_\_

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator  
Penroc Oil Corporation

3. Address of Operator  
P.O. Box 2769, Hobbs, NM 88241-2769

4. Well Location  
Unit Letter 0 : 720 feet from the South line and 1980 feet from the East line  
Section 4 Township 10S Range 34E NMPM County Lee

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☒  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Well is shut-in for build-up. RU WSU - Swab test for oil cut - if not satisfactory - plan to P&A as follows:

- ① Release plkr and spot 25 sxs. Plug above Abo perms 8900-9020'.
- ② TOH w/ plkr - TTH - tag cement plug - POH to 6900' and spot 25 sxs. plug.
- ③ Tag same. Spot 25 sxs. plug @ 5 1/2" liner top & pull up to 2200' to spot 25 sxs.
- ④ TOH & RU to pull 8 5/8" CSG & slip over shoe. TTH w/ tubing & spot cement plug 50' in & 50' out - woc. Tag same & spot 25 sxs. cement plug @ base of surface CSG @ 360'.
- ⑤ spot 10 sx. surface plug. Install Dryhole marker - cut off & clamp location. Ready for NMOC.D inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC.D guidelines ☒ a general permit ☐ or an (attached) alternative OGD-approved plan ☐.

SIGNATURE M. Y. Merchant TITLE PRESIDENT

DATE

Type or print name M. Y. Merchant  
For State Use Only

E-mail address: mymerche@hotmail.com Telephone No. (505) 492-1236

APPROVED BY: Chris Williams

TITLE Dist. Sup.

DATE 8/9/04

Conditions of Approval (if any):