

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505


SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-36791
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☐ FEE ☐
2. Name of Operator Xeric Oil & Gas Corporation		6. State Oil & Gas Lease No.
3. Address of Operator P. O. Box 352 Midland, TX 79702		7. Lease Name or Unit Agreement Name: West Pearl Queen Unit
4. Well Location Unit Letter <u>H</u> : 2310 feet from the <u>North</u> line and 825 feet from the <u>East</u> line Section <u>31</u> Township <u>19S</u> Range <u>35E</u> NMPM Lea County		8. Well No. 301
10. Elevation (Show whether DR, RKB, RT, GR, etc.) RKB 3731.5		9. Pool name or Wildcat Pearl; Queen

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐ OTHER: ☐	SUBSEQUENT REPORT OF: REMEDIAL WORK ☐ ALTERING CASING ☐ COMMENCE DRILLING OPNS. ☒ PLUG AND ABANDONMENT ☐ CASING TEST AND CEMENT JOB ☐ OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

8/13/04 Spud well @ 11:00 AM MDT with Key Drilling Rig #6.

8/14/03 TD 12 1/4" surface hole @ 635'. Circulate hole clean. RIH w/15 jts. 24# J-55 8 5/8" csg. to a setting depth of 635'. Cement with 400 sx Class "C". Circulate 65 sx to pit. Plug Down. WOC 8 hrs. Nipple up BOP. Install H2S equipment as per NMOCD orders.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 8/17/04
Type or print name ACrawford@xericoil.com 432-683-3171
(This space for State use) Telephone No.

APPROVED BY Mary W. Wink TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE AUG 19 2004
Conditions of approval, if any: