

DISTRICT I
P.O. Box 1930, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-21744
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☐ OTHER SWD

2. Name of Operator
Fasken Oil and Ranch, Ltd.

3. Address of Operator
303 W. Wall Ave., Suite 1800, Midland, TX 79701

4. Well Location
Unit Letter M : 554 Feet From The South Line and 554 Feet From The West Line
Section 6 Township T15S Range 35E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
4061' DF

7. Lease Name or Unit Agreement Name

Stoltz State SWD

8. Well No. 1

9. Pool name or Wildcat
SWD, San Andres-Glorieta

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ Approved as to plugging of the Well Bore.
OTHER: ☐ Liability under bond is retained until surface restoration is completed.

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 6-30-04 MIRU.
- 7-01-04 Cut 2-3/8" tbg. @ 4467', pkr. stuck @ 4500'.
- 7-01-04 Circulate hole w/ 10# MLF.
- 7-02-04 Attempt to remove 4-1/2" casing slips, recheck well file, showed 4-1/2" casing cemented to surface.
- 7-02-04 Billy Pritchard NMOCDC okayed to spot plug @ 2600'.
- 7-02-04 Cut off 4-1/2" PN, NU wellhead & BOP, TIH w/ 2619' of tbg.
- 7-06-04 Mix & spot 25 sx cmt. calculate TOC @ 2350'.
- 7-06-04 Perf. well @ 435', sqz. 225 sx cmt. to circulate cement to surface.
- 7-06-04 RDMO. Cut off wellhead, install dry hole marker, & clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Roger Massey TITLE Agent DATE 7/15/04
TELEPHONE NO. (432) 530-0907

(This space for State Use)

APPROVED BY: Harry W. Wink TITLE QC FIELD REPRESENTATIVE II/STAFF MANAGER DATE AUG 27 2004
CONDITIONS OF APPROVAL, IF ANY: