Submit 3 Copies To Appropriate District Office	State of N	lew Mexico	Form C-103
District I	Energy, Minerals a	nd Natural Resources	Revised May 08, 2003
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-025-23691
District III	District III 1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.
District IV 1220 S. St. Francis Dr., Santa Fe, NM			o. State on & Gas Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Greenwood
PROPOSALS.)			O WALLEN
1. Type of Well:			8. Well Number
Oil Well Gas Well Other			18
2. Name of Operator Zio Energy Inc.			9. OGRID Number
Zia Energy, inc.			025616
3. Address of Operator 2203 Timberloch Place, Suite 229 The Woodlands, TX 77380			10. Pool name or Wildcat
			Eunice San Andes
4. Well Location			
Unit Letter M	· 330' feet from the	South line and 5	600 feet from the West line
Unit Letter M	: 330' feet from the _	line and	feet from the VVEST line
Section 9	Township 223	S Range 37E	NMPM Lea County
Section -		ether DR, RKB, RT, GR, etc	
	3403' GR	inci Di, iuid, iii, on, en	···
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
	NTENTION TO:		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
· El Olivi (Elliebi E 170) (1		I TEMEDIAL WO	ALIERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DE	RILLING OPNS PLUG AND
PULL OR ALTER CASING	MULTIPLE	CASING TEST A	AND ABANDONMENT
	COMPLETION	CEMENT JOB	
OTHER.			
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dates.)			
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion.			
6-24-04 thru 7-13-04			
MIRU Mesa Well Service workover rig. Set in equip. Dig out cellar. Rig up reverse equip. Washover dry			
hole marker. NU BOP. Test to 3000 psi-OK. Make up 7 7/8" bit and drill out cement plugs and clean out old			
wellbore. Previously drilled as Wagner, Stoltz & Brown, #1 Greenwood. Clean out to 5200'. Circ hole clean and			
run electric logs. TOH laying down 2 7/8" AOH DP. RU and run 115 jts, 5132' of 5.5" 17# J55 LT&C Csg. Shoe			
at 5132'. Float collar at 5085'. RU BJ & Cement casing w/ 575 sx Super C Modified cement. Yld1.46 @ 13.4#/gal. Plug dn at 0500 hrs on 7-13-04. ND BOP, set slips and cut off 5.5" csg. Release rig.			
10.4mgai. 1 lug an at 0000 fils on 7-15-04. ND BOP, set silps and cut on 5.5 csg. Release fig.			
I hereby certify that the information	n above is true and complete	to the hest of my knowledge	re and heliaf
	2 of the and and complete	to the best of my knowledg	ge and bener.
SIGNATURE / Sue of	eeT	TLE Agent	DATE_3/10/04
Type or print name Gene Lee			Telephone No. (505) 626-4292
(This space for State use)			
APPPROVED BY HOLD WELL OC FIELD REPRESENTATOY WELL DATE			
Conditions of approval, if any: TITLE OC. FIELD REPRESENTATIVE II/STAFF MSHAGER 1 2001			
	ر		~ + 2004