New Mexico Oil Conservation Division, District I 1625 N. French Drive Hobbs, NM 83249

Form 3160-5 (August 1999)	UNITED STATES	DEPARTMENT OF THE INTERIOR	
(,B	BUREAU OF LAND MANAGEMENT		5. Lease Serial No.
AND REPORTS ON WELLS		NM 0140978	
SUNDRY NOTICES AND ALFORTIO of the enter an Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side			7. If Unit or CA/Agreement, Name and/or No.
C 11/-11			8910118570
Type of Well Gas Well Gas Well Other			8. Well Name and No.
- Norma of Operator			LANGLIE JAL #94
2. Name of Operation PHOENIX HYDROCARBONS OPERATING CORPORATION 3b. Phone No. (include area code)			30-025-11635
3a. Address P O BOX 3638, MIDLAND, TX 79702 432-686-9869			10. Field and Pool, or Exploratory Area LANGLIE MATTIX
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, State
O-990' FSL & 1980' FEL Sec 17-T25S-R37E			LEA COUNTY, NM
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA			
	Acidize Deepen	Production (Start	Resume) Water Shull 1976
Notice of Intent	Alter Casing Fracture		Well Integrity
		nstruction 🔲 Recomplete	
Subsequent Report	Change Plans X Plug and		
Final Abandonment No			
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximated quration interest. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zenes. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BLA. Required subsequent reports shall, be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleted, and the operation results in a multiple completion or recompleted. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operation is determined that the site is readv for final inspection.) IOB # 04-			
APPROVED	8-13-D4 (5 HRS RIG) NOTIFY OCD – MIRU – NUBOP – RIH & SP	OT 35 SXS @ 3209' – POOH – CL	OSE IN WELL
SEP 1 3 2004	8-16-04 (11 HRS RIG) RIH & NO TAG @ 3209' – RESET PLUG – SPOT 35 SXS @ 3209' – POOH – WOC – RIH & TAG @ 2908' - CIR. 110 BBLS MUD (30 SXS GEL) – POOH & SPOT 30 SXS @ 2400'-2220' – POOH & SPOT 30 SXS @ 1135' – POOH – WOC – WILL TAG IN AM		
GARY GOURLEY PETROLEUM ENGINEE	8-17-04 (8 HRS RIG) RIH & TAG @ 912' – POOH – PERFORATE @ 371' – SET PACKER @ 60' – SQUEEZE 45 SXS – CLOSE IN WELL - RIH & TAG @ 210'- POOH - SPOT 15 SXS @ 60' TO SURFACE – INSTALL DRY HOLE MARKER– COVER PIT & CELLAR – MOVE OUT – OCD REPRESENTATIVE BUDDY HILL		
(RULE CHANGE BY OCD REQUIRE DISPOSAL & LINER REMOVAL)			
14. I hereby certify that the foregoing is true and correct			
Name (Printed/Typed)		Title AGENT	
PHYLLIS R G	UNTER	AGEN'L	
Signature Pupilie Rounter Date 9/7/04			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved by Lang W. Wink OC FIELD REPRESENTATIVE II/STAFF MANAGER SEP 22 2004			
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant hous legal or equitable title to those rights in the subject lease office which would entitle the applicant to conduct operations thereon.			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.			
GWW			

MAYO MARRS CASING PULLING INC. BOX 863 KERMIT, TEXAS 79745

PHOENIX HYDROCARBONS OPERATING CORP.

Lease: LANGLIE JAL UNIT # 94 Project: P & A – CEMENTING REPORT

08-13-04 - SPOT 35 SXS @ 3209'-3209' & TAG 08-16-04 - SPOT 35 SXS @ 3209'-2908' & TAG 08-16-04 - SPOT 30 SXS @ 2400'-2220' 08-16-04 - SPOT 30 SXS @ 1135'-912' & TAG 08-17-04 - PERFORATE @ 371' 08-17-04 - SQUEEZE 45 SXS @ 371'-210' & TAG 08-17-04 - SPOT 15 SXS @ 60' TO SURFACE

INSTALL DRY HOLE MARKER CIRCULATE 10# MUD

