

## UNITED STATISTIC Off Conservation Division, District I DEPARTMENT OF THE INTER 5. French Drive BUREAU OF LAND MANAGER FRENDS, NM 88249

BORENO OF	LAND MANAGEMENT	FORM APPROVED Budget Bureau No. 1004-0135
SUNDRY NOTICES	SAND REPORTS ON WELLS	Expires March 31, 1993 5. Lease Designation and Serial No.
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir		NM-LC062391
Use "APPLICATION FC	DR PERMIT—" for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT	IN TRIPLICATE	NA
1. Type of Well		7. If Unit or CA, Agreement Designation
Øit     Gas       Well     Other		NA
2. Name of Operator DEVON ENERGY PRODUCTION COMPA		8. Well Name and No.
3. Address and Telephone No.	••••••••••••••••••••••••••••••••••••••	Kachina 5 Federal #7
	LAHOMA CITY, OKLAHOMA 73102 (405) 552-4615	9. API Well No.
		30-025-32400
4. Location of Well (Footage. Sec., T., R., M., or Survey I		10. Field and Pool, or Exploratory Area
2130' FNL & 990' FWL, SW NW Section 5-7	Г18S-R33Е	South Corbin (Bone Spring)
		11. County or Parish, State
		Lea County, New Mexico
CHECK APPROPRIATE BOX(s	) TO INDICATE NATURE OF NOTICE, REPO	
TYPE OF SUBMISSION	TYPE OF ACTION	/S
Notice of Intent		
Notice of intent	Abandonment	Change of Plans
Subsequent Report	Recompletion	Change of Plans
	Plugging Back	
Final Abandonment Notice	Casing Repair Altering Casing	Water Shut-Off OCD
	Other	Conversion to Injection
		Note: Report results of multiple completion on Well
<ol> <li>Describe Proposed or Completed Operations (Clearly state all p subsurface locations and measured and true vertical depths in</li> </ol>	vertinent details, and give pertinent dates, including estimated date of starting a for all markers and zones pertinent to this work )*	
	g & abandonment. Upon further review Devon requ	
interval in this well. Devon sent election letters	s out on 9/8/04 to partners, which have a 30 election per	lests permission to test the Bone Spring riod to participate in this re-completion.
1. MIRU PU. Kill well w/ 2% KCl. ND tree		-

2. RUWL. Make gauge ring run to 9,240'. RIH w/ 51/2" CIBP & set @ 9,240'. Dump bail 35' cmt on top.

3.	RIH w/casing gun and perforate Bone Spring at 2 SPF from 9,106' - 9,116', & 9,128' - 9,130'	24 shots	PP	RU	رر لرز	Ļ
----	---	----------	----	----	-----------	---

4. RIH w/ 2 7/8" tubing & 5-1/2" production packer. Set packer @ +/-9,056'. Swab test Bone Spring perforations. 1 4 2004

5. If swab test of Bone Spring is favorable, then RU BJ Services and acidize perforations if necessary per BJ recommendation. Swab/flow back load water & acid. Pull 2-7/8" production tubing and packer.

ADDON

5. If post acid job swab test is favorable, then run 2-7/8" production tubing and place on rod pump. Turn well to production.

14. I hereby certify that the foregoing is true and correct	
$\rho$ : $\rho h$	Ronnie Slack
Signed Ronnie Slack	
This space for Federal or State office use)	
Approved by Conditions of approval, if any:	APPROVED FOR <u>3</u> MONTH PERIOD
sonanions of approval, if any.	
	ENDING 12-14-04
Title 18 1/ S.C. Section 1001 makes it a arima for	

itle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representation on any matter within its jurisdiction.





