

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

March 4, 2004

SUNDRY NOTICES AND REPORTS ON WELLS						
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other						7. Lease Name or Unit Agreement Name
						Blue Baer Dunn 32
2. Name of Operator						8. Well Number
EOG Resources, Inc						1
3. Address of Operator						9. OGRID Number
P.O. Box 2267, Midland, TX, 79702						
4. Well Location						10. Pool name or Wildcat
Unit Letter <u> N </u> : <u> 676 </u> feet from the <u> South </u> line and <u> 1980 </u> feet from the <u> West </u> line Section <u> 32 </u> Township <u> 15-S </u> Range <u> 35-E </u> NMPM Lea County						Eidson, Morrow North Gas
11. Elevation (Show whether DR, RKB, RT, GR, etc.)						

Pit Location: UL N Sect 32 Twp 15S Rng 35E Pit type Steel Depth to Groundwater 68 Distance from nearest fresh water well Over 1000'
Distance from nearest surface water _____ Below-grade Tank Location UL _____ Sect _____ Twp _____ Rng _____ ;
676 feet from the South line and 1980 feet from the West line (Steel Tank)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
MULTIPLE COMPLETION <input type="checkbox"/>	
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>

1. Notify OCD 24 hrs prior to MI & RU.
2. NU BOPE, pull out of perm pkr at 13350, POH with tbg.
3. RU WL, set 4 1/2" CIBP at 13340, spot 25sx, plug 13340-13200 (Morrow) WOC Tag.
4. Displace hole w/MLF, 9.5# Brine w/2% gel P/BBL.
5. Spot 25sx, plug from 12100-11900 (Atoka).
6. Spot 25sx, plug from 11600-11400 (Strawn).
7. Spot 25sx, plug from 10100-9900 (Wolfcamp).
8. Spot 25sx, plug from 7450-7250 (Tubb).
9. Spot 60sx, plug from 4850-4100 (S. Andres, Grayburg, 8 5/8 Shoe) WOC Tag.
10. Spot 25sx, plug from 3100-2900 (Yates).
11. Cut 4 1/2" csg at 2000, L/D csg, spot 40sx, plug from 2050-1900 (Stub) WOC Tag.
12. Spot 60sx, plug from 525-325 (11 3/4 Shoe) WOC Tag.
13. 10sx Surf, install dry hole marker.

SIGNATURE [Signature] TITLE _____ Consultant _____ DATE 9-14-04

Type or print name Jimmy Bagley E-mail address: _____ Telephone No. 432-561-8600

APPROVED BY Harry W. Wink TITLE CC FIELD REPRESENTATIVE II/STAFF MANAGER DATE SEP 22 2004
Conditions of approval, if any: _____

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLOUGHING OPERATIONS FOR THE C-103 TO BE APPROVED.