Office Office 10 Approp			New Mexico			rm C-103
District I		nergy, Minerals	and Natural Reso	urces		May 27, 2004
1625 N. French Dr., Hobbs, District II					L API NO.	
1301 W. Grand Ave., Artesi	ia, NM 88210 C		VATION DIVIS	ION $\frac{1}{5 \text{ In}}$	<u>\$ 30−025028061</u> dicate Type of Lease	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410			J. 11	STATE FEE		
District IV Santa Fe, NM 8/505				6. St	ate Oil & Gas Lease No.	
1220 S. St. Francis Dr., San 87505	ta Fe, NM				B-2317	
	NDRY NOTICES AN	ND REPORTS O	N WELLS	7. Le	ease Name or Unit Agreem	ent Name
(DO NOT USE THIS FORM				ГО А	_	
DIFFERENT RESERVOIR PROPOSALS.)	USE "APPLICATION F	OR PERMIT" (FOR	M C-101) FOR SUCH		tate 35 Unit	
1. Type of Well: Oil Well Gas Well Other Injection				8. W	Vell Number 029	
2. Name of Operator McGowan Working Partners				i	9. OGRID Number	
				1027	220397 10. Pool name or Wildcat	
3. Address of Operator PO Box 55809 Jackson, Mississippi 39296-5809					·	
PO Box 55809 4. Well Location	Jackson, Mi	ssissippi	39296-5809	Vac	cuum Grayburg San	Andres_
	I : 1440	feet from the	couth lin	e and 10	feet from the <u>east</u>	line
Unit Letter 35 Section	<u></u>	Township 17			_	l.
Section	11 FI		hether DR, RKB, RT		County Lea	1
		03:8 GR/40		, GR, cic.)		-
Pit or Below-grade Tank A						
Pit type_stealDep	th to Groundwater <u>60</u>	Distance from ne	arest fresh water well_]	mil Distance fro	om nearest surface water <u>5</u> m:	iles
Pit Liner Thickness:	mil Belo	ow-Grade Tank: Vo	lume <u>110</u>	_bbls; Constructi	on Material <u>steal</u>	
12	2. Check Approp	riate Box to Ir	ndicate Nature of	Notice, Repo	rt or Other Data	
	, • • •					
	CE OF INTENT		_		JENT REPORT OF:	
PERFORM REMEDIA		AND ABANDON		DIAL WORK	★ ALTERING C	ASING [
TEMPORARILY ABAN	 -	IGE PLANS		ENCE DRILLING	OPNS.☐ P AND A	
		IPLE COMPL	☐ CASING	G/CEMENT JOB		
PULL OR ALTER CAS	SING MULT					
OTHER:	SING [] MOLI		☐ OTHER	t:		
OTHER: 13. Describe propo	osed or completed op	erations. (Clearl	y state all pertinent	details, and give	pertinent dates, including e	
OTHER: 13. Describe proportion of starting any	osed or completed op proposed work). SE	erations. (Clearl	y state all pertinent	details, and give	pertinent dates, including e ellbore diagram of propose	
OTHER: 13. Describe proportion of starting any or recompletion	osed or completed op proposed work). SE on.	erations. (Clearl E RULE 1103. I	y state all pertinent For Multiple Compl	details, and give etions: Attach w		
OTHER: 13. Describe proportion of starting any or recompletion Started 9/	osed or completed op proposed work). SE on. 16/04, Rigged	erations. (Clearl E RULE 1103. I	y state all pertinent For Multiple Compl pipe and pac	details, and give etions: Attach weeker.	ellbore diagram of propose	
OTHER: 13. Describe proportion of starting any or recompletion Started 9/9/17/04,	osed or completed op proposed work). SE on. 16/04, Rigged Ran bit to dr	erations. (Clearl E RULE 1103. I up pulled :111out fil	y state all pertinent For Multiple Compl pipe and pac 1 bit plugged	details, and give etions: Attach we ker. I up come or	ellbore diagram of propose	
OTHER: 13. Describe proportion of starting any or recompletion Started 9/9/17/04, 9/18/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a	erations. (Clearl E RULE 1103. I up pulled tillout fill	y state all pertinent For Multiple Compl pipe and pac l bit plugged d drilling ou	details, and give etions: Attach we ker. I up come out fill.	ellbore diagram of propose	d completion
OTHER: 13. Describe proportion of starting any or recompletion Started 9/9/17/04, 9/18/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo	erations. (Clearly ERULE 1103. It is pulled the string, in the correct string,	y state all pertinent For Multiple Compl pipe and pac l bit plugged d drilling ou picked up pa	details, and give etions: Attach we ker. I up come out fill. acker, Run	ellbore diagram of propose ut of holes. in hole, set pac	d completion
OTHER: 13. Describe proportion of starting any or recompletion Started 9/9/17/04, 9/18/04,	osed or completed op proposed work). SE n. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa	erations. (Clearly ERULE 1103. It is pulled till till till till till till till til	y state all pertinent For Multiple Compl pipe and pac l bit plugged d drilling ou picked up pa	details, and give etions: Attach we ker. I up come out fill. acker, Run	ellbore diagram of propose	d completion
OTHER: 13. Describe proportion of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol	erations. (Clearle ERULE 1103. It is pulled till till till till till till till til	y state all pertinent For Multiple Compl pipe and pace 1 bit plugged d drilling ou picked up pace , hooked onto	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off sto	ellbore diagram of propose ut of holes. in hole, set pac em nippled down a	d completion ker and nd up,
OTHER: 13. Describe proposition of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall	erations. (Clearly ERULE 1103.) I up pulled fillout fill ind finished ork string, acker fluid e.	y state all pertinent For Multiple Compl pipe and pac 1 bit plugged d drilling of picked up pa , hooked onto	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off sto	ellbore diagram of propose ut of holes. in hole, set pace em nippled down and cks with 100 bbls	d completion ker and nd up, fresh
OTHER: 13. Describe proposition of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall	erations. (Clearly ERULE 1103.) I up pulled fillout fill ind finished ork string, acker fluid e.	y state all pertinent For Multiple Compl pipe and pac 1 bit plugged d drilling of picked up pa , hooked onto	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off sto	ellbore diagram of propose ut of holes. in hole, set pace em nippled down and cks with 100 bbls	d completion ker and nd up, fresh
OTHER: 13. Describe proposition of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall	erations. (Clearly ERULE 1103.) I up pulled fillout fill ind finished ork string, acker fluid e.	y state all pertinent For Multiple Compl pipe and pac 1 bit plugged d drilling of picked up pa , hooked onto	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off sto	ellbore diagram of propose ut of holes. in hole, set pace em nippled down and cks with 100 bbls	d completion ker and nd up, fresh
OTHER: 13. Describe proposition of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall	erations. (Clearly ERULE 1103.) I up pulled fillout fill ind finished ork string, acker fluid e.	y state all pertinent For Multiple Compl pipe and pac 1 bit plugged d drilling of picked up pa , hooked onto	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off sto	ellbore diagram of propose ut of holes. in hole, set pace em nippled down and cks with 100 bbls	d completion ker and nd up, fresh
OTHER: 13. Describe proposition of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall	erations. (Clearly ERULE 1103.) I up pulled fillout fill ind finished ork string, acker fluid e.	y state all pertinent For Multiple Compl pipe and pac 1 bit plugged d drilling of picked up pa , hooked onto	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off sto	ellbore diagram of propose ut of holes. in hole, set pace em nippled down and cks with 100 bbls	d completion ker and nd up, fresh
OTHER: 13. Describe proposition of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall	erations. (Clearly ERULE 1103.) I up pulled fillout fill ind finished ork string, acker fluid e.	y state all pertinent For Multiple Compl pipe and pac 1 bit plugged d drilling of picked up pa , hooked onto	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off sto	ellbore diagram of propose ut of holes. in hole, set pace em nippled down and cks with 100 bbls	d completion ker and nd up, fresh
OTHER: 13. Describe proposition of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall	erations. (Clearly ERULE 1103.) I up pulled fillout fill ind finished ork string, acker fluid e.	y state all pertinent For Multiple Compl pipe and pac 1 bit plugged d drilling of picked up pa , hooked onto	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off sto	ellbore diagram of propose ut of holes. in hole, set pace em nippled down and cks with 100 bbls	d completion ker and nd up, fresh
OTHER: 13. Describe proposition of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall	erations. (Clearly ERULE 1103.) I up pulled fillout fill ind finished ork string, acker fluid e.	y state all pertinent For Multiple Compl pipe and pac 1 bit plugged d drilling of picked up pa , hooked onto	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off sto	ellbore diagram of propose ut of holes. in hole, set pace em nippled down and cks with 100 bbls	d completion ker and nd up, fresh
OTHER: 13. Describe proportion of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04, 9/21/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall flush. Turn 134 joints I. 5/½215.5 # ni set at 4214.8	erations. (Clearly ERULE 1103.) I up pulled fillout fill and finished ork string, acker fluid e. On acid jowell back of the control of the co	y state all pertinent For Multiple Comple pipe and page of the plugged drilling of picked up page of the pooked onto the with 2-1000 on run M.I.T. @4209.14 d Lockset page of the page of	details, and give etions: Attach we ker. I up come on t fill. I cker , Run o on-off storm all blocker with or cker with or	in hole, set pace em nippled down and cks with 100 bbls acker was complet tool	ker and up, fresh e.
OTHER: 13. Describe proportion of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04, 9/21/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall flush. Turn 134 joints I. 5/1/215.5 # ni set at 4214.8	erations. (Clearly ERULE 1103.) I up pulled fillout fill and finished ork string, acker fluid e. On acid jowell back of the control of the co	y state all pertinent For Multiple Comple pipe and page of the plugged drilling of picked up page, hooked onto the with 2-1000 on run M.I.T. @4209.14 d Lockset page ete to the best of my	details, and give etions: Attach we ker. It up come on the fill. It is considered to the constant of the const	in hole, set pace em nippled down as cks with 100 bbls acker was complet tool	ker and up, fresh e.
OTHER: 13. Describe proposed of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04, 9/21/04, I hereby certify that the grade tank has been/will be	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall flush. Turn 134 joints I. 5/1/215.5 # ni set at 4214.8	erations. (Clearly ERULE 1103.) I up pulled fillout fill and finished ork string, acker fluid e. On acid jowell back of the control of the co	y state all pertinent For Multiple Compl pipe and pace 1 bit plugged d drilling ou picked up pace , hooked onto b with 2-1000 on run M.I.T. @4209.14 d Lockset pace ete to the best of my guidelines \(\Bar{A}, a general	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off stood at the composition of	in hole, set pace mippled down and cks with 100 bbls acker was complet tool tool tool tool tool tool tool t	ker and up, fresh e.
OTHER: 13. Describe proportion of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04, 9/21/04,	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall flush. Turn 134 joints I. 5/1/215.5 # ni set at 4214.8	erations. (Clearly ERULE 1103.) I up pulled fillout fill and finished ork string, acker fluid e. On acid jowell back of the control of the co	y state all pertinent For Multiple Comple pipe and page of the plugged drilling of picked up page, hooked onto the with 2-1000 on run M.I.T. @4209.14 d Lockset page ete to the best of my	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off stood at the composition of	in hole, set pace mippled down and cks with 100 bbls acker was complet tool tool tool tool tool tool tool t	ker and up, fresh e.
OTHER: 13. Describe proposed of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04, 9/21/04, I hereby certify that the grade tank has been/will be	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall flush. Turn 134 joints I. 5/1/215.5 # ni set at 4214.8	erations. (Clearly ERULE 1103.) I up pulled fillout fill and finished ork string, acker fluid e. On acid jowell back of the control of the co	y state all pertinent For Multiple Compl pipe and pace 1 bit plugged d drilling ou picked up pace , hooked onto b with 2-1000 on run M.I.T. @4209.14 d Lockset pace ete to the best of my guidelines \(\Bar{A}, a general	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off stood at the composition of	in hole, set pace mippled down and cks with 100 bbls acker was complet tool tool tool tool tool tool tool t	ker and up, fresh e.
OTHER: 13. Describe proposed of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04, 9/21/04, I hereby certify that the grade tank has been/will be SIGNATURE	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall flush. Turn 134 joints I. 5/1/215.5 # ni set at 4214.8	erations. (Clearly ERULE 1103.) I up pulled fillout fill and finished ork string, acker fluid e. On acid jowell back of the control of the co	y state all pertinent For Multiple Compl pipe and pace 1 bit plugged d drilling ou picked up pace , hooked onto b with 2-1000 on run M.I.T. @4209.14 d Lockset pace ete to the best of my guidelines \(\), a general	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off stood at the composition of	in hole, set pace em nippled down and cks with 100 bbls acker was complet tool tool tool tool tool tool tool t	ker and up, fresh e.
OTHER: 13. Describe proportion of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04, 9/21/04, I hereby certify that the grade tank has been/will be SIGNATURE Type or print name For State Use Only	osed or completed op proposed work). SE on. /16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall flush. Turn 134 joints I. 5/1/215.5 # ni set at 4214.8	erations. (Clearly ERULE 1103. It up pulled tillout fill and finished ork string, acker fluid e. con acid job well back of the contact of the	y state all pertinent For Multiple Compl pipe and pace 1 bit plugged d rilling ou picked up pace hooked onto b with 2-1000 on run M.I.T. @4209.14 d Lockset pace tet to the best of my guidelines \(\sum_{\text{, a general}} \)	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off sto I salt bloome on the salt bloome of the salt bloome of the complex of t	in hole, set pace em nippled down and cks with 100 bbls acker was completed to tool tool tool tool tool tool tool	ker and up, fresh e.
OTHER: 13. Describe proportion of starting any or recompletion Started 9/9/17/04, 9/18/04, 9/20/04, 9/21/04, I hereby certify that the grade tank has been/will be SIGNATURE Type or print name	osed or completed op proposed work). SE on. 16/04, Rigged Ran bit to dr Ran new bit a Layed down wo circulated pa moved off hol Did 3000 gall flush. Turn 134 joints I. 5/½215.5 # ni set at 4214.8	erations. (Clearly ERULE 1103. It up pulled tillout fill and finished ork string, acker fluid e. con acid job well back of the contact of the	y state all pertinent For Multiple Compl pipe and pace 1 bit plugged d rilling ou picked up pace hooked onto b with 2-1000 on run M.I.T. @4209.14 d Lockset pace tet to the best of my guidelines \(\sum_{\text{, a general}} \)	details, and give etions: Attach we ker. I up come out fill. acker, Run o on-off sto I salt bloome on the salt bloome of the salt bloome of the complex of t	in hole, set pace em nippled down and cks with 100 bbls acker was complet tool tool tool tool tool tool tool t	ker and up, fresh e.

