

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

FORM APPROVED  
OMB No. 1004-0135  
Expires November 30, 2000

**SUNDRY NOTICES AND REPORTS ON WELLS**  
*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**

1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator  
ConocoPhillips

3a. Address  
4001 Penbrook Drive Odessa, TX 79762

3b. Phone No. (include area code)  
(432)368-1207

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  
Section 4, T-21-S, R-36-E, Lot #10  
3430 FNL & 1750 FEL

5. Lease Serial No.  
LC 031740B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.  
Meyer B 4 #33

9. API Well No.  
30-025-35884

10. Field and Pool, or Exploratory Area  
Oil Center; Blinbry

11. County or Parish, State  
Lea County, NM


**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/ Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other <b>Remove active well from TA Status</b>
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

This well shows to be temporarily abandoned by the BLM - the well was re-completed to the Blinbry 09/30/03, please see attached documentation. Currently the well is an active producer.

Please remove this well from the temporarily abandoned well list



14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Kay Maddox

Signature

Title

Regulatory Agent

Date

09/15/04

9/15/04

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENTFORM APPROVED  
OMB No. 1004-0135  
Expires November 30, 2000

## SUNDRY NOTICES AND REPORTS ON WELLS

*Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.*

**SUBMIT IN TRIPLICATE - Other instructions on reverse side**1. Type of Well  
☒ Oil Well ☐ Gas Well ☐ Other2. Name of Operator  
ConocoPhillips Company3a. Address  
4001 Penbrook Street Odessa TX 797623b. Phone No. ( include area code )  
(432)368-16674. Location of Well ( Footage, Sec., T., R., M., or Survey Description )  
3430' FNL & 1750' FEL  
Lot #10, Sec. 4, T-21-S, R-36-E5. Lease Serial No.  
LC 031740B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.  
Meyer B 4, Well #339. API Well No.  
30-025-3588410. Field and Pool, or Exploratory Area  
Oil Center; Blinebry11. County or Parish, State  
Lea  
New Mexico

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/ Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input checked="" type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Tubb zone abandoned, Blinebry isolated, per the following well report:

09/29/03 Held PJSM. MIRU pulling unit over well. Unhang well, bled psi DN. Unseat pump, COOH w/rods & pump. MIRU pump truck, kill well. ND wellhead, NU BOP. COOH w/tbg. Shut well in, SION.

09/30/03 Held PJSM. MIRU pump truck, kill well. Wait on BLM rep. RIH w/CIBP & PKR on 2-7/8" tbg. Set CIBP @ 6550', pull up set pkr & test CIBP to 550 psi, O.K. Release pkr, COOH w/tbg & pkr. RIH w/prod. tbg. ND BOP, NU wellhead. Shut dn, SION.

10/01/03 Held PJSM. Open well, RIH w/pump & rods, space well out. MIRU pump truck, load & test 500 psi, O.K. Hang well on, rig dn pulling unit. Will move pulling unit.

14. I hereby certify that the foregoing is true and correct  
Name ( Printed/Typed )

Celeste G. Dale

Title  
Regulatory Analyst

Signature

Date  
10/10/2003**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

( Instructions on reverse )