New Maxico Oil Conservation Division, District I 1625 N. French Drive Hobbs, NM 83240				
Form 3160-5 UNITED STATES (August 1999) DEPARTMENT OF THE INTERIOR			FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000	
BUREAU OF LAND MANAGEMENT			5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an			LC031670B 6. If Indian, Allottee or Tribe Name	
abandoned well. Use Form 3160-3 (APD) for such proposals.				
SUBMIT IN TRIPLICATE - Other instructions on reverse side 1. Type of Well				7. If Unit or CA/Agreement, Name and/or No.
X Oil Well Gas Well Other				8. Well Name and No. Warren Unit #116
2. Name of Operator ConocoPhillips Company				9. API Well No.
3a. Address 4001 Penbrook Street - Oc	3b. Phone No. (include area code) (432)368-1506		30-025-32520 10. Field and Pool, or Exploratory Area	
4. Location of Well(Footage, Sec., T., R., M., or Survey Description) 660' FNL & 610' FWL, Sec. 28, T-20-S, R-38-E, UL. D				Warren Blinebry Tubb
				11. County or Parish, State Lea County, New Mexico
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION			
□ Notice of Intent		Deepen	Production (Start	· —
Subsequent Report	 Alter Casing Casing Repair 	 Fracture Treat New Construction 	 Reclamation Recomplete 	Well Integrity
Final Abandonment Notice	 Change Plans Convert to Injection 	Plug and AbandonPlug Back	Temporarily AbaWater Disposal	
 Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Forne 31604 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, anothe operator has determined that the site is ready for final inspection.) 3/30/2004: HELD PJSM. MIRU PULLING UNIT. UNHANG WELL, BLED PSI DN. JARRED ON PUMP, BUMP STUCK. BACKED OFF RODS. SHUT WELL IN, SION. 				
2. 3/31/2004: HELD PJSM. COOH WITH RODS LAYING THEM DN ON BOARDS. MIRU PUMP TRUCK, KILL WELL. ND WELLHEAD, NU BOP AND ENVIROVAT. COOH WITH TUBING, STRIPPING WELL OUT OF HOLE. SHUT WELL IN, SION.				
3. 4/1/2004: HELD PJSM. CONTINUED STRIPPING WELL OOH. PUMP STUCK IN BOTTOM JOINT, DUE TO SCALE. RIH WITH TUBING, TAG FOR FILL. TAGGED AT 6948', NO FILL. MIRU TUBOSCOPE, SCAN TUBING OOH. FOUND 5 BAD JOINTS, TUBING SCANNED 192 YELLOW, 18 BLUE, 3 GREEN, 1 RED AND 1 JT WITH PUMP STUCK IN IT. SHUT WELL IN. SION.				
*** conf				tinued on back***
		<u></u>		
 I hereby certify that the foregore Name (<i>Printed/Typed</i>) Stacey D. Linder 	ing is true and correct	Title HSE/R	egulatory Represe	entative
Signature Stacen N- Ninder Date 09/10/2004				
ACCEPTED FOR FEDERAL OR STATE OFFICE USE				
Conditions of approval, if any, Stefftta2heft. A004val of this notice does not warrant or certify that the applicant holds legal or equitable tille to those rights in the subject lease which would entitle the applicant to conduct one rations thereon				or record only! Approval returning well to production and keeping
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make fraudulent statements or representations as to any matter within its jurisdiction.				

Warren Unit #116

- 4. 4/20/2004: HELD PJSM. OPEN WELL. RIH WITH PROD TBG, RAN 2-3/8 SN, 1 JT 2-7/8 POLY LINED TBG, 30 JTS 2-3/8 TBG, TAC, 184 JTS 2-3/8 TBG. MIRU PUMP TRUCK, ND BOP, NU WELLHEAD. DISPLACE 500 GAL XYLENE FOLLOWED W/ 15 BBLS TREATED BW DN TBG. WAIT 3HRS. DISPLACE 500 GAL 15% ACID FOLLOWED W/ 15 BBLS TREATED BW DN TBG. SHUT WELL IN, SIOWE.
- 5. 4/5/2004: HELD PJSM. OPEN WELL. RIH W/ SWAB, FLUID LEVEL AT 6100'. HAD PROBLEMS SWABBING DUE TO FLOW LINE BEING PLUGGED UP. WAIT ON HOT OILER TO PUMP DN FLOW LINE. RD HOT OILER. PICK UP PUMP, AND RIH W/ RODS. PICKING UP RODS OFF BOARDS. SPACE WELL OUT. SHUT DN.
- 6. 4/6/2004: HELD PJSM. OPEN WELL, CHANGE OUT PACKING ON STUFFING BOX. WAIT ON ROUSTABOUTS TO UNPLUG FLOW LINE. MIRU PUMP TRUCK, LOAD AND TEST, 500 PSI, OK. GOOD PUMP ACTION. RIG PULLING UNIT DN.

BOSWELL OFFICE BURRAU OF LAND MOME

SOUG SEP IL A MILL: 33

RECEVED