Submit 3 Copies To Appro	onriate District	Stata a	f Marry Ma				E	C 100
Office			f New Me				Form	
District I		Energy, Mineral	rgy, Minerals and Natural Resources		WELLA	May 27, 2004 WELL API NO.		
1625 N. French Dr., Hobb District II	5 N. French Dr., Hobbs, NM 88240				WELL A			
	301 W. Grand Ave., Artesia, NM 88210 OIL CO.		NSERVATION DIVISION		C T 1	30-005-20822		
District III	Sor W. Grand Heel, Muesia, Will 00210		O South St. Francis Dr.			5. Indicate Type of Lease		
	Pio Brazos Rd Aztec NM 87/10			, NM 87505		STATE FEE		
District IV Salita FC 1220 S. St. Francis Dr., Santa Fe, NM			1°C, 19191 07	C, 141VI 07505		6. State Oil & Gas Lease No.		
87505		,						
		CES AND REPORTS		· · · · · · · · · · · · · · · · · · ·	7. Lease		it Agreement N	lame
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMI						Paul LR		
PROPOSALS.)		ATION FOR FERMIT (FO	IT (FORM C-101)FOR SOCH		8. Well	Number		
		Gas Well 🔲 Other	ether RECEIVED			8	,	
2. Name of Operator			Ht		9. OGR	ID Number		
Yates Petrole	eum Corporatio	on	CI.	P 2 4 7004		025	575	
3. Address of Operat			••	-	10. Pool	l name or Wil	dcat	
105 S. 4 <sup>th</sup> St	reet, Artesia, N	JM 88210	001	BARTESIA		Tom To	om SA	
4. Well Location			<del></del>					
Unit Letter	G : 1	1980 feet from the	North	line and	1980	feet from the	East	line
Section	25	Township	7S Ra	nge 31E	NMPM	Chaves	County	
		11. Elevation (Show						
		11. Dievation (Bhow	4390 <sup>3</sup>					
Pit or Below-grade Tank	Application 🗌 o	r Closure 🗌						
		Distance from n	earest fresh w	ater well	Distance from r	nearest surface w	vater N/A	
Pit Liner Thickness:	mil	Below-Grade Tank: N	volume	DDIS;	Construction N	laterial		
	12. Check A	Appropriate Box to I	Indicate N	ature of Notic	e. Report o	r Other Dat	a	
					-			
		TENTION TO:	_			NT REPO		_
PERFORM REMEDIA	AL WORK 📋	PLUG AND ABANDC	)N 🖂					
				REMEDIAL WO			ERING CASIN	
TEMPORARILY ABA		CHANGE PLANS						
					DRILLING OP			
TEMPORARILY ABA PULL OR ALTER CA		CHANGE PLANS		COMMENCE D	DRILLING OP			
TEMPORARILY ABA PULL OR ALTER CA OTHER:	NDON	CHANGE PLANS MULTIPLE COMPL		COMMENCE D CASING/CEME OTHER:	DRILLING OP ENT JOB	NS. PLU	IG AND ABAND	
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop	NDON	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear	Tly state all j	COMMENCE E CASING/CEME OTHER: pertinent details,	ORILLING OP ENT JOB and give pert	NS. PLU	G AND ABAND	
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an	NDON SING posed or compl y proposed wo	CHANGE PLANS MULTIPLE COMPL	I I rly state all j For Multip	COMMENCE E CASING/CEME OTHER: pertinent details, le Completions:	ORILLING OP ENT JOB and give pert Attach wellb	NS. PLU	G AND ABAND	DN
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop	NDON SING posed or compl y proposed wo	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear	I I rly state all j For Multip	COMMENCE E CASING/CEME OTHER: pertinent details, le Completions:	ORILLING OP ENT JOB and give pert Attach wellb	NS. PLU	IG AND ABAND	DN
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti	NDON SING posed or compl y proposed wo on.	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103.	I I rly state all J For Multip	COMMENCE D CASING/CEME OTHER: pertinent details, le Completions:	and give pert Attach wellb	NS. PLU	IG AND ABAND cluding estima f proposed cor BE NOTIFIED	Ited dat mpletio 24
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp	NDON SING posed or compl y proposed wo on. oration plans to	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103.	I I rly state all J For Multip	COMMENCE D CASING/CEME OTHER: pertinent details, le Completions:	and give pert Attach wellb	NS. PLU	IG AND ABAND cluding estima f proposed cor BE NOTIFIED	Ited dat mpletio 24
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq	NDON SING ossed or compl y proposed wo ion. oration plans to uipment neces	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary.	Tly state all J For Multip	COMMENCE D CASING/CEME OTHER: pertinent details, le Completions:	and give pert Attach wellb URS PRIOR	NS. PLU inent dates, in ore diagram o ON MUST B TO THE B ERATIONS F	IG AND ABAND cluding estima f proposed cor BE NOTIFIED	Ited dat mpletio 24
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a	NDON SING oosed or compl y proposed wo on. oration plans to uipment neces at 3965' with 3	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary.	Tly state all J For Multip	COMMENCE D CASING/CEME OTHER: pertinent details, le Completions:	and give pert Attach wellb	NS. PLU inent dates, in ore diagram o ON MUST B TO THE B ERATIONS F	IG AND ABAND	Ited dat mpletio 24
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with	NDON SING SING SING SING SING SING SING SIN	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary.	Tly state all J For Multip	COMMENCE D CASING/CEME OTHER: pertinent details, le Completions:	and give pert Attach wellb URS PRIOR	NS. PLU inent dates, in ore diagram o ON MUST B TO THE B ERATIONS F	IG AND ABAND cluding estima f proposed cor BE NOTIFIED	Ited dat mpletio 24
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole	NDON SING SING SING SING SING SING SING SIN	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug.	Tly state all p For Multip	COMMENCE E CASING/CEME OTHER: pertinent details, le Completions: lows: THE HO PLU TO	and give pert Attach wellb URS PRIOR JGGING OP BE APPRO	NS. PLU inent dates, in ore diagram o ON MUST B TO THE B ERATIONS F	IG AND ABAND cluding estima f proposed cor BE NOTIFIED	Ited dat mpletio 24
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement	NDON SING SING SING SING SING SING SING SIN	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary.	Tly state all p For Multip	COMMENCE E CASING/CEME OTHER: pertinent details, le Completions: lows: THE HO PLU TO	and give pert Attach wellb URS PRIOR JGGING OP BE APPRO	NS. PLU	IG AND ABAND icluding estima f proposed cor BE NOTIFIED IEGINNING OR THE C-10	Ited dat mpletio 24
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole	NDON SING SING SING SING SING SING SING SIN	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640	rly state all p For Multip s well as foll	COMMENCE E CASING/CEME OTHER: pertinent details, le Completions: lows: THE HO PLU TO	and give pert Attach wellb URS PRIOR JGGING OP BE APPRO	NS. PLU	IG AND ABAND icluding estima f proposed cor BE NOTIFIED IEGINNING OR THE C-10	Ited dat mpletio 24
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cem	NDON SING oposed or compl y proposed wo on. oration plans tr uipment neces at 3965' with 3 9.5# mud. is at 1740'. in and out of cr is at 60'. ment in and out	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. (	rly state all p For Multip s well as foll	COMMENCE E CASING/CEME OTHER: pertinent details, le Completions: lows: THE HO PLU TO	and give pert Attach wellb URS PRIOR JGGING OP BE APPRO	NS. PLU inent dates, in ore diagram o ON MUST F TO THE B ERATIONS F VED.	IG AND ABAND Icluding estima f proposed con BE NOTIFIED IEGINNING OR THE C-10	DN Ited dat mpletio 2.4 3 3 3 3
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole	NDON SING oposed or compl y proposed wo on. oration plans tr uipment neces at 3965' with 3 9.5# mud. is at 1740'. in and out of cr is at 60'. ment in and out	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. (	rly state all p For Multip s well as foll	COMMENCE E CASING/CEME OTHER: pertinent details, le Completions: lows: THE HO PLU TO	and give pert Attach wellb URS PRIOR JGGING OP BE APPRO	NS. PLU inent dates, in ore diagram o ON MUST F TO THE B ERATIONS F VED.	IG AND ABAND Icluding estima f proposed con BE NOTIFIED IEGINNING OR THE C-10	DN Ited dat mpletio 2.4 3 3 3 3
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead an	NDON SING oposed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 .9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. (( er.	Tag plug)	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hous: THE HO PLL TO cement to 1640'.	and give pert Attach wellb URS PRIOR JGGING OP BE APPRO	NS. PLU inent dates, in ore diagram o ON MUST F TO THE B ERATIONS F VED.	IG AND ABAND Icluding estima f proposed con BE NOTIFIED IEGINNING OR THE C-10	DN Ited dat mpletio 2.4 3 3 3 3
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead an	NDON SING oposed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 .9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. (	Tag plug)	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hous: THE HO PLL TO cement to 1640'.	and give pert Attach wellb URS PRIOR JGGING OP BE APPRO	NS. PLU inent dates, in ore diagram o ON MUST F TO THE B ERATIONS F VED.	IG AND ABAND Icluding estima f proposed con BE NOTIFIED IEGINNING OR THE C-10	DN Ited dat mpletio 2.4 3 3 3 3
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead an	NDON SING oposed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 .9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. (( er.	Tag plug)	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hous: THE HO PLL TO cement to 1640'.	and give pert Attach wellb URS PRIOR JGGING OP BE APPRO	NS. PLU inent dates, in ore diagram o ON MUST F TO THE B ERATIONS F VED.	IG AND ABAND Icluding estima f proposed con BE NOTIFIED IEGINNING OR THE C-10	DN Ited dat mpletio 2.4 3 3 3 3
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead an	NDON SING oposed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 .9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. (( er.	Tag plug)	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hous: THE HO PLL TO cement to 1640'.	and give pert Attach wellb URS PRIOR JGGING OP BE APPRO	NS. PLU inent dates, in ore diagram o ON MUST F TO THE B ERATIONS F VED.	IG AND ABAND Icluding estima f proposed con BE NOTIFIED IEGINNING OR THE C-10	DN Ited dat mpletio 2.4 3 3 3 3
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead an	NDON SING oposed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 .9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. (( er.	Tag plug)	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hous: THE HO PLL TO cement to 1640'.	and give pert Attach wellb URS PRIOR JGGING OP BE APPRO	NS. PLU inent dates, in ore diagram o ON MUST F TO THE B ERATIONS F VED.	IG AND ABAND Icluding estima f proposed con BE NOTIFIED IEGINNING OR THE C-10	DN Ited dat mpletio 2.4 3 3 3 3
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead an	NDON SING oposed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 .9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. (( er.	Tag plug)	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hous: THE HO PLL TO cement to 1640'.	and give pert Attach wellb URS PRIOR JGGING OP BE APPRO	NS. PLU inent dates, in ore diagram o ON MUST F TO THE B ERATIONS F VED.	IG AND ABAND Icluding estima f proposed con BE NOTIFIED IEGINNING OR THE C-10	DN Ited dat mpletio 2.4 3 3 3 3
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead an NOTE: Yates Petroleu	NDON SING ossed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark um Corporatio	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. ( er.	Tag plug)	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: House: THE HO PLU TO cement to 1640'.	ORILLING OP ENT JOB and give pert Attach wellb COMMISSI URS PRIOR JGGING OP BE APPROV	NS. PLU inent dates, in ore diagram o ON MUST F TO THE B ERATIONS F VED.	IG AND ABAND Icluding estima f proposed con BE NOTIFIED IEGINNING OR THE C-10	DN Ited dat mpletio 2.4 3 3 3 3
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead ar NOTE: Yates Petroleu I hereby certify that th	NDON SING oosed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 .9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark um Corporatio	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. ( er. <i>n will use steel pits and</i>	Tag plug)	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hows: THE HO PLL TO cement to 1640'.	COMMISSI URS PRIOR JGGING OP BE APPROV	NS. PLU inent dates, in ore diagram o ON MUST E TO THE E ERATIONS F VED.	IG AND ABAND ICluding estima f proposed cor BE MOTIFIED IECINNING OR THE CIO OR THE CIO ICL 2006 NUCL ICL 2006 ICL 2006 ICL 2006 ICL 2006 ICL 2007 ICL 2	DN ited dat mpletio 24 3 3 3 3 3 5 6 6 6 6 6 7 6 6 6 7 7 7 8 7 7 7 7 7 7 7 7 7 7 7 7 7
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead ar NOTE: Yates Petroleu I hereby certify that th	NDON SING oosed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 .9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark um Corporatio	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. ( er.	Tag plug)	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hows: THE HO PLL TO cement to 1640'.	COMMISSI URS PRIOR JGGING OP BE APPROV	NS. PLU inent dates, in ore diagram o ON MUST E TO THE E ERATIONS F VED.	IG AND ABAND ICluding estima f proposed cor BE MOTIFIED IECINNING OR THE CIO OR THE CIO ICL 2006 NUCL ICL 2006 ICL 2006 ICL 2006 ICL 2006 ICL 2007 ICL 2	DN ited dat mpletio 24 3 3 3 3 3 5 6 6 6 6 6 7 6 6 6 7 7 7 8 7 7 7 7 7 7 7 7 7 7 7 7 7
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead ar NOTE: Yates Petroleu I hereby certify that th	NDON SING oosed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 .9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark um Corporatio	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. ( er. <i>n will use steel pits and</i> above is true and comp	rly state all j For Multip s well as foll '. Displace Tag plug) d no earth pi	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hous: THE HO PLU TO cement to 1640'.	DRILLING OP ENT JOB and give pert Attach wellb COMMISSI URS PRIOR JGGING OP BE APPRO (Tag plug)	NS. PLU inent dates, in ore diagram o ON MUST E TO THE B ERATIONS F VED.	IG AND ABAND ICluding estima f proposed cor SE NOTIFIED IEGINNING OR THE C-10 IEGINNING OR THE C-10 IEGINNING OCD - approved p	DN tted dat mpletio 24 3 3 3 3 3 5 6 6 6 7 6 7 6 7 6 7 7 7 8 7 7 7 7 7 7 7 7 7 7 7 7 7
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead ar NOTE: Yates Petroleu I hereby certify that th grade tank has been/will b	NDON SING oosed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 .9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark um Corporatio	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. ( er. <i>n will use steel pits and</i> above is true and comp	rly state all j For Multip s well as foll '. Displace Tag plug) d no earth pi	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hows: THE HO PLL TO cement to 1640'.	DRILLING OP ENT JOB and give pert Attach wellb COMMISSI URS PRIOR JGGING OP BE APPRO (Tag plug)	NS. PLU inent dates, in ore diagram o ON MUST E TO THE B ERATIONS F VED.	IG AND ABAND ICluding estima f proposed cor BE MOTIFIED IECINNING OR THE CIO OR THE CIO ICL 2006 NUCL ICL 2006 ICL 2006 ICL 2006 ICL 2006 ICL 2007 ICL 2	DN tted dat mpletio 24 3 3 3 3 3 5 6 6 6 7 6 7 6 7 6 7 7 7 8 7 7 7 7 7 7 7 7 7 7 7 7 7
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead ar NOTE: Yates Petroleu I hereby certify that th grade tank has been/will b	NDON SING sosed or comply proposed wo ion. oration plans to uipment neces at 3965' with 3 9.5# mud. in and out of cases at 1740'. in and out of cases at 60'. nent in and out d install marked are constructed or be constructed or	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. ( er. <i>n will use steel pits and</i> above is true and comp closed according to NMOC	I I I I I I I I I I I I I I I I I I I	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hows: THE HO PLU TO cement to 1640'.	DRILLING OP ENT JOB and give pert Attach wellb COMMISSI URS PRIOR JGGING OP BE APPROV (Tag plug) (Tag plug)	NS. PLU inent dates, in ore diagram o ON MUST B TO THE B ERATIONS F VED. C. I further cer hed) alternative DATE _S	IG AND ABAND ICluding estima f proposed cor BE NOTIFIED IEGINNING OR THE C-10 IEGINNING OR THE C-10 IEGINNING IEGINNING OR THE C-10 IEGINNING IEGINNING OR THE C-10 IEGINNING IEGINNING OR THE C-10 IEGINNING IE	$\frac{1}{2004}$
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cem 8. Cut off wellhead ar NOTE: Yates Petroleu I hereby certify that th grade tank has been/will b SIGNATURE	NDON SING sosed or comply proposed wo ion. oration plans to uipment neces at 3965' with 3 9.5# mud. in and out of cases at 1740'. in and out of cases at 60'. nent in and out d install marked are constructed or be constructed or	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. ( er. <i>n will use steel pits and</i> above is true and comp closed according to NMOC	I I I I I I I I I I I I I I I I I I I	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hows: THE HO PLU TO cement to 1640'.	DRILLING OP ENT JOB and give pert Attach wellb COMMISSI URS PRIOR JGGING OP BE APPROV (Tag plug) (Tag plug)	NS. PLU inent dates, in ore diagram o ON MUST B TO THE B ERATIONS F VED. C. I further cer hed) alternative DATE _S	IG AND ABAND ICluding estima f proposed cor SE NOTIFIED IEGINNING OR THE C-10 IEGINNING OR THE C-10 IEGINNING OCD - approved p	$\frac{1}{2004}$
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cem 8. Cut off wellhead ar NOTE: Yates Petrolea I hereby certify that th grade tank has been/will b SIGNATURE Type or print name	NDON SING sosed or comply proposed wo ion. oration plans to uipment neces at 3965' with 3 9.5# mud. in and out of cases at 1740'. in and out of cases at 60'. nent in and out d install marked are constructed or be constructed or	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. ( er. <i>n will use steel pits and</i> above is true and comp closed according to NMOC LUCC TITL	I I I I I I I I I I I I I I I I I I I	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: HO PlU TO cement to 1640'.	DRILLING OP ENT JOB and give pert Attach wellb COMMISSI URS PRIOR JGGING OP BE APPROV (Tag plug) (Tag plug)	NS. PLU	IG AND ABAND ICluding estima f proposed cor SE NOTIFIED IEGINNING OR THE CAU 12345 OUT 200 12345 OUT 200 12345 000 12345 000 12345 000 12345 0000 000 000 0000 0000 0000 0000 0000 0000 0000 0000 0000 0000 0000 0000 0000 0000 0000 00000 0000 00000 00000 00	DN $\square$ ited dat inpletio 24 24 3 3 3 3 3 3 3 3
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cen 8. Cut off wellhead ar NOTE: Yates Petroleu I hereby certify that th	NDON SING oosed or comply y proposed wo ion. oration plans to uipment neces at 3965' with 3 .9.5# mud. is at 1740'. in and out of cr is at 60'. nent in and out d install mark um Corporatio	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. ( er. <i>n will use steel pits and</i>	Tag plug)	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hows: THE HO PLL TO cement to 1640'.	COMMISSI URS PRIOR JGGING OP BE APPROV	NS. PLU inent dates, in ore diagram o ON MUST E TO THE E ERATIONS F VED.	IG AND ABAND ICluding estima f proposed cor BE MOTIFIED IECINNING OR THE CIO OR THE CIO ICL 2006 NUCL ICL 2006 ICL 2006 ICL 2006 ICL 2006 ICL 2007 ICL 2	$\frac{1}{24}$
TEMPORARILY ABA PULL OR ALTER CA OTHER: 13. Describe prop of starting an or recompleti Yates Petroleum Corp 1. MIRU all safety eq 2. Set a 4-1/2" CIBP a 3. Circulate hole with 4. Shoot squeeze hole 5. Spot 50 sx cement 6. Shoot squeeze hole 7. Circulate 25 sx cem 8. Cut off wellhead an NOTE: Yates Petroleu I hereby certify that th grade tank has been/will b SIGNATURE Type or print name	NDON SING sosed or comply proposed wo ion. oration plans to uipment neces at 3965' with 3 9.5# mud. in and out of cases at 1740'. in and out of cases at 60'. nent in and out d install marked are constructed or be constructed or	CHANGE PLANS MULTIPLE COMPL leted operations. (Clear rk). SEE RULE 1103. o plug and abandon this sary. 5' cement on plug. asing from 1740'-1640 of casing to surface. ( er. <i>n will use steel pits and</i> above is true and comp closed according to NMOC	I I I I I I I I I I I I I I I I I I I	COMMENCE I CASING/CEME OTHER: pertinent details, le Completions: Hows: THE HO PLU TO cement to 1640'.	DRILLING OP ENT JOB and give pert Attach wellb COMMISSI URS PRIOR JGGING OP BE APPROV (Tag plug) (Tag plug)	NS. PLU	IG AND ABAND ICluding estima f proposed cor BE NOTIFIED IEGINNING OR THE C-10 IEGINNING OR THE C-10 IEGINNING IEGINNING OR THE C-10 IEGINNING IEGINNING OR THE C-10 IEGINNING IEGINNING OR THE C-10 IEGINNING IE	DN $\square$ ited dat inpletio 24 24 3 3 3 3 3 3 3 3

Conditions	ofAn	proval	(if any
Conditions	or np	provar	(II ally





4