## New Mexico Oil Conservation Division, District I

Form 3160-5 (August 1999)

1625 N. French Drive **UNITED STATES** DEPARTMENT OF THE INTERIOR Obbs, NM 88240 BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0135 Expires November 30, 2000

5. Lease Serial No. LC 063458

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side  1. Type of Well				7. If Unit or CA/Agreement, Name and/or No.	
☐ Oil Well ☐ Gas Well ☐ Other  2. Name of Operator				8. Well Name and No. Warren Unit, Well #146	
ConocoPhillips Company  3a. Address  4001 Penbrook Street - Oc	3b. Phone No. (include (432)368-1506	le area code)	9. API Well No. 30-025-34362		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 660' FSL & 860' FEL, Sec 26, T-20-S, R-38-E				10. Field and Pool, or Exploratory Area Warren Blinebry Tubb (62965)  11. County or Parish, State Lea County, NM	
12. CHECK AF	PROPRIATE BOX(ES)	ΓΟ INDICATE NATU	RE OF NOTICE,	REPORT, OR O	THER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
<ul><li>□ Notice of Intent</li><li>☑ Subsequent Report</li><li>□ Final Abandonment Notice</li></ul>	<ul> <li>□ Acidize</li> <li>□ Alter Casing</li> <li>□ Casing Repair</li> <li>□ Change Plans</li> <li>□ Convert to Injection</li> </ul>	<ul> <li>□ Deepen</li> <li>□ Fracture Treat</li> <li>□ New Construction</li> <li>□ Plug and Abandon</li> <li>□ Plug Back</li> </ul>	Production (S Reclamation Recomplete Temporarily A Water Dispose	□ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑ ☑	Water Shut-Off Well Integrity Other Commingle the wellbore.
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof if the proposal is to deepen directionally or recomplete horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)  1. 4/21/04: HELD PJSM. MIRU PULLING UNIT. UNHANG WELL, BLED PSI DN. UNSEAT PUMP. LET EQUALIZED START COOH W/ RODS, LAYING DN RODS (C-RODS). LAID DN 79 7/8 RODS. SHUT WELL, N, SION, SI					
14. I hereby certify that the foregoin Name (Printed/Typed)	ng is true and correct	Title	77		
Stacey D. Linder			egulatory Repre	sentative	
Signature	N. Linder	Date 09/15/2			
Conditions of approval, if any a spacertify that the applicant Holds legal which would entitle the applicant to	DAVID R. GLASS  Ittached Approval of this notic of equilibric title to those rights conduct operations thereon.	ce does not warrant or s in the subject lease	îice	Date	
Title 18 U.S.C. Section 1001, makes fraudulent statements or representati	ons as to any matter within its	vingly and willfully to make jurisdiction.	to any department o	r agency of the Unite	d States any false, fictitious or

## Warren Unit #146

- **4. 4/26/04:** HELD PJSM. OPEN WELL, WAIT ON RODS TO BE DELIVERED. RIH W/ PUMP AND RODS, PICKING UP RODS OFF BOARDS, SPACE WELL OUT. WAIT ON PUMP TRUCK. MIRU PUMP TRUCK, LOAD AND TEST, 500 PSI,OK. GOOD PUMP ACTION. SHUT DN. LEFT WELL PUMPING.
- 5. 4/27/04: HELD PJSM. GOOD PUMP ACTION, RIG DN PULLING UNIT.

BUTEAL OF LEVED MALAT. FORMS DEPOSOR

71 -01 M 12 933 PB

HEGEINED