New Mexico Oil Conservation Division. District I

Form 3460-5 UNITED S (April 2004) DEPARTMENT O BUREAU OF LANI SUNDRY NOTICES ANI Do not use this form for proper	OF THE INTERIOR MANAGEMENT D REPORTS OSAIS to drill	ON WELLS	-	
abandoned well. Use Form 316 SUBMIT IN TRIPLICATE- Other 1. Type of Well Gas Well 2. Name of Operator EOG Resources, Inc	50 - 3 (APD) for	such proposals.	7. If Unit or CA/Agreement, Name and/or No. Diamond "34" Federal 8. Well Name and No. 3	
3a Address P.O. Box 2267, Midland, TX, 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Unit Letter N, 660 FSL, 1980 FWL Section 34, Township 23-S, Range 32-E		e No. (include area code) 51- 8600	9. API Well No. 30-025-33351 10. Field and Pool, or Exploratory Area West Triste Draw Delaware 11. County or Parish, State Lea, New Mexico	
12. CHECK APPROPRIATE BOX(TYPE OF SUBMISSION Acidize Alter Casing Casing Repair Change Plans Convert to Inject: 13. Describe Proposed or Completed Operation (clearly state if the proposal is to deepen directionally or recomplete he Attach the Bond under which the work will be performed following completion of the involved operations. If the office involved operations is the performed following completion of the involved operations. If the office involved operations is the performed following completion of the involved operations. If the office involved operations is the performed following completion of the involved operations. If the office involved operations is the performed following completion of the involved operations.	Deeper Fractur New C Plug an ion Plug Be e all pertinent details, prizontally, give subsu	TYPE OF ACTION Production (Star Reclamation Recomplete and Abandon Temporarily Abandon Water Disposal including estimated starting date of any prace locations and measured and true.)	Well Integrity Other proposed work and approximate duration thereof. vertical depths of all pertinent markers and zones.	
following completion of the involved operations. If the otesting has been completed. Final Abandonment Notices determined that the site is ready for final inspection.) 1. Notify BLM 24 hrs prior to MI and RU. 2. Set 5 1/2" CIBP at 7400, spot 25sx, plug from 3. Displace hole with MLF, 9.5# Brine w/25# ge 4. Spot 25sx, plug from 6100-5900 (Cherry Can 5. Spot 45sx, plug from 5000-4600 (Rustler, 8 5. 6. Cut 5 1/2" csg at 2500, L/D csg.	n 7400-7240 (Delayel P/BBL.	numple completion or recompletion in ter all requirements, including reclamater all requirements, ware) WOC Tag.		

- Cut 3 1/2 Csg at 2500, L/D csg.
 Spot 35sx, plugfrom 2550-2450 (Stub).
 Spot 80sx, plug from 700-400 (13 3/8 Shoe) WOC Tag.
 10sx Surf, install dry hole marker.

		O_{3}
 		0'21
Title	Consultant	. 100
Date	09/29/2004	
OR STATE C	FFICE USE	
Title	Date	OCT 0 4 2004
nt or ase Office		
	Date OR STATE C Title	Date 09/29/2004 OR STATE OFFICE USE Title Date

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)



SEE ATTACHED FOR CONDITIONS OF APPROVAL

PLUGGING & ABANDONHENT WORKSHEET