New Mexico Oli Conservation Division, District I 1625 M. French Drive FORM APPROVE

Form 3160-5 (JUNE 1990)				\$240 Bu	FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993 5. Lease Designation and Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals					NM 27805 6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE 1. Type of Well					7. If Unit or CA, Agreement Designation		
Oil Gas Well Well Other					l Name and No.		
2. Name of Operator STRATA PRODUCTION COMPANY					Connally Federal #1		
3. Address and Telephone No. P. O. Box 1030					30-025-27772		
Roswell, New Mexico 88202-1030 505-622-1127					10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					Red Tank Cisco Canyon East		
Section 15, T22S-R32E					11. County or Parish, State		
1980' FSL & 1980' FEL					Lea County		
12. CHECK APPI	ROPRIATE BOX	(s) TO INDICATE I	NATURE OF NOTICE	REPOR	RT. OR OTHER DA	TA	
TYPE OF SUBMISSION TYPE OF ACTION						TA 123456	
Notice of Intent		Abandonment			Change of Plans		
X Subsequent Rep	oort	=	upletion ng Back		New Construction / OV Non-Routine Fracturing/	OCD Hopps	
		Casing	Repair		Water Shut-Off	YCASINED	
Final Abandonn	nent Notice		ng Casing		Conversion to Injection	MW 100	
		Other	Workover		Dispose Water \\C		
13. Describe Proposed or Completed C	Operations (Clearly state all per	tinent details, and give pertinent date	s, including estimated date of starting an	nronosed work	Note: Report results of multiple completion of Well Completion or Recompletion Report and to French	25150261811	
09/08/04: TO @ 09/09/04: TO w/r 09/10/04: SIF 09/11/04: TIF 30 09/14/04: TIF wei 09/15/04: Co TIF wei 09/16/04: Co on ope 09/17/04: RU w/5	iks. SD. IH w/overshot 9204'. Jar the IH w/tbg & ove nill. Prep to o IH w/tbg. SD o IH w/mills. Tag nill. PU, GIH IH w/cutters. O IH w/overshot o IH w/oversh	& jars. Rec 1 2 g loose. SOH wershot. LD 12 jr lress stub. Leave lue to repair rig. at 9242'. Dres w/cutters. Ran Cut tbg @ 9304'. derrick. Leave & jars. Latch on 2-7/8" Tbg. PU, vershot & jars. Couldn't pass 98 fish. Leave well w/fish. LD 30 jr 36'. PU to 130,00 gb. e. Couldn't pass eight. Cont out	ch on to fish @ 92/ 2-7/8" collar. TIH v /5 pnts over string its 2-7/8" tbg. Bot /e well open to tar Leave well open s stub & clean out 40 stands in hole. TOH w/fish. PU, well open to tanks to fish at 9304'. C GIH w/overshot & Latch on to fish at 326'. TOH w/wireli open to tanks. Sl its 2-7/8" pipe. PU 000#. Set off jars. s 10562'. TOH w/ of hole w/tbg. Recell open to tanks.	w/overs w/over	hot & jars. Catce eave well open to collapsed. PU, obs. SD. 6'. Circ bottoms well open to tandovershot & jars. PU, RU rotary were the collapsed of the collapsed of RU wireline. Let the collapsed of RU wireline.	h fish tanks. SD. GIH up. TOH nks. SD. Have ery little tanks. SD. vireline. s extra s. Latch eave well	
			-				
Signed Signed Signed	PULL STORE TO	ECORD THE Prod	uction Records	_{D-1} 1	10/15/04		
				Date	10/10/04		
Approved by Conditions of approval, if any	SGD/DAVI	OR.GLASS Trile		Date		 .	

* See Instruction on Reverse Side

F3160-5.WK1