	· · · · · · · · · · · · · · · · · · ·	• •	* 12					
6	Unica	f New Me		Form C-103 May 27, 2004 WELL API NO. 30-025-20794				
	District I Energy, Mineral 1625 N. French Dr., Hobbs, NM 88240 District II							
	1301 W. Grand Ave., Artesia, NM 88210 OIL CONSER			5. Indicate Type of Lease				
	District III 1000 Rio Brazos Rd., Aztec, NM 87410			STATE X FEE				
	District IV Santa F 1220 S. St. Francis Dr., Santa Fe, NM 87505	Fe, NM 8'	/505	6. State Oil & Gas Lease No. B-1501				
	SUNDRY NOTICES AND REPORTS O (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DE DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FO PROPOSALS.)	7. Lease Name or Unit Agreement Name Vacuum Glorieta East Unit Tract 15						
	1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other			 8. Well Number 002 9. OGRID Number 217817 10. Pool name or Wildcat Vacuum Glorieta 				
	2. Name of Operator ConocoPhillips Company							
	3. Address of Operator 4001 Penbrook Street Odessa, TX 79762							
	4. Well Location							
	Unit Letter O : 810 feet from the	e South	line and	55 feet from the East line				
	Section 30 Township 1		ange 35E	NMPM CountyLea				
	11. Elevation (Show w	whether DR	, RKB, RT, GR, etc.)					
	Pit or Below-grade Tank Application 🗌 or Closure 🗌 Pit typeDepth to GroundwaterDistance from n	earest fresh v	vater well Dist	ance from nearest surface water				
	Pit Liner Thickness: mil Below-Grade Tank: V			nstruction Material				
:	· · · · · · · · · · · · · · · · · · ·							
	12. Check Appropriate Box to I	noicate N	ature of notice,	Report of Other Data				
	NOTICE OF INTENTION TO:			SEQUENT REPORT OF:				
	PERFORM REMEDIAL WORK PLUG AND ABANDO TEMPORARILY ABANDON X CHANGE PLANS		REMEDIAL WORK					
	TEMPORARILY ABANDON X CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL		COMMENCE DRI					
			CASING/CEMENT	I JOB				
-	OTHER:		OTHER:					
	 Describe proposed or completed operations. (Clear of starting any proposed work). SEE RULE 1103. or recompletion. 	For Multip	le Completions: Att	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion				
	Procedure and wellbore diagram attached							
	Ŭ			121314157677 30				
				15. 10 Hold 22				
				45 031. Jun 23				
				2				
				0008610				
_								
1	hereby certify that the information above is true and comple rade tank has been/will be constructed or closed according to NMOCI	ete to the b guidelines	est of my knowledge], a general permit []	e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan .				
1	SIGNATURE Stacey he Kinder	_TITLERe	gulatory Representa	tiveDATE_10/20/2004				
	Type or print name Stacey D. Linder	E-mail ad	ldress:stacey.d.linde	Telephone No. (432)368-1506				
	APPROVED BY: Law 1). Wink	TITLE	ظمینے سے ا	NTATIVE II/STAFF MANAGER				
	Conditions of Approval (if ary):		OC FIELD REPRESE	NIANVEN, SHATE DATE UCT 2 6 2004				

RECOMMENDED TEMPORARY ABANDONMENT PROCEDURE:

- 1. Test anchors as required.
- 2. Hold safety meeting & MIRU Well Service Unit.
- 3. POOH with rods and insert pump as required.
- 4. RU pump truck and kill well. Ensure well is dead. ND wellhead. NU BOPE.
- 5. POOH with production tubing. Visually inspect tubing while COOH. If condition is good, use tubing as workstring. If not, lay down production tubing and PU tubing workstring.
- 6. TIH with bit and casing scraper to top perf in each well as shown below. POOH with bit & casing scraper.

<u>WELL</u>	TOP PERF
#02-06	5985'
#15-02	6064'
#17-03	6076'
#19-03	6069'
#27-02	6051'
#32-01	6148'
#37-04	5939'

- 7. PU and GIH with 4-1/2" CIBP on workstring. Set CIBP within 100' of top perforation as shown in Step 6 above.
- 8. Test casing and CIBP to 500 psig for 30 minutes per NMOCD requirements
- 9. RU pump truck and circulate well with inhibited packer fluid containing corrosion inhibitor.
- 10. POOH and lay down workstring.
- 11. ND BOPE and NU wellhead.
- 12. RDMO well service unit.

ConocoPhillips - Permian Basin Business Unit March 27, 2003

	RKB: 3994' DF: ' GL: 3982' 12-1/4" hole 8-5/8" 24# J-55 Casing 51 jts. ST&C, set @ 1598' 640 sx cmt. TOC @ surface	Lease & Well No.: Well Category: Area: Subarea: API Number: Legal Description: Spudded: Completed:		VGEU #15-02 New Mexico Buckeye 30-025-20794 810' FSL & 1955' FEL, Lea County, New Mexic 08/06/1964		(formerly Phillips Sante Fe #100) Status:SI (hole in tubing) Field: Vacuum Glorieta , Sec 30, T-17-S, R-35-E ico		
	TOC @ 2500' (Temp Survey 8/20/64)	Well History: <u>Date</u> 8/23/1964 8/26/1964 9/25/1975 " 7/23/1980 " 7/13/1984 "	Interval 6064'- 6074' 6064'- 6074' 6064'- 6074' " 6064'- 6074' "	Type 15% HCL 15% HCL 28% HCL 3% HCL 15% HCL Gelled brine 28% Gelled Nitrogen Gelled brine	Gals 500 1500 2000 3250 3000 6000 275 MCF 8000	Sand None None " 2500# 20/40 "	Rate BPM 0.75 2.9 4 " 6 " 10 "	Max. Press 2800 2800 2000 " 0 # " 2800#
	Glorieta Perforations 2 SPF (08/22/64) 20 holes 6064-6074	Queen Grayburg San Andres	2857 3713 3975 4380 5920					
PBTD: TD:	6143' 6200'	Equipment Data 193 jts 2 3/8" 4.7 TAC @ 5972', St 2" x 1 1/4" x 16' r 70 - 7/8" D rods a	# J-55 Tubing E N @ 6089' od pump					

7-7/8" Hole 4 1/2" Casing: 177 jts. 5760' 9.5# J-55, 14 jts. 439' 10.5# ST&C 800 sx cmt

۰. پ

-

٠.

.