

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.	30-025-26803-00-00
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name:	Rountree
8. Well No.	1
9. Pool name or Wildcat	Wildcat/San Andres)

SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Rountree	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		8. Well No. 1	
2. Name of Operator Western Oil Producers Inc		9. Pool name or Wildcat Wildcat/San Andres	
3. Address of Operator P O Box 2055 Roswell, NM 88202			
4. Well Location Unit Letter <u>N</u> : <u>660</u> feet from the <u>South</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>8</u> Township <u>20S</u> Range <u>36E</u> NMPM County <u>Lea</u>			
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3622.2 GR			

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions : Attach wellbore diagram of proposed completion or recompletion.

13 3/8"  365' 9 5/8"  5510'

Perfs 3666' to 3674' and 3696' to 3702'

Set a CIBP 3,640' 35 sks cement on top

Set 100' plug 3,300', set 100' plug 2,000', set 100' plug 1,000', set 100' plug 415'


50' in and 50' out 13 3/8" — TAG

10 sks surface plug

Install dry hole marker

USE - STEEL PIT
OVER 1000' TO WATER WELL
" " TO SURFACE WATER
DEPTH TO WATER - 33'

**THE OIL CONSERVATION DIVISION MUST
BE NOTIFIED 24 HOURS PRIOR TO THE
BEGINNING OF PLUGGING OPERATIONS.**



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TABLE

DATE _____

Type or print name

Genny Long

Telephone No. _____

(This space for State use)

APPROVED BY

Conditions of approval, if any:

~~CC FIELD REPRESENTATIVE II/STAFF MANAGER~~ **Now**

2004