Form C-103 Submit 3 Copies To Appropriate District State of New Mexico Office Energy, Minerals and Natural Resources Revised March 25, 1999 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-36247 District II OIL CONSERVATION DIVISION 811 South First, Artesia, NM 87210 5. Indicate Type of Lease 2040 South Pacheco District III STATE X FEE 🗆 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 2040 South Pacheco, Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) North Hobbs G/SA Unit 1. Type of Well: Oil Well X Gas Well Other 8. Well No. 2. Name of Operator 527 Occidental Permian Limited Partnership 9. Pool name or Wildcat 3. Address of Operator P.O. Box 4294. Houston. TX 77210-4294 Hobbs: Grayburg - San Andres 4. Well Location 1782 627 South feet from the_ West feet from the_ line and line Unit Letter _ 30 Range **NMPM** County Lea Section Township 18-S 38-E 10. Elevation (Show whether DR, RKB, RT, GR, etc.) 3649' GR 11. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK **ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. **PLUG AND ABANDONMENT CASING TEST AND PULL OR ALTER CASING MULTIPLE** COMPLETION CEMENT JOB X OTHER: OTHER: Spud & Run Surface Casing 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation. 5/19/03: MI x RU. Spud 12-1/4" hole at 9:00 p.m. (NMOCD notified) Hobbs 5/20/03 -Run 38 jts. 8-5/8", 24#, J-55, ST&C casing with 10 centralizers and set at 1536 5/21/03: Cement with 550 sx. PBCZ lead and 300 sx. Premium Plus tail. Circulate Nosx, to surface. Plug down x WOC. Nipple up BOPE x test to 1200 psi. TIH x PU drill superior to 1200 psi. Test pipe rams x annular to 1200 psi. Drill out cement and resume drilling operations. I hereby certify that the information above is true and complete to the best of my knowledge and belief. TITLE Regulatory Compliance Analyst DATE SIGNATURE_ Mark Stephens Type or print name Telephone No. 281/552-1158 (This space for State use) MAY 2 8 2003

OC FIELD REPRESENTATIVE IL/STAFF MANAGER

APPROVED BY

Conditions of approval, if any