Submit 3 Copies To Appropriate District	State of	New Me	avico		
Office District I	Energy, Minerals and Natural Resources				Form C-103
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.	May 27, 2004
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION				30-025-09787
District III	1220 South St. Francis Dr.			5. Indicate Type of L	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505			STATE	FEE 🔀
1220 S. St. Francis Dr., Santa Fe, NM 87505	e, NM			6. State Oil & Gas Le 141560	ease No.
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Un	it Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH					
TROPOSALS.)				Cooper Jal Unit	
1. Type of Well: Oil Well 2. Name of Operator	Gas Well Other	🗙 Inje	ector	8. Well Number	211 w
2. Name of Operator	SDG Resources L. P.			9. OGRID Number	193003
3. Address of Operator	P. O. Box 1390			10 Deal annual Will	
	Montrose, CO 81402			10. Pool name or Wil Yates & 7-Rivers.	ldcat JALMAT:
4. Well Location					
Unit LetterK	:2310feet from the _	SOUTI	I line and	2310feet from the	WEST line
Section 24	Township		Range 36E	NMPM LEA	
	11. Elevation (Show wh	hether DR,	RKB, RT, GR, etc.)	1.2	e county
Pit or Below-grade Tank Application		3,313' K			
Pit type_DIRT_Depth to Groundwater_	130'				
Pit Liner Thickness: 400 mil	Below-Grade Tank: Volum	rest fresh wa			e water_>1000 feet
oralle 200 Dbis, Construction Material Synthetic					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK	PLUG AND ABANDON		REMEDIAL WORK		
	CHANGE PLANS		COMMENCE DRILL	LING OPNS. 🗍 🛛 P AI	
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMENT	ЈОВ 🗌	
OTHER: Clean out injector w/Coile	ed Tubing and Acidize	D3 -	OTHER:		_
13. Describe proposed or completed operations. (Clearly state all pertinent details and give pertinent details					
of standing any proposed work). SEE RULE 1103. FOF WILLEIDIE Completions. Attach wellhow diagram - from the test					
or recompletion.					
Objective: Clean out injector w/Coiled Tubing and Acidize with 4,000 gallons 15% NEFE HCl acid.					
123-20-03					
1. MIRU Coiled Tubing Unit.				~~2°	
 RIH 1 ¼" Perf-Clean Tool on 1 Energize Tool and clean out on 	¹ / ₄ " coil tubing to 2962'.			in the second	1
 Energize Tool and clean out open hole 3,001'-3,400' with surfactant water. Acidize open hole 3,001'-3,400' with 4,000 gallons 15% NEFE HCl acid. POOH with coiled tubing and rig down Perf-Clean Tool. BD Coiled Tubing Unit 					
5. POOH with coiled tubing and rig down Perf-Clean Tool.					
6. RD Coiled Tubing Unit.				la O	
7. Place well on injection at appro	ximately 220 bwpd.			100	
8. Maximum permitted injection p	ressure is 600 psig.			51.81	
				000	919191910
Lhereby certify that the information	1				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below- grade tank has been/will be constructed or closed according to NMOCD guidelines Z, a general permit \Box or an (attached) alternative OCD-approved plan \Box .					
SIGNATURE LETTING	anyoles 1	TITLE_S	enior Petroleum Eng	ineer [DATE_11/10/04_
Type or print name	E-mail a	address: D	omingo@sdgresourc	es.com Telenhone N	lo. 432-550-7580
For State Use Only				-steen relephone N	0. 432-330-7380
APPROVED BY:	Wanto -		D REPRESENTATIVI	- II/STAFE MANNA CEO	NOV
APPROVED BY: Conditions of Approval (if any):					

