

New Mexico Oil Conservation Division, District I
1625 N. French Drive
Hobbs, NM 88240

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

3a. Address

3b. Phone No. (include area code)

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

9. API Well No.

10. Field and Pool, or Exploratory Area

11. County or Parish, State

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/ Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal


☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

see attachment



14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

Title

Signature

Date

ACCEPTED FOR RECORD THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on reverse)

TEXLAND PETROLEUM, INC.

CASING AND CEMENTING REPORT

Well: **BOWERS A 45**Date: **10-15-04**

Jts	Item	Length	Depth
	KB-BELL NIPPLE GL	6.00	6.00
90	5 1/2 15.5# J55 LTC	3936.13	3942.13
	STAGE TOOL	2.20	3944.33
16	5 1/2 17# J55 LTC WRAP EXT.	721.20	4665.43
23	5 1/2 15.5# J55 LTC	1023.03	5688.46
	DEPTH CONTROL COLLAR	1.10	5689.56
24	5 1/2 15.5# J55 LTC	1078.49	6768.05
1	5 1/2 15.5# J55 SHORT JT	27.25	6795.30
7	5 1/2 17# J55 LTC	314.85	7110.15
	FLOAT COLLAR	1.10	7111.25
1	5 1/2 17# J55 LTC	45.02	7156.27
	FLOAT COLLAR	1.10	7157.37
1	5 1/2 15.5# ORANGE PEELED JT	10.34	7167.78

163 JTS

Cement Information

Service Co.: **HOBBS**

CMT 1st STAGE W/ 525 SKS SUPER H 2.5# SALT, 0.4% LAP-1, 0.3% CFR3
 0.25 D-AIR 3000 MIXED AT 13.2# 1.62 YIELD DISPL. W/ 90 BFW X 79 BAK PIT
 MUD Plug DOWN AT 05:15 HRS ON 10/15/4 FLOAT HOLD OPEN STAGE TOOL
 CIRC 32 BLS CMT OFF TOOL

CMT 2nd STAGE W/ 230 SKS INFILL C MIXED AT 11.9# 2.45 YIELD
 300 SKS CLASS C 0.5% LAP-1, 0.2% CFR3 MIXED AT 15# 1.29 YLD
 625 SKS INFILL C 1/4# CF MIXED AT 11.9# 2.45 YIELD 50 SKS CLASS
 C MIXED AT 14.8# 1.32 YIELD DISPL W/ 93 BFW Plug DOWN AT
 15:15 HRS 10/15/4 CLOSE STAGE TOOL HOLD OK CIRC 75 SKS CMT TO PIT
 -JAM