



Form C-103
March 4, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Chevron USA Inc

3. Address of Operator
15 Smith Rd, Midland, TX 79705

4. Well Location
- Unit Letter G : 1980 feet from the North line and 2080 feet from the East line
- Section 22 Township 21-S Range 36-E NMPM Lea County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)

Pit Location: UL G Sect 22 Twp 21S Rng 36E Pit type Steel Depth to Groundwater 150 Distance from nearest fresh water well Over 1000'
Distance from nearest surface water _____ Below-grade Tank Location UL _____ Sect _____ Twp _____ Rng _____ ;
1980 feet from the North line and 2080 feet from the East line (Steel Tank)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	<input checked="" type="checkbox"/> SUBSEQUENT REPORT
-------------------------	---

- | | | | |
|-----------------------|--------------------------|---------------------|-------------------------------------|
| PERFORM REMEDIAL WORK | <input type="checkbox"/> | PLUG AND ABANDON | <input checked="" type="checkbox"/> |
| TEMPORARILY ABANDON | <input type="checkbox"/> | CHANGE PLANS | <input type="checkbox"/> |
| PULL OR ALTER CASING | <input type="checkbox"/> | MULTIPLE COMPLETION | <input type="checkbox"/> |
| OTHER: | | | <input type="checkbox"/> |

- SUBSEQUENT REPORT OF:**
- REMEDIAL WORK ☐ ALTERING CASING ☐
- COMMENCE DRILLING OPNS ☐ PLUG AND ☒
ABANDONMENT
- CASING TEST AND ☐ Hobbs
CEMENT JOB ☐ OGD
- OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. RIH Tag 5 1/2" CIBP at 3920, spot 25sx, plug from 3920-3700 (Grayburg).
2. Displace hole w/MLF, 9.5# Brine w/12.5# gel P/BBL.
3. Spot 35sx, plug from 2900-2600 (8 5/8 Shoe, B-Salt) Tag at 2566.
4. Perf 4 holes at 1600, sqz 75sx from 1600-1300 (T-Salt) Tag at 1190.
5. Perf 4 holes at 410, Circ cmt from 410-Surf w/125sx (11 3/4 Shoe) Tag at Surf.
7. Install dry hole marker 618-04.

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE [Signature] TITLE Consultant DATE 6-8-04

Type or print name Jimmy Bagley E-mail address: _____ Telephone No. 432-561-8600

(This space for State use)

DEC 06 2004

APPROVED BY Larry W. Wink OCTOBER REPRESENTATIVE II/STAFF MANAGER DATE 10/1/88

Conditions of approval, if any: