UNITED STATES

New Mexico Oil Conservation Division, D. Form, Approved 1625 N. French Drive

Budget Bureau	No.	1004-013

Form 3160-5 (JUNE 1990) DEPARTMENT OF THE INTERIOR Hobbs, NM 88240

	Expires. Water 31, 1993
SUNDRY NOTICES AND REPORTS ON WELLS	5. Lease Designation and Serial No. NM-10529
Do not use this form for proposals to drill or to deepen or reentry to a different reservoir. Use "APPLICATION FOR PERMIT-" for such proposals	6. If Indian, Allottee or Tribe Name
SUBMIT IN TRIPLICATE	7. If Unit or CA, Agreement Designation
Гуре of Well Oil Gas Well Well Other	
	8. Well Name and No.
Name of Operator STRATA PRODUCTION COMPANY	SDE 18 Federal #1
Address and Telephone No. P. O. Box 1030	30-025-25622
Roswell, New Mexico 88202-1030 505-622-1127	10. Field and Pool, or Exploratory Area
ocation of Well (Footage, Sec., T., R., M., or Survey Description)	Sand Dunes Delaware East
990' FNL & 1980' FWL	11. County or Parish, State
Section 18-23S-32E	Lea County, New Mexico

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION	•
X Notice of Intent	Abandonment	Change of Plans
	Recompletion	New Construction
Subsequent Report	X Plug	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	OTHER	Dispose Water
		(Note: Report results of multiple completion on Well
Describe Proposed or Completed Operations (Class	rly state all pertinent details and sive negliges 4.4.	Completion or Recompletion Report and Log form.)

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plugging Procedure:

- 1. MIRU.
- 2. Set CIBP @ 8335' with 35' cement on top.
- 3. Spot 25 sacks @ 6749'-6849'.
- 4. Spot 25 sacks @ 4600'-4700'. WOC, Tag.
- 5. Spot 25 sacks @ 2500'-2600'.
- 6. Spot 25 sacks @ 916'-1016'. WOC, Tag.
- 7. Spot 10 sacks @ 50' to surface. Cut off wellhead. RD.
- 8. Install dry hole marker, remove equipment, clean, rip and reseed location per BLM guidelines.

Attachments from Mayo Marrs: Procedure and rig availability

14. I hereby certify that the foregoing is true and correct				<u></u>
Signed Keug Moritt Title (This space for Federal or State office use)	Production Records	Date	11/30/2004	
Approve (ORIG. SGD.) DAWD R. GLASS Title Conditions of approval, if any:		Date _	DEC 0 2 2004	



MAYO MARRS CASING PULLING, INC.

P.O. Box 863

Kermit, Tx. 79745 915-586-3076

11-22-02

STRATA PRODUCTION COMPANY

PO. BOX 1030

ROSWELL, N.M. 88202

Attn: KELLY BRITT

PHONE 505-622-112"

FAX 505-623-3533

Dear Ms. Britt

Mayo Marrs Casing Pulling Inc. would like to submit an offer to P&A as follows:

SDE 18 FEDERAL # 1

\$ 10,085.00

PROCEEDURE:

- 1. MIRU MOVE IN WORKSTRING MOVE IN STEEL PIT
- 2. SET CIBP @ 8335' DUMP 35' CEMENT ON TOP-RIH WITH TUBING
- 3. CIR. 9.5# MUD-POOH
- 4. SPOT 25 SXS @ 6849'-6749'
- 5. SPOT 25 SXS @ 4800'-4700' -WOC- TAG
- 6. SPOT 25 SXS @ 2600'-2500'
- 7. SPOT 25 SXS @ 1018'-918' -WOC TAG
- 8. SPOT 10 SXS @ 50' TO SURFACE CUT OFF WELLHEAD-RIG DOWN
- 9. INSTALL DRY HOLE MARKER-EMPTY PIT MOVE OUT

A RESPONSIBILITY SHEET IS ATTACHED.

ANY CHANGES DUE TO OCD, BLM OR STRATA WOULD BE BILLED FROM OUR CURRENT RATES.

We do appreciate the opportunity to furnish this bid and look forward to any help we may be.

Sincerely,

Rickey Smith

MAYO MARRS CASING PULLING INC. BOX 863 KERMIT, TEXAS 79745 (915) 586-3076 FAX (915) 586-2453

TO:	KELLY BRITT
COMPANY	STRATA
FAX#	505-623-3533
# OF PAGES	INCLUDING FAX COVER SHEET
FROM:	RICKEY SMITH
DATE:	
COMMENTS:	
IT WOULD BE NOTIFICATION	1-5 WEEKS BEFORE WE HAVE A RIG LOOSE ACCORDING TO
THANKS,	
RICKEY SMIT	· · · · · · · · · · · · · · · · · · ·