Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resourc	es May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	N 30-025-34039
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	•	VA-1000
	ICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLI	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH	
PROPOSALS.)	C W-11 📈 O4	8. Well Number
1. Type of Well: Oil Well	Gas Well Other	1
2. Name of Operator		9. OGRID Number
Yates Petroleum Corporation 3. Address of Operator	On	025575 10. Pool name or Wildcat
105 S. 4 th Street, Artesia,	NM 88210	Townsend Permo Upper Penn
4. Well Location		
Unit Letter C	330 feet from the North line and	1360 feet from the West line
Section 29	Township 15S Range 35	
是是一个一个的。 第一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个一个	11. Elevation (Show whether DR, RKB, RT, G	R, etc.)
Pit or Below-grade Tank Application	4018' GR	
)	r Distance from nearest fresh water well	Distance from nearest surface water
Pit Liner Thickness: mil		ols; Construction Material
12. CHECK	Appropriate Box to Indicate Nature of No.	ouce, Report or Other Data o
NOTICE OF IN	ITENTION TO:	SUBSEQUENT REPORT OF:/
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL	
TEMPORARILY ABANDON	CHANGE PLANS	CE DRILLING OPNS TO BE AND A
PULL OR ALTER CASING	MULTIPLE COMPL	EMENT JOB
OTHER:	OTHER:	
	OTHER:	uils, and give pertinent dates, including estimated date
of starting any proposed we	ork). SEE RULE 1103. For Multiple Completion	ns: Attach wellbore diagram of proposed completion
or recompletion.	•	• • • •
or recompletion.	,	
or recompletion. 8-12-04 to 11-17-04		Moved packer up hole and isolated hole in casing
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok about the set of th	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' a	Moved packer up hole and isolated hole in casing and spotted 50 sx "H" Neat w/fluid loss. Squeezed to
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' ar @ 4650' and pumped 250 sx "C" Neat thru he	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to oles 4697-4762'. Squeezed to 500#. Drilled retainer
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru here and cement to 10292'. Latched RBP @ 10	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to bles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru hater and cement to 10292'. Latched RBP @ 10 spotted 3 sx 20/40 sand on RBP. Set cement ret	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to bles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. Sufficiently well as a square of the set of the	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru here and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement ret 10# w/75 sx in formation. Drilled retainer and	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to bles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. Sufficiently with the set of the set	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru her and cement to 10292'. Latched RBP @ 10 spotted 3 sx 20/40 sand on RBP. Set cement ret 10# w/75 sx in formation. Drilled retainer and wn tubing to 1200#. Bled down to 600# in 15 m	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to bles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. Sufficiently with the set of the set	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru hater and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement ret 10# w/75 sx in formation. Drilled retainer and we tubing to 1200#. Bled down to 600# in 15 m and loss into 11687-11711'. Squeezed to 5000#	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to bles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok abd 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. Sufficiently with the set of the se	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru hater and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement ret 10# w/75 sx in formation. Drilled retainer and wn tubing to 1200#. Bled down to 600# in 15 m id loss into 11687-11711'. Squeezed to 5000# 4' to 1000#. Held. Drilled cement to 11711	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to bles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min.
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 11400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru hater and cement to 10292'. Latched RBP @ 10 optited 3 sx 20/40 sand on RBP. Set cement retainer and with the set in formation. Drilled retainer and with tubing to 1200#. Bled down to 600# in 15 m id loss into 11687-11711'. Squeezed to 5000# 4' to 1000#. Held. Drilled cement to 11711 by w/42 .42" holes. Acidized w/1500 gal 7-1/2%	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to oles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min. Morrow acid w/1000 SCF N2/bbls. Set 5-1/2" CIBP
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 11400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru hater and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement ret 10# w/75 sx in formation. Drilled retainer and wn tubing to 1200#. Bled down to 600# in 15 m and loss into 11687-11711'. Squeezed to 5000# 4' to 1000#. Held. Drilled cement to 11711 by w/42 .42" holes. Acidized w/1500 gal 7-1/2% Perforated Wolfcamp (2 JSPF) 9716-23' (16),	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to bles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min.
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 11400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI @ 11813' Capped w/35' cement.	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru hater and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement ret 10# w/75 sx in formation. Drilled retainer and wn tubing to 1200#. Bled down to 600# in 15 m and loss into 11687-11711'. Squeezed to 5000# 4' to 1000#. Held. Drilled cement to 11711 by w/42 .42" holes. Acidized w/1500 gal 7-1/2% Perforated Wolfcamp (2 JSPF) 9716-23' (16),	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to oles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min. Morrow acid w/1000 SCF N2/bbls. Set 5-1/2" CIBP
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 1400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI @ 11813' Capped w/35' cement. holes. Acidized w/3500 gal 20% He	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru hater and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement ret 10# w/75 sx in formation. Drilled retainer and wn tubing to 1200#. Bled down to 600# in 15 m and loss into 11687-11711'. Squeezed to 5000# 4' to 1000#. Held. Drilled cement to 11711 by w/42 .42" holes. Acidized w/1500 gal 7-1/2% Perforated Wolfcamp (2 JSPF) 9716-23' (16),	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to oles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min. Morrow acid w/1000 SCF N2/bbls. Set 5-1/2" CIBP
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 11400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI @ 11813' Capped w/35' cement. holes. Acidized w/3500 gal 20% He 2-7/8" open-ended tubing @ 9640'.	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru he are and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement ret 10# w/75 sx in formation. Drilled retainer and with tubing to 1200#. Bled down to 600# in 15 m and loss into 11687-11711'. Squeezed to 5000# 4' to 1000#. Held. Drilled cement to 11711 at 1000#. Acidized w/1500 gal 7-1/2% Perforated Wolfcamp (2 JSPF) 9716-23' (16), Cl w/Cationic surfactants.	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to oles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min. Morrow acid w/1000 SCF N2/bbls. Set 5-1/2" CIBP 9761-64' (8) and 9782-88' (14) for total of 54 .42"
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 11400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI @ 11813' Capped w/35' cement. holes. Acidized w/3500 gal 20% Held 2-7/8" open-ended tubing @ 9640'.	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru he are and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement ret 10# w/75 sx in formation. Drilled retainer and wn tubing to 1200#. Bled down to 600# in 15 m aid loss into 11687-11711'. Squeezed to 5000# 4' to 1000#. Held. Drilled cement to 11711 at 100 y w/42 .42" holes. Acidized w/1500 gal 7-1/2% Perforated Wolfcamp (2 JSPF) 9716-23' (16), Cl w/Cationic surfactants.	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to coles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min. Morrow acid w/1000 SCF N2/bbls. Set 5-1/2" CIBP 9761-64' (8) and 9782-88' (14) for total of 54 .42"
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 11400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI @ 11813' Capped w/35' cement. holes. Acidized w/3500 gal 20% Held 2-7/8" open-ended tubing @ 9640'.	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru he are and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement ret 10# w/75 sx in formation. Drilled retainer and wn tubing to 1200#. Bled down to 600# in 15 m aid loss into 11687-11711'. Squeezed to 5000# 4' to 1000#. Held. Drilled cement to 11711 at 100 y w/42 .42" holes. Acidized w/1500 gal 7-1/2% Perforated Wolfcamp (2 JSPF) 9716-23' (16), Cl w/Cationic surfactants.	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to oles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min. Morrow acid w/1000 SCF N2/bbls. Set 5-1/2" CIBP 9761-64' (8) and 9782-88' (14) for total of 54 .42"
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 11400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI @ 11813' Capped w/35' cement. holes. Acidized w/3500 gal 20% Held 2-7/8" open-ended tubing @ 9640'.	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru he are and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement ret 10# w/75 sx in formation. Drilled retainer and wn tubing to 1200#. Bled down to 600# in 15 m aid loss into 11687-11711'. Squeezed to 5000# 4' to 1000#. Held. Drilled cement to 11711 at 100 y w/42 .42" holes. Acidized w/1500 gal 7-1/2% Perforated Wolfcamp (2 JSPF) 9716-23' (16), Cl w/Cationic surfactants.	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to oles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min. Morrow acid w/1000 SCF N2/bbls. Set 5-1/2" CIBP 9761-64' (8) and 9782-88' (14) for total of 54 .42" owledge and belief. I further certify that any pit or below-rmit or an (attached) alternative OCD-approved plan
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 11400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI @ 11813' Capped w/35' cement. holes. Acidized w/3500 gal 20% Held 2-7/8" open-ended tubing @ 9640'. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru had been and cement to 10292'. Latched RBP @ 10 spotted 3 sx 20/40 sand on RBP. Set cement retainer and with two the retainer and with the retainer and with the retainer to 1200#. Bled down to 600# in 15 m and loss into 11687-11711'. Squeezed to 5000# 4' to 1000#. Held. Drilled cement to 11711 by w/42 .42" holes. Acidized w/1500 gal 7-1/2% Perforated Wolfcamp (2 JSPF) 9716-23' (16), Cl w/Cationic surfactants.	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to coles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min. Morrow acid w/1000 SCF N2/bbls. Set 5-1/2" CIBP 9761-64' (8) and 9782-88' (14) for total of 54 .42" oveledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 11400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI @ 11813' Capped w/35' cement. holes. Acidized w/3500 gal 20% He 2-7/8" open-ended tubing @ 9640'. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Stormi Da	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru had been and cement to 10292'. Latched RBP @ 10 spotted 3 sx 20/40 sand on RBP. Set cement retainer and with two the retainer and with the retainer and with the retainer to 1200#. Bled down to 600# in 15 m and loss into 11687-11711'. Squeezed to 5000# 4' to 1000#. Held. Drilled cement to 11711 by w/42 .42" holes. Acidized w/1500 gal 7-1/2% Perforated Wolfcamp (2 JSPF) 9716-23' (16), Cl w/Cationic surfactants.	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to oles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min. Morrow acid w/1000 SCF N2/bbls. Set 5-1/2" CIBP 9761-64' (8) and 9782-88' (14) for total of 54 .42" owledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 11400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI @ 11813' Capped w/35' cement. holes. Acidized w/3500 gal 20% Held 2-7/8" open-ended tubing @ 9640'. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru had been and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement retainer and with the set of the wide of the wide of the set of the wide	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to coles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min. Morrow acid w/1000 SCF N2/bbls. Set 5-1/2" CIBP 9761-64' (8) and 9782-88' (14) for total of 54 .42" Description
or recompletion. 8-12-04 to 11-17-04 TIH and set test packer @ 11590' between 4697-4762'. Tested ok ab 4500# w/45 sx. Set cement retaine and cement to 4768'. Drilled retain 1000#. Moved packer to 11200'. S"H" w/fluid loss. Squeezed to 500 annulus to 1200#. Held. Tested do 11220'. Pumped 150 sx "H" w/fluid 11400'. Tested perfs 11260-1132. Perforated Atoka 11863-70' (6 JSPI @ 11813' Capped w/35' cement. holes. Acidized w/3500 gal 20% He 2-7/8" open-ended tubing @ 9640'. I hereby certify that the information grade tank has been/will be constructed or SIGNATURE Type or print name Stormi Da	and test RBP @ 10600'. Tested to 100,000#. ove and below. Set cement retainer @ 10208' at @ 4650' and pumped 250 sx "C" Neat thru had been and cement to 10292'. Latched RBP @ 10 Spotted 3 sx 20/40 sand on RBP. Set cement retainer and with the set of the wide of the wide of the set of the wide	and spotted 50 sx "H" Neat w/fluid loss. Squeezed to coles 4697-4762'. Squeezed to 500#. Drilled retainer 600' and released. Set RBP @ 11400' and tested to ainer @ 11215'. Pumped 100 sx "H" Neat and 50 sx cement to 11330'. Set packer @ 11200' and tested in. Slight leak 11260-11324'. Set cement retainer @ w/90 sx in formation. Drilled retainer and cement to '. Tested squeeze to 1000#. Held ok for 15 min. Morrow acid w/1000 SCF N2/bbls. Set 5-1/2" CIBP 9761-64' (8) and 9782-88' (14) for total of 54 .42" oveledge and belief. I further certify that any pit or belowermit or an (attached) alternative OCD-approved plan