Submit 3 Copies To Appropriate District Office	Diate of New .		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		March 4, 2004 WELL API NO.
District II	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		30 025 33415
1301 W. Grand Ave., Artesia, NM 8821 District III			5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410			STATE X FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM	1 8/303	6. State Oil & Gas Lease No.
87505			B-3196
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			State 35 No. 11
1. Type of Well:		8. Well Number	
Oil Well X Gas Well Other			11
2. Name of Operator			9. OGRID Number
McGowan Working Partners, In 3. Address of Operator	<u>c.</u>		220397 10. Pool name or Wildcat
P.O. Box 55809, Jackson MS 39	9296-5809		Vacuum – Greyburg/San Andres
4. Well Location			
Unit Letter <u>H</u>	: <u>2020</u> feet from the	North line and	1310 feet from the East line
Section 35	Township 175	S Range 341	E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)  Pit Location: ULSectTwpRngPit typeDepth to GroundwaterDistance from nearest fresh water well			
i e			
	Below-grade Tank Location U	ULSectTwp	;
feet from theline an	dfeet from theline		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK X PLUG AND ABANDON  SUBSEQUENT REPORT OF:  REMEDIAL WORK ALTERING CASING			
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRI	LLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AN	ND ABANDONMENT
OTHER:		OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
<ol> <li>Pull production string, run bit to PBTD (4910') and test tubing to 5000 psi.</li> <li>Perf. @ 4270-74', 4302-06', 4515-25', &amp; 4758-84' w/4" casing gun, 2 spf 180 phase</li> </ol>			
3. Acidize in 3 stages using RBP – (1) 4758-84', (2) 4648-4715', (3) 4270-4515'.			
4. Run 2-1/4" WBBL to 4600" on 4" N-80 buttress, crossover to 2-7/8" @ 4250 & hang on tubing rotator, run 2-1/4" pump.			
5. Perform witnessed MIPT and return to service.  I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-			
grade tank has been/will be constructed or closed according to NMOCD guidelines, a general permit or an (attached) alternative OCD-approved plan.			
SIGNATURE Glenn 7	<u>tepner</u> TI	TLE Regulatory O	fficer DATE 22 Nov 04
Type or print name Glenn He	oner E-mail address: g	glenn@mcgowanwp.com	m Telephone No. (601) 982-3444
(This space for State use)			
APPPROVED BY Ches Welliams TITLE West Supervior DATE 11/24/04			
Conditions of approval, if any:		production of the	11/27/01