

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised March 25, 1999

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO. 30-025-20313
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-867
7. Lease Name or Unit Agreement Name: Mesa Queen Unit
8. Well No. 18
9. Pool name or Wildcat Mesa Queen Assoc.

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> Water Injection Well	
2. Name of Operator Xeric Oil & Gas Corporation	
3. Address of Operator PO Box 352 Midland, Texas 79702	
4. Well Location Unit Letter <u>N</u> : <u>330</u> feet from the <u>South</u> line and <u>2310</u> feet from the <u>West</u> line Section <u>17</u> Township <u>16S</u> Range <u>32E</u> NMPM Lea County	
10. Elevation (Show whether DR, RKB, RT, GR, etc.) 4337' DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: Re-instate TA status <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. Contact NMOCD to witness pressure test (give 24 hr advance notice)
2. Nipple up to injection head to kill truck.
3. Circulate casing with treated water.
4. Pressure test to 500# for 30 minutes recording results on chart.
5. Nipple down injection head from kill truck.
6. Re-instate Temporarily Abandon Status.

This Approval of Temporary
Abandonment Expires 5/25/06

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Glenda Hunt TITLE Sr. Production Analyst DATE 5/18/01

Type or print name Glenda Hunt

915-683-3650
Telephone No.

(This space for State use)

ORIGINAL SIGNED BY

MAY 25 2001

APPROVED BY GARY WILSON TITLE FIELD MANAGER DATE 5/18/01

Conditions of approval, if any: FIELD WORK

JCSG

