Office		of New Mex			Form C-103		
District I	Energy, Miner	als and Natura	al Resources	WELL API NO.	Revised March 25, 1999		
1625 N. French Dr., Hobbs, NM 882 District II		30-025-00383					
811 South First, Artesia, NM 88210 District III	OIL CONSE 1220 So	5. Indicate Type of Lease					
1000 Rio Brazos Rd., Aztec, NM 874	410	STATE 🗹 FEE 🗆					
District IV 1220 S. St. Francis Dr., Santa Fe, NN 87504	M Santa	6. State Oil & Gas Lease No. B-9683					
	NOTICES AND REPORTS	ON WELLS		7. Lease Name or	Unit Agreement Name:		
(DO NOT USE THIS FORM FOR P DIFFERENT RESERVOIR. USE "A PROPOSALS.)					n Ranch Unit		
1. Type of Well: Oil Well Gas W	ell 🗌 Other						
2. Name of Operator			····	8. Well No.			
Grand Banks Energy	· · · · · · · · · · · · · · · · · · ·		<u></u>	1	· · · · · · · · · · · · · · · · · · ·		
3. Address of Operator	COF Midland Taxas 70704			9. Pool name or Wildcat			
4. Well Location	00E, Midland, Texas 79705)		Wolfcamp			
11. Cho	10. Elevation (Sho 4 eck Appropriate Box to	302' GL	ture of Notice,	Report or Other	Data		
NOTICE O PERFORM REMEDIAL WOR	OF INTENTION TO: RK PLUG AND ABAND	DON 🗆	SUE REMEDIAL WOR		PORT OF: ALTERING CASING		
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DF	RILLING OPNS. 🔲			
PULL OR ALTER CASING			CASING TEST A CEMENT JOB		ABAND CAMENT		
OTHER:			· · · · · · · · · · · · · · · · · · ·	porary Abandonment	V		
				allow and the state of the stat	including estimated date		
12. Describe proposed or co	work). SEE RULE 1103. 1	ly state all pert For Multiple C	ompletions: Atta	ch wellbore diagram	of proposed completion		
 Describe proposed or co of starting any proposed or recompilation. Recent well work was perfor 	work). SEE RULE 1103. 1 med to establish the fact th	For Multiple Co at this wells m	ompletions: Atta	ch wellbore diagram	of proposed completion		
 Describe proposed or co of starting any proposed or recompilation. Recent well work was perfor and, as such, the well was ten 	work). SEE RULE 1103. 1 med to establish the fact th	For Multiple Co at this wells m	ompletions: Atta	ch wellbore diagram	of proposed completion		
 12. Describe proposed or co of starting any proposed or recompilation. Recent well work was perfor and, as such, the well was ten Well work recap: 	work). SEE RULE 1103. 1 med to establish the fact th mporarily abandoned as he	For Multiple Co at this wells m	ompletions: Atta	ch wellbore diagram	of proposed completion		
 Describe proposed or co of starting any proposed or recompilation. Recent well work was perfor and, as such, the well was ten 	work). SEE RULE 1103. 1 med to establish the fact th mporarily abandoned as he is at 9090'). at 9040'. Test RBP to 1000 sults on chart meter. Retriev	For Multiple C at this wells m erein described psi. OK. Unse	echanical casing	ch wellbore diagram <i>integrity satisfied O</i> ted 7" casing to 500 p	of proposed completion <i>CD Rule 203.C.(1)(a).</i> psi. Held pressure for		
 12. Describe proposed or coord starting any proposed or recompilation. Recent well work was perfort and, as such, the well was teached well work recap: (Highest existing perforation Set RBP at 9050' and packer 30+ minutes and recorded resonant set and	work). SEE RULE 1103. 1 med to establish the fact th mporarily abandoned as he is at 9090'). at 9040'. Test RBP to 1000 sults on chart meter. Retriev	For Multiple C at this wells m erein described psi. OK. Unse	echanical casing	ch wellbore diagram <i>integrity satisfied O</i> ted 7" casing to 500 p	of proposed completion <i>CD Rule 203.C.(1)(a).</i> psi. Held pressure for		
 12. Describe proposed or coord starting any proposed or recompilation. <i>Recent well work was perfor and, as such, the well was ter</i> <u>Well work recap:</u> (Highest existing perforation Set RBP at 9050' and packer 30+ minutes and recorded respacker fluid. Laid down tubin 	work). SEE RULE 1103. 1 med to establish the fact th mporarily abandoned as he is at 9090'). at 9040'. Test RBP to 1000 sults on chart meter. Retriev ng. NU wellhead.	For Multiple C at this wells m erein described psi. OK. Unse ed packer and	echanical casing echanical casing at packer and test RBP. Set CIBP at	ch wellbore diagram <i>integrity satisfied O</i> ted 7" casing to 500 p t 9000'. Circulated en	of proposed completion <i>CD Rule 203.C.(1)(a).</i> psi. Held pressure for		
 12. Describe proposed or coord starting any proposed or recompilation. <i>Recent well work was perfor and, as such, the well was ter</i> <u>Well work recap:</u> (Highest existing perforation Set RBP at 9050' and packer 30+ minutes and recorded respacker fluid. Laid down tubin FINAL REPORT 2-23-01. 	work). SEE RULE 1103. 1 med to establish the fact th mporarily abandoned as he is at 9090'). at 9040'. Test RBP to 1000 sults on chart meter. Retriev ng. NU wellhead.	For Multiple C at this wells m erein described psi. OK. Unse ed packer and st.	ompletions: Atta echanical casing at packer and test RBP. Set CIBP at This Approva Abandonment	ch wellbore diagram integrity satisfied O ted 7" casing to 500 p t 9000'. Circulated er	of proposed completion <i>CD Rule 203.C.(1)(a).</i> psi. Held pressure for		
 12. Describe proposed or coord starting any proposed or recompilation. <i>Recent well work was perfor and, as such, the well was ter</i> Well work recap: (Highest existing perforation Set RBP at 9050' and packer 30+ minutes and recorded respacker fluid. Laid down tubin FINAL REPORT 2-23-01. Recorded pressure chart is attracted 	work). SEE RULE 1103. I med to establish the fact th mporarily abandoned as he is at 9090'). at 9040'. Test RBP to 1000 sults on chart meter. Retriev ng. NU wellhead. tached as evidence of the test mation above is true and com	For Multiple C at this wells m erein described psi. OK. Unse ed packer and st.	echanical casing echanical casing at packer and test RBP. Set CIBP at This Approva Abandonment est of my knowle	ch wellbore diagram integrity satisfied O ted 7" casing to 500 p t 9000'. Circulated er	of proposed completion <i>CD Rule 203.C.(1)(a).</i> psi. Held pressure for		
 12. Describe proposed or coord starting any proposed or recompilation. <i>Recent well work was perfor and, as such, the well was ter</i> <u>Well work recap:</u> (Highest existing perforation Set RBP at 9050' and packer 30+ minutes and recorded respacker fluid. Laid down tubin FINAL REPORT 2-23-01. Recorded pressure chart is attended to the pressure cha	work). SEE RULE 1103. I med to establish the fact th mporarily abandoned as he is at 9090'). at 9040'. Test RBP to 1000 sults on chart meter. Retriev ng. NU wellhead. tached as evidence of the test mation above is true and com	For Multiple C at this wells m erein described psi. OK. Unse ed packer and st.	echanical casing echanical casing at packer and test RBP. Set CIBP at This Approva Abandonment est of my knowle	ch wellbore diagram integrity satisfied O ted 7" casing to 500 p t 9000'. Circulated en 1 Of Temporary Expires	of proposed completion <i>CD Rule 203.C.(1)(a).</i> Desi. Held pressure for thire casing volume with 3/27/06 DATE: Mar 5, 2001		
 12. Describe proposed or coord starting any proposed or recompilation. <i>Recent well work was perfor and, as such, the well was ter</i> <u>Well work recap:</u> (Highest existing perforation Set RBP at 9050' and packer 30+ minutes and recorded respacker fluid. Laid down tubin FINAL REPORT 2-23-01. Recorded pressure chart is attacked to the information SIGNATURE: Machine SIGNATURE: Machine Signature Starter St	work). SEE RULE 1103. I med to establish the fact th mporarily abandoned as he is at 9090'). at 9040'. Test RBP to 1000 sults on chart meter. Retriev ng. NU wellhead. tached as evidence of the test mation above is true and com	For Multiple C at this wells m erein described psi. OK. Unse ed packer and st.	echanical casing echanical casing at packer and test RBP. Set CIBP at This Approva Abandonment est of my knowle	ch wellbore diagram integrity satisfied O ted 7" casing to 500 p t 9000'. Circulated en 1 Of Temporary Expires	of proposed completion <i>CD Rule 203.C.(1)(a).</i> Dosi. Held pressure for thire casing volume with 3/2.7/0.6 DATE: Mar 5, 2001 the No. (915) 686-9790		
 12. Describe proposed or coord starting any proposed or recompilation. <i>Recent well work was perfor and, as such, the well was ter</i> <u>Well work recap:</u> (Highest existing perforation Set RBP at 9050' and packer 30+ minutes and recorded respacker fluid. Laid down tubin FINAL REPORT 2-23-01. Recorded pressure chart is attact I hereby certify that the information SIGNATURE: MCC Type or print name Terry 	work). SEE RULE 1103. I med to establish the fact th mporarily abandoned as he is at 9090'). at 9040'. Test RBP to 1000 sults on chart meter. Retriev ng. NU wellhead. tached as evidence of the test mation above is true and com	For Multiple C at this wells m erein described psi. OK. Unse red packer and st. mplete to the b TITLE: A	echanical casing echanical casing at packer and tess RBP. Set CIBP at Abandonment est of my knowle gent	ch wellbore diagram <i>integrity satisfied O</i> ted 7" casing to 500 p t 9000'. Circulated er 1 of Temporary Expires dge and belief. Telephor	of proposed completion <i>CD Rule 203.C.(1)(a).</i> Dosi. Held pressure for thire casing volume with 3/2.7/0.6 DATE: Mar 5, 2001 the No. (915) 686-9790		
 12. Describe proposed or coord starting any proposed or recompilation. Recent well work was perfor and, as such, the well was term well work recap: (Highest existing perforation Set RBP at 9050' and packer 30+ minutes and recorded respacker fluid. Laid down tubin FINAL REPORT 2-23-01. Recorded pressure chart is attact I hereby certify that the inform SIGNATURE: Type or print name Terry (This space for State use) 	work). SEE RULE 1103. 1 med to establish the fact th mporarily abandoned as he is at 9090'). at 9040'. Test RBP to 1000 sults on chart meter. Retriev ng. NU wellhead. tached as evidence of the test mation above is true and com M. Duffey	For Multiple C at this wells m erein described psi. OK. Unse red packer and st. mplete to the b TITLE: A	echanical casing echanical casing at packer and test RBP. Set CIBP at This Approva Abandonment est of my knowle	ch wellbore diagram <i>integrity satisfied O</i> ted 7" casing to 500 p t 9000'. Circulated er 1 Of Temporary Expires dge and belief. Telephon	of proposed completion <i>CD Rule 203.C.(1)(a).</i> Desi. Held pressure for thire casing volume with 3/27/06 DATE: Mar 5, 2001		



, e



Daily Report

• • •

AFE#	Lease	Well#	Description	Date	Field	County	State	Activity Description	Daily\$	CumS
1001	Anderson Ranch Unit	1	Temporarily abandon wellbore	19-Feb-01	Anderson Ranch	Lea	NM	MIRU Key Energy Services rig.	900	900
				20-Feb-01	Anderson Ranch	Lea	NM	ND WH. RU rig. Install BOP. TOOH w/ 317 jts of 2-7/8" tubing. PU 6-1/8" bit and scraper and 2 jts of tubing. RIH. Install TIW valve. SDFN.	2,318	4,118
				21-Feb-01	Anderson Ranch	Lea	NM	Open TIW valve. No pressure. RU tbg testers. GIH testing 317 joints. Found one split joint. TOOH. LD 25 jts. PU 7* packer/RBP. RIH w/ 158 jts SDFN.	5,361	9,479
				22-Feb-01	Anderson Ranch	Lea	NM	Open well w/ no pressure. FIH and set RBP at 9050' and packer at 9040' Test plug to 1000 psi. Test casing to 500 psi. OK. Released packer and plug, retrieved plug and TOOH. RIH with 7" CIBP and set at 9000'. LD one joint. SDFN.		15,814
				23-Feb-01	Anderson Ranch	Lea	NM	Open well, Circ 260 bbls of packer fluid, TOOH laying down tubing, ND BOP, NU WH, RDMO, FINAL REPORT	4,456	20,270