

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Box Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002532088
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil / Gas Lease No.	
7. Lease Name or Unit Agreement Name	WEST DOLLARHIDE DRINKARD UNIT
8. Well No.	137
9. Pool Name or Wildcat	DOLLARHIDE TUBB DRINKARD
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	GR-3166', KB-3179'

SUNDRY NOTICES AND REPORTS ON WELL
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:	OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator	TEXACO EXPLORATION & PRODUCTION INC.
3. Address of Operator	205 E. Bender, HOBBS, NM 88240
4. Well Location	Unit Letter <u>O</u> : <u>1125</u> Feet From The <u>S</u> Line and <u>2450</u> Feet From The <u>E</u> Line Section <u>19</u> Township <u>24-S</u> Range <u>38-E</u> NMPM <u>LEA</u> COUNTY

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPERATION <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-01-98: MIRU. PULL RDS & PMP.
 4-03-98: INSTL BOP. PULL OUT OF HLE W/209 JTS 2 7/8" TBG, TA, 11 JTS TBG, 1-IPC JT, SN, MUD ANCHOR. RAN 4 3/4" BIT & 5 1/2" CSG SCRAPER TO 7034'.
 4-04-98: WELLCHECK 2 7/8" TBG OUT OF HLE. RAN 5 1/2" CIBP ON WL & SET @ 7030'.
 4-06-98: TIH W/SONIC HAMMER ON 2 7/8" TBG. ACID WSH DRINKARD ABO CSG PERFS 6639-6985' W/120 BBLS 2% KCL & 2000 GALS 15% NEFE HCL. DROP BALL OPEN SLEEVE. RU SWAB. START FL @ 1400'. END FL @ 3500'.
 4-07-98: PULL OUT OF HLE W/SN, 1-IPC JT, 12 JTS 2 7/8" TBG (377.50'), TA, 209 JTS 2 7/8" TBG (6578.93') & TBG SUBS. REM BOP. SN @ 7007'.
 4-08-98: PUMP 70 BBL/S 2% KCL FW DN ANNULAS & 30 BBLS DN TBG. RAN GAS ANCHOR ON PUMP, SNKR BARS, RDS. LOAD TBG W/10 BBLS 2% KCL. SPACE PUMP @ 7.5". PRESS TBG TO 500#-OK. RIG DOWN. ON PRODUCTION @ 1:00 PM. PMPNG & TESTING.
 4-11-98: SCALE SQUEEZED, VIA CSG, W/3 DRUMS TECHN-HIB 793 MIXED IN 30 BBLS PROD WTR. FLSH W/250 BBLS PROD WTR. ON PRODUCTION @ 9:00 AM 4-13-98.
 4-22-98: ON 24 HR OPT. PUMPED 20 BO, 156 BW, & 11 MCF.
 FINAL REPORT

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Denise Leake TITLE Engineering Assistant DATE 4/28/98
 TYPE OR PRINT NAME J. Denise Leake Telephone No. 397-0405

(This space for State Use) ORIGINAL SIGNED BY CHRIS WILLIAMS
 DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE 4Y 05 1998
 CONDITIONS OF APPROVAL, IF ANY: