

DUPLICATE

NEW MEXICO OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

6-1-56

PACKER-SETTING AFFIDAVIT
(Dual Completions)

STATE OF NEW MEXICO)
County of Lea) ss

T. H. Taylor, being first duly sworn according to law, upon his oath deposes and says:

That he is of lawful age and has full knowledge of the facts herein below set out.

That he is employed by TEXACO Inc. in the capacity of Production Foreman and as such is its authorized agent.

That on Feb. 24, 19 60, he personally supervised the setting of a Baker Model "D" Ret-Prod. Packer in TEXACO Inc.'s
(Make and Type of Packer) (Operator)

United Royalty "A" Well No. 4, located in Unit
(lease)
Letter K, Section 19, Township 24-S, Range 38-E, NMPM,
Lea County, New Mexico.

That said packer was set at a subsurface depth of 6540 feet,
said depth measurement having been furnished by McCullough Tool Company.

That the purpose of setting this packer was to effect a seal in the annular space between the two strings of pipe where the packer was set so as to prevent the commingling, within the well-bore, of fluids produced from a stratum below the packer with fluids produced from a stratum above the packer. That this packer was properly set and that it did, when set, effectively and absolutely seal off the annular space between the two strings of pipe where it was set in such manner as that it prevented any movement of fluids across the packer.

TEXACO Inc.
(Company)

T. H. Taylor
(its Agent)

Subscribed and sworn to before me this the 25 day of Feb., AD, 19 60.

Arthur B. Williams
Notary Public in and for the County of Lea.

My Commission Expires April 12, 1961.

HOBBS OFFICE OCC
1960 MAR 10 AM 10:39

P. O. Box 352
Midland, Texas

March 15, 1960

New Mexico Oil Conservation Commission
P. O. Box 2045
Hobbs, New Mexico


Re: Packer Leakage Test, United
Royalty "A" Well No. 4,
Unit "K", Section 19, T-24-S,
R-38-E, Dollarhide (Queen)
and Drinkard Pools, Lea County,
New Mexico

Attention: Mr. Joe D. Ramey

Gentlemen:

Attached is a corrected packer leakage test report for the subject well. The pressures shown for Flow Test No. 1 on the packer leakage test form submitted March 11, 1960, were shown in the incorrect completion columns.

Yours very truly,


S. C. Blevins, Jr.
Assistant District Superintendent

LNF-MAB

Attachments