Submit 3 Copies to Appropriate District Office

State of New Mexico Energy, Minerals and Natural Resources Department

	Form C-103
4	Revised 1-1-

OIL CONSERVATION DIVISION 2040 Pacheco St. Santa Fe, NM 87505					WELL API No. 30 025 1			
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, I	INIVI O7	505		₅Indicate Typ		STATE	FEE
DISTRICT III - 1000 Rio Brazos Rd., Aztec, NM 87410					6State Oil & 0 B-1732	Gas Lease No		
(DO NOT USE THIS FORM FOR P DIFFERENT RES	OTICES AND REPORTS OF ROPOSALS TO DRILL OR TO DE ERVOIR. USE "APPLICATION FO C-101) FOR SUCH PROPOSALS	EEPEN (OR PER	OR PLUG BACI	К ТО А	₁Lease Nam	e or Unit Agre arhide Drir	eement Name	
Type of Well: OIL GAS WELL WELL	OTHER							
₂Name of Operator Texaco E&P Inc.					₃Well No. 13			
3Address of Operator P.O. Box 3109, Midland, Texas	79702				₃Pool name o Dollarhid		,Tubbs,Quee	en
4Well Location	Feet From The Sout			330		-	\\/oot	
Unit Letter M :330	Feet From TheSout		_ Line and	330	Feet Fro	om The	West	Line
Section 20	Township 249		lange	38E	NMPM		Lea	County
	₁₀Elevation (<i>Show whe</i>	∍ther DF, F	RKB, RT, GR, etc	:.)				
11 Check	Appropriate Box to Indica	ate Na	ture of Not	ice, Rep	ort, or O	ther Data	а	
NOTICE OF	INTENTION TO:			SUBS	SEQUEN	IT REPO	ORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	\boxtimes	REMEDIAL WO	ORK		Al	LTERING CASIN	νG [
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE D	RILLING O	PNS.	PL	UG AND ANBA	NDONMENT [
PULL OR ALTER CASING]	;	CASING TEST	AND CEME	NT JOB			-
OTHER:		_ 🔲	OTHER:					[
12Describe Proposed or Completed Opera work) SEE RULE 1103.	tions (Clearly state all pertinent details	, and give						
1) Notify OCD of intent to plug 2) MIRU, NU BOP 3) Set CIBP @ 6450, mix and circulate 10# mud, cap w/30 sx (Tubbs) 4) Spot 20 sx cement fm 5300-5400 (Glorieta) (F) Spot 20 sx cement fm 3617, 3717 (Queen) (C) Spot 20 sx cement fm 3617, 3717 (Queen) (C) Spot 20 sx cement fm 3617, 3717 (Queen)								

405) Spot 26 sx cement fm 3617-3717 (Queen) 3677-3907 6) Spot 20 sx cement fm 2618-2718 (b-salt) WOC/Tag 7) Spot 20 sx cement fm 1412-1512 (t-salt) WOC/Tag

- 8) Spot 20 sx cement fm 195-295 (8 5/8 shoe) WOC/Tag
- 9) Spot 5 sx cement fm 50'
- 10) RDMO, cut off well head, install dry hole marker, clean location

hereby certify that the informat	ion above is true and complete to the best	of my knowledge and ballef	
SIGNATURE /	Califf	TITLE Engineer	DATE 12-01-99
TYPE OR PRINT NAME JIM COI	bitt		TELEPHONE NO. (915) 688-4438
(This space for State Use)	Orig. Signed by Paul Kautz Geologist		NFC - 2 1990

CONDITIONS OF APPROVAL, IF ANY:

APPROVED BY

