Submit 3 Conica o Appropriate District Office		ew Mexico aral Resources Department		Form C-103 Revine 1-1-89
OSTRICT I		TION DIVISION	WELL API NO.	
	P.O. Bo		30-025-122	229
ISTRICT II O. Drawer DD, Arleain, NM 88210	Santa Fe, New Mi	exico 87504-2088	S. Indicate Type of Leas	
DISTRICT III 1000 Rio Brazos Kd., Aziec, NM 87410			6. Sinte Oil & Gas Leas	
			B-1732	
DO NOT USE THIS FORM FOR DIFFERENT RE (FOR	OTICES AND REPORTS ON PROPOSALS TO DRILL OR TO DI ESERVOIR. USE "APPLICATION F IM C-101) FOR SUCH PROPOSALS	7. Lesse Name or Unit	Agroanen Name Le Drinkard Unit	
Type of Well: Oil CAS WELL WELL		Injection		
Name of Operator			S. Well No.	
Texaco Prod	ucing Inc		39	1
·	0 Hobbs, New Mexico	88240	Dollarhide Tub	-
	660 Feet From The <u>South</u>	Lips and _779_	Fest From The	_East Line
Section 28	Towestic 24S	Range 38E	MMPM Lea	County
	10. Elevaluca (Show	whether DF, RKB, RT, GR, etc.)	Led	
		3205' KB		
	ck Appropriate Box to Ind INTENTION TO:		leport, or Other Da BSEQUENT REP	
	7			
ERFORM REMEDIAL WORK	PLUG AND ABANDON			ERING CASING
EMPORARILY ABANDON	CHANGE PLANS		gopns. 🔲 plu	
JLL OR ALTER CASING]	CASING TEST AND C		
THER:		OTHER:		
work) SEE RULE 1103. P & A Well 9	Operations (Clearly state all pertinent d -18-90 rt on reverse)	etails, and give pertinent dates, incl	uting estimated date of star	ing any proposed
I hanny curity that the infestmentes show	- In true and complete to the best of my know	radge and belief.		
	son	Engr. Asst		DATE 9-27-90
TYPE OR PROT NAME L.W. JC	ohnson			(505) -0426
(This space for State Uac)	6 Kalle	OIL & GAS I		DEC 1 3 1990
CONDITIONS OF AFTROVAL, IF ANY:				
D N				

HOBER OLLICE

0661 T O 190

BLISS PETROLEUM CORPORATION

(BAB (505) 393-7320 * P.O.BOX 1817 * Hobbs, N.M. 88241

Daily Workover Report

Company:	Texaco USA	Well Name: W. Dollarhide Drinkard Unit No. 39
Date	Description	Supervisor: L. White

- 09-12-90 Contacted Mr. Jerry Sexton w/ NMOGC and advised that we were moving on the above well to P & A. MIRU Tyler WS Unit No. 102. Picked up on tbg. & installed BOP. MIRU Bliss P & A equip.. POOH & laid dwn. 128 jts. 2-3/8" internal plastic coated tbg. & HOWCO on & off tool. CI BOP & SDFN.
- 09-13-90 Packer in csg. is Baker Model TSN w/ on & off tool. Ran Baker on & off tool & picked up 127 jts. new 2-3/8" work string. Tallied in hole. Tagged up on Pkr. @ 3951'. Latched onto Pkr.. Pulled to 63 pts. & sheared pins. POOH w/ tbg., retr. Hd., & 7" TSN Pkr.. Ran SN, 201 jts. tbg. & tagged CIBP @ 6210'. Hooked up pump & loaded 7" csg. w/ 10# brine. CI BOP & press. tested csg. to 350 psig. Held OK. Mixed & spotted 105 bbl. 9.5# MLF from 6210' to 3500'. POOH & laid dwn. 86 jts. tbg.. Mixed 25 sx. Class "C" cmt. & displ. dwn tbg. w/ 13.3 BMLF. First plug from 3586'- 3425'. Laid dwn. 17 jts. tbg. & bot. @ 3056'. Mixed 25 sx. Class "C" cmt. & displ. dwn tbg. w/ 11.2 BMLF. Second plug from 3056'- 2905'. Laid dwn. 54 jts. tbg. & std. back 44 jts. in derrick. SDFN
- 09-14-90 Crew to location. Dug out cellar. Welded on 7" lift nipple. RU to pull casing. Found 7" heads for power tongs would not fit. SD to get proper tong heads.
- 09-15-90 Picked up on 7" to 75 pts.. Would not come off slips. Broke out bolts below 7" slips & spool to 9-5/8". Tried to work pipe but would not to 75 pts.. RIH W/ 7" jet cutter and cut csg. @ 1128' KB. Worked csg. & could not pull @ 50 pts. above its weight. SD.
- 09-16-90 SD Sunday
- 09-17-90 Cut off 7" pull nipple. Installed BOP. RIH w/ 38 jts. tbg. & bot. @ 1179'. Mixed 25 sx. Class "C" cmt. & displ. dwn. tbg. w/ 4.0 BMLF. Calc. cmt. plug from 1179'-1030'. WOC 4 hrs.. RIH w/ sinker bar on WL, tagged cmt. @ 1022'. Plug from 1179'-1022'. Perf. @ 360'KB w/ 4 JH using 4" carrier gun. RU pump truck. CI BOP. Pumped dwn. 7" & broke circ. up 9-5/8" X 13-3/8" annulus. CI valve on 9-5/8" & pumped into csg., circ. broke out behind the 13-3/8". Did not get circ. up 7" X 9-5/8" annulus. Circ. 10 Bbl. mud into perfs. Mixed & pumped 175 sx. Class "C" cmt. dwn. 7" @ 650 psig. Had good returns up 9-5/8" X 13-3/8" annulus. Did not circ. up 7" X 9-5/8" annulus. Flushed lines & BOP. SDFN
- 09-18-90 Removed BOP. RDMO well serv. unit. RD P&A Equip. & move off. Cut off Install dry hole marker.

End of report.