

Submit 3 Copies To Appropriate District Office District I State of New Mexico Energy, Minerals and Natural Resources	Form C-103 March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-27133 5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1200 Rio Brazos Rd., Aztec, NM 87410	STATE 🗹 FEE 🗖
District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name West Vacuum Unit
PROPOSALS.) 1. Type of Well:	8. Well Number
Oil Well Gas Well Other	54
2. Name of Operator Chevron USA Inc	9. OGRID Number
3. Address of Operator	10. Pool name or Wildcat
15 Smith Rd, Midland, TX 79705 4. Well Location	Vacuum Grayburg San Andres
Unit Letter L : 2130 feet from the South line and	810 feet from the West line
Section 33 Township 17-S Range 34-E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) picos
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: UL L Sect 33 Twp 17S Rng 34E Pit type Steel Depth to Groundwater 87 Distance from nearest fresh water well Over 1000'	
Distance from nearest surface water Below-grade Tank Location ULSectTw	oRng;
2130 feet from the South line and 810 feet from the West line (Steel Tank)	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	K 227377 ALTERING CASING
TEMPORARILY ABANDON	
PULL OR ALTER CASING MULTIPLE CASING TESTA	の の の
COMPLETION CEMENT JOB	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)
OTHER: OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion	
or recompletion.	8272 82 22 92 proposed completion
1. Notified OCD with P&A intent. 7. Perf 4	holes at 250, sqz 85sx, Circ cmt to Surf
at 4110. 8 Install	WOC Tag at Surf. dry hole marker 12-6-04.
3. Displace hole w/MLF, 9.5# Brine w/12.5# salt gel P/BBL. 4. Spot 25sx, plug from 2800-2600 (Yates, B-Salt).	proved as to plugging of the Well Bore.
5. Spot 25sx, plug from 1700-1500 (8 5/8 Shoe). 6. Perf 4 holes at 1250, saz 50sx cmt, plug from 1250, 1050, W/OC Tea at 1050.	pility under bond is retained until
6. Perf 4 holes at 1250, sqz 50sx cmt, plug from 1250-1050, WOC Tag at 1060. Surface restoration is completed until I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.	
SIGNATURE TITLE Consulta	DATE_12-06-04
Type or print name Jimmy Bagley E-mail address:	Telephone No. 432-561-8600
(This space for State use)	
APPPROVED BY Jany - W DTLE	, DATE
Conditions of approval, if any	
GARY WWINK OC FIELD REPRESENTATIVE II/	STAFF MANAGER JAN 0 3 2005