

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions reverse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input checked="" type="checkbox"/> Water Injection Well		5. LEASE DESIGNATION AND SERIAL NO. LC-067968
2. NAME OF OPERATOR Skelly Oil Company		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P. O. Box 1351, Midland, Texas 79701		7. UNIT AGREEMENT NAME West Dollarhide Queen Sand Unit
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) 330' PSL and 2310' VEL Sec. 19-24S-38E		8. FARM OR LEASE NAME West Dollarhide Queen Sand Unit
14. PERMIT NO.		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 3164' KB		10. FIELD AND POOL, OR WILDCAT Dollarhide Queen
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 19-24S-38E
		12. COUNTY OR PARISH Lea
		13. STATE New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

- 1) Moved in pulling unit 5-11-73. Pulled tubing and packer.
- 2) Set 7" bridge plug at 3615'.
- 3) Circulated with 10# mud.
- 4) Spotted 15 sack cement plug 3537-3615'.
- 5) Spotted 100 sack cement plug 860-1377'.
- 6) Spotted 10 sack cement plug from surface to 21'.
- 7) Installed dry hole marker.

No casing was pulled. The 10-3/4" OD 28.5# casing set at 304', and the 7" OD 20# casing set at 3749' were left in the hole.

All intervals not cemented were filled with 10# mud.


Well plugged and abandoned 5-11-73.

18. I hereby certify that the foregoing is true and correct

(SIGNED) D. R. Crow **D. R. Crow** TITLE Lead Clerk DATE May 31, 1973

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY:



*See Instructions on Reverse Side