Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 30-025-09394 District II OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III 1000 Rio Brazos Rd., Aztec, NM 87410 STATE X FEE  $\square$ Santa Fe. NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A STATE A A/C 1 DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 8. Well Number 1. Type of Well: Oil Well Gas Well X Other 065 2. Name of Operator 9. OGRID Number MISSION RESOURCES CORPORATION 148381 3. Address of Operator 10. Pool name or Wildcat 1331 LAMAR, SUITE 1455 HOUSTON, TEXAS 77010-3039 JALMAT: TAN, YATES, 7-RVRS (GAS) 79240 4. Well Location 660 Unit Letter feet from the line and \_ WEST feet from the line Section 23 Township 23S Range 36E **NMPM** County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3365 'GR Pit or Below-grade Tank Application or Closure Pit type \_\_n/a \_\_Depth to Groundwater \_\_149 '\_\_ Distance from nearest fresh water well \_\_1000 '+ Distance from nearest surface water \_\_1000 '+ Below-Grade Tank: Volume 500 bbls; Construction Material Steel (Frac Tanks) Pit Liner Thickness: \_ 12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL WORK ALTERING CASING [ TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING CASING TEST AND MULTIPLE COMPLETION **CEMENT JOB** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Add Perforations & Frac. Please see attached Procedure with Wellbore Schematic. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to NMOCD guidelines \_\_\_\_\_, a general permit X or an (attached) alternative OCD-approved plan \_\_\_\_\_ TITLE Regulatory Coordinator \_DATE \_\_\_ E-mail address: nancy.gatti@mrcorp.com Type or print name Nancy K. Gatti Telephone No. 713-495-3128 For State Use Only

TITHE FIELD REPRESENT

APPROVED BY

Conditions of Approval, if any

## Mission Resources Corp. AAC-1 #65 Jalmat Field Lea County, NM December 13, 2004

## **Work Over Procedure**

- 1. MIRU work over rig. Pull tubing.
- 2. RU e-line unit.
- 3. Perforate Tansil, Yates and 7 Rivers from 2850' to 3408'.
- 4. Break down and acidize each NEW perf with PPI tool.
- 5. RIH and set packer on 4-1/2" tubing. RD work over rig.
- 6. Frac well per recommendation.
- 7. Flow and test well. Put back to sales.
- 8. Put well back on pump when well loads up.



