Submit 3 Copies To Appropriate District Office	State of Ne			Form C-103
District I 1625 N. French Dr., Hobbs, NM 87240	Energy, Minerals and	Natural Resources	WELL API NO.	May 27, 2004
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVA	TION DIVISION	30-025-0	
District III	1220 South S		5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, 1	NM 87505	STATE X	
1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas	Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name: STATE A A/C 1	
1. Type of We <u>ll:</u>			8. Well Number	
Oil Well Gas Well Other			084	
2. Name of Operator MISSION RESOURCES CORPORATION			9. OGRID Number 148381	
3. Address of Operator			10. Pool name or Wildcat	
1331 LAMAR, SUITE 1455 HOUSTON, TEXAS 77010-3039			JALMAT; TAN, YATES, 7-RVRS (GAS) 79240	
4. Well Location				
Unit Letter G :	1980 feet from the	NORTH line and	2310 feet from	n the EAST line
Section 23	Township 23	S Range 36E	NMPM	County LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
Pit or Below-grade Tank Application or Closure				
Pit typen/aDepth to Groundwater149'Distance from nearest fresh water well1000'+ Distance from nearest surface water1000'+				
Pit Liner Thickness:n/a mil		olume 500 bbls; Construction		Frac Tanks)
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
			SEQUENT REP	
PERFORM REMEDIAL WORK X	PLUG AND ABANDON			ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS		ING OPNS. 🔲	PLUG AND
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		ABANDONMENT
0.771.177	33 <u>227737</u>			07.25.26
OTHER:		OTHER:		<u> </u>
 Describe proposed or completed of starting any proposed work). or recompletion. Add Perforations & Frac.				
Please see attached Procedure with Wellbore Schematic.				
				The second secon
I hereby certify that the information al grade tank has been/will be onstructed or c	ove is true and complete t	o the best of my knowledge	and belief. I further c	ertify that any pit or below-
SIGNATURE / KINCUL K	Jalli Jacob gu		0 1	24 44 42
	·	T 11 11		
Type or print name Nancy K. Gatti	D		Teleph	one No. 713-495-3128
For State Use Only	1,11,0	E-mail address:	E II/STAFF MANAGE	•
APPROVED BY Lay	1. Wink	_ TITLE		ATEJAN 1 9 2005
Conditions of Approval, if any:				
*				

Mission Resources Corp. AAC-1 #84 Jalmat Field Lea County, NM December 13, 2004

Work Over Procedure

- 1. MIRU work over rig. Pull tubing.
- 2. RU e-line unit.
- 3. Perforate Tansil and 7 Rivers from 2827' to 3312'.
- 4. Break down and acidize each NEW perf with PPI tool.
- 5. RIH and set packer on 4-1/2" tubing. RD work over rig.
- 6. Frac well per recommendation.
- 7. Flow and test well. Put back to sales.
- 8. Put well back on pump when well loads up.



