Submit 3 Copies To Appropriate District State of New Mexico Form C-103 Office Energy, Minerals and Natural Resources May 27, 2004 District I WELL API NO. 1625 N. French Dr., Hobbs, NM 87240 District II 30-025-10720 OIL CONSERVATION DIVISION 1301 W. Grand Ave., Artesia, NM 88210 5. Indicate Type of Lease 1220 South St. Francis Dr. District III 1000 Rio Brazos Rd., Aztec, NM 87410 STATE | FEE X Santa Fe, NM 87505 District IV 6. State Oil & Gas Lease No. 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS 7. Lease Name or Unit Agreement Name: (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A W.T. MATKINS DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: 8. Well Number Oil Well Gas Well X Other 002 2. Name of Operator 9. OGRID Number MISSION RESOURCES CORPORATION 148381 3. Address of Operator 10. Pool name or Wildcat 1331 LAMAR, SUITE 1455 HOUSTON, TEXAS 77010-3039 JALMAT: TAN, YATES, 7-RVRS (GAS) 79240 4. Well Location 1980 Unit Letter SOUTH feet from the line and feet from the EAST Township 23S Range **NMPM** County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3370.7'GR Pit or Below-grade Tank Application or Closure Pit type __n/a __Depth to Groundwater __149' __Distance from nearest fresh water well __1000'+ Distance from nearest surface water __1000'+ Pit Liner Thickness: _ Below-Grade Tank: Volume 500 bbls; Construction Material Steel (Frac Tanks) 12. Check Appropriate Box to Indicate, Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK X PLUG AND ABANDON REMEDIAL WORK ALTERING CASING **TEMPORARILY ABANDON CHANGE PLANS** COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION **CEMENT JOB** OTHER: OTHER: 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. Add Perforations & Frac. Please see attached Procedure with Wellbore Schematic. I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or belowgrade tank has been/will be constructed or closed according to PMOCD guidelines ______, a general permit X or an (attached) alternative OCD-approved plan ______ Regulatory Coordinator TITLE___ _DATE_ E-mail address: nancy.gatti@mrcorp.com Type or print name Nancy K. Gatti Telephone No. 713-495-3128

OC FIELD REPRESENTATIVE ILISTAFF MANDATER JAN 1 9

Conditions of Approval, if any:

For State Use Only

Mission Resources Corp. W. T. Maktins #2 Jalmat Field Lea County, NM December 13, 2004

Work Over Procedure

- 1. MIRU work over rig. Pull tubing.
- 2. RU e-line unit.
- 3. Perforate Yates and 7 Rivers from 3212' to 3490'.
- 4. Break down and acidize each NEW perf with PPI tool.
- 5. RIH and set packer on 3-1/2" tubing. RD work over rig.
- 6. Frac well per recommendation.
- 7. Flow and test well. Put back to sales.
- 8. Put well back on pump when well loads up.



