

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-10517
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name New Mexico "M" State
8. Well Number 34
9. OGRID Number 008359
10. Pool name or Wildcat Langlie Mattix 7R-Qn-Gryburg

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☐ Other Water Injection

2. Name of Operator
GP II Energy, Inc.

3. Address of Operator
P.O. Box 50682 Midland, TX 79710

4. Well Location
Unit Letter D : 660 feet from the North line and 660 feet from the West line
Section 29 Township 22S Range 37E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
GR 3382'

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:


REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

Approved as to plugging of the Well Bore.
Liability under bond is retained until
surface restoration is completed.



I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOC guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Linda Edwards TITLE Production Clerk DATE 1/18/05

Type or print name Linda Edwards
For State Use Only

E-mail address: linda@gp2energy.com Telephone No. 432-684-4748

APPROVED BY: Larry W. Wink
Conditions of Approval (if any):

OFFICIAL REPRESENTATIVE OF STATE

DATE JAN 25 2005

MAYO MARRS CASING PULLING INC.
BOX 863
KERMIT, TEXAS 79745

GP II ENERGY, INC.

Lease: NEW MEXICO "M" STATE # 34
Project: P & A – CEMENTING REPORT

08-03-04 - SQUEEZE 80 SXS FROM 3680' TO SURFACE

INSTALL DRY HOLE MARKER

MAYO MARRS CASING PULLING INC.

GP II ENERGY, INC.

Lease: NEW MEXICO -M- STATE # 34

Project: P & A -

JOB #

07-30-04 (2 HRS RIG)

NOTIFY OCD - MIRU - DIG & LINE PIT PER OCD NEW RULES -

08-02-04 (10 HRS RIG)

WORK TO GET SLIPS OUT FOR 1 HR - REMOVE SLIPS - ONLY 2 INCHES STRETCH - WORK TUBING - PIPE PART @ 384' - BRING IN TUBING FROM 1ST WELL - GO TO KERMIT FOR FISHING TOOLS - RIH & SPEAR INTO FISH - WORK TUBING - PART @ 52,000# - GO TO KERMIT FOR MMCPI 1 1/2" DRILL PIPE - MOVE IN TO LOCATION - CLOSE IN WELL

8-03-04 (8 HRS RIG)

RIH CATCH PART - WORK SPEAR OUT OF HOLE - RIH WITH SPEAR & CATCH FISH - WORK & PUMP ON TUBING FOR 3 HRS - CALL OCD - WAIT ON ORDERS FROM OCD - TEST WELL - SQUEEZE 80 SXS - CLOSE IN @ 400# - WOC 2 HRS & TAG @ SURFACE - RIG DOWN - CUT OFF WELLHEAD & ANCHORS - INSTALL DRY HOLE MARKER - LEVEL PIT & CELLAR - MOVE OUT