Office		New Mexico	Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Ellergy, Millierais	and Natural Resources	WELL API NO.
District II	OIL CONGEDA	IATION DIVIGION	30-025-09634
1301 W. Grand Ave., Artesia, NM 88210 District III	OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe	e, NM 87505	6. State Oil & Gas Lease No.
87505			141560
SUNDRY NOT	ICES AND REPORTS ON	N WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPODIFFERENT RESERVOIR. USE "APPLI	CATION FOR PERMIT" (FORN	'EN OR PLUG BACK TO A A C-101) FOR SUCH	
PROPOSALS.)	•		Cooper Jal Unit
Type of Well: Oil Well     Name of Operator	Gas Well  Other	X Injector	8. Well Number 216 w
2. Name of Operator	SDG Resources L. P.		9. OGRID Number 193003
3. Address of Operator	P. O. Box 1390		10. Pool name or Wildcat JALMAT:
·	Montrose, CO 81401		10. Pool name or Wildcat JALMAT: Tansill, Yates & 7-Rivers; LANGLIE
			MATTIX: 7-Rivers, Queen
4. Well Location			
Unit Letter M	: 660 feet from the	_SOUTH line and	660 feet from the WEST Line
Section 24	Township		
SATE WE THE		nether DR, RKB, RT, GR, etc.,	NMPM LEA County
And the second s		3,325' GR	
Pit or Below-grade Tank Application			
Pit type_DIRTDepth to Groundwater130 feetDistance from nearest fresh water well_>1000 feet_ Distance from nearest surface water_>1000 feet			
Pit Liner Thickness: 12 mil Below-Grade Tank: Volume 200 bbls; Construction Material Synthetic			
12. Check	Appropriate Box to Inc	dicate Nature of Notice,	
		aroute riutare of riotice,	Report of Other Data
NOTICE OF IN		SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK   ALTERING CASING			
TEMPORARILY ABANDON	CHANGE PLANS	☐ COMMENCE DRI	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB
OTHER:		OTUED D	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
13. Describe proposed or comp	leted operations. (Clearly	state all pertinent details, and	dive pertinent dates including actioned date
13. Describe proposed or composed wo	oleted operations. (Clearly ork). SEE RULE 1103. Fo	state all pertinent details, and	d give pertinent dates, including estimated date
13. Describe proposed or comp	oleted operations. (Clearly ork). SEE RULE 1103. Fo	state all pertinent details, and	well to 3,780', Acidized w/4,200 gals.  If give pertinent dates, including estimated date tach wellbore diagram of proposed completion
13. Describe proposed or comp of starting any proposed we or recompletion.	ork). SEE RULE 1103, Fo	state all pertinent details, and or Multiple Completions: Att	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
13. Describe proposed or composed wo	ork). SEE RULE 1103, Fo	state all pertinent details, and or Multiple Completions: Att	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
<ul><li>13. Describe proposed or comp of starting any proposed we or recompletion.</li><li>Objective: Deepen well to 3,70</li></ul>	ork). SEE RULE 1103, Fo	state all pertinent details, and or Multiple Completions: Att	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
<ol> <li>Describe proposed or comp of starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing and proposed well to 3,70</li> </ol>	0', washed and acidized from the state of th	or Multiple Completions: Attorned and April 1985 an	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
<ol> <li>Describe proposed or compof starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing and RIH with 4 3/4" bit &amp; 6 3 1/2" dr</li> </ol>	0', washed and acidized from the state of th	or Multiple Completions: Attorned and Attorn	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion
<ol> <li>Describe proposed or compof starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing and RIH with 4 3/4" bit &amp; 6 3 1/2" draw the deepened 4 3/4" hole from 3,214</li> </ol>	0', washed and acidized from the state of th	or Multiple Completions: Attorned April 1985 April 2015	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix)
<ol> <li>Describe proposed or compof starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing and starting any proposed well to 3,70</li> <li>RIH with 4 3/4" bit &amp; 6 3 1/2" draw the deepen of 4 3/4" hole from 3,21/4.</li> <li>Washed open hole 3,035'-3,780</li> </ol>	ork). SEE RULE 1103. For one of the control of the	or Multiple Completions: Attorned April 1985 April 2015	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix)
<ol> <li>Describe proposed or compof starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing and starting any proposed well to 3,70</li> <li>RIH with 4 3/4" bit &amp; 6 3 1/2" draw draw draw draw draw draw draw draw</li></ol>	ork). SEE RULE 1103. For one of the control of the	or Multiple Completions: Attorned April 1985 April 2015	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix)
<ol> <li>Describe proposed or compof starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing and starting and starting any proposed well to 3,70</li> <li>RIH with 4 3/4" bit &amp; 6 3 1/2" draw draw draw draw draw draw draw draw</li></ol>	ork). SEE RULE 1103. For one of the control of the	or Multiple Completions: Attorned April 1985 April 2007	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  & Langlie Mattix)
<ol> <li>Describe proposed or compof starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing: RIH with 4 3/4" bit &amp; 6 3 1/2" dr</li> <li>Deepened 4 3/4" hole from 3,216</li> <li>Washed open hole 3,035'-3,786</li> <li>Acidized open hole 3,035'-3,787</li> <li>POOH with 2 7/8" work string</li> <li>RIH with 5 1/2" x 2 3/8" Baker 1</li> </ol>	O', washed and acidized from the state of th	or Multiple Completions: Attorned April 1985 April 2085	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix)  Swith inhibited packer fluid
<ol> <li>Describe proposed or comp of starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing and subjective in the subje</li></ol>	O', washed and acidized from the state of th	or Multiple Completions: Attorned April 1985 April 2085	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix)  Swith inhibited packer fluid
<ol> <li>Describe proposed or compost of starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing and starting in the starting in th</li></ol>	O', washed and acidized from the state of th	or Multiple Completions: Attorned April 1985 April 2085	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix)  Swith inhibited packer fluid
<ol> <li>Describe proposed or compost of starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing and starting in the starting in th</li></ol>	O', washed and acidized from the state of th	or Multiple Completions: Attorned April 1985 April 2085	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix)  Swith inhibited packer fluid
<ol> <li>Describe proposed or comp of starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing and starting in the s</li></ol>	ork). SEE ROLE 1103. For one of the control of the	or Multiple Completions: Attorned April Completions: Attorned April Completions: Attorned April Completions: Attorned April Completions and 4 3/4" bit. water using Perf-Clean Tool. NEFE HCl acid. Cool. er to 2,995'; circulate annulus d not hold – casing leak. Pull	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix  s with inhibited packer fluid.  chart for NMOCD.
<ol> <li>Describe proposed or comp of starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing: 3. RIH with 4 3/4" bit &amp; 6 3 1/2" dr</li> <li>Deepened 4 3/4" hole from 3,210</li> <li>Washed open hole 3,035'-3,780</li> <li>Acidized open hole 3,035'-3,780</li> <li>Acidized open hole 3,035'-3,780</li> <li>RIH with 5 1/2" x 2 3/8" Baker 1</li> <li>Set packer and test annulus to 5</li> <li>Shut well in.</li> </ol>	ork). SEE RULE 1103. For one of the control of the	or Multiple Completions: Attorned April 1985	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix  s with inhibited packer fluid.  chart for NMOCD.
<ol> <li>Describe proposed or comp of starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing: 3. RIH with 4 3/4" bit &amp; 6 3 1/2" dr</li> <li>Deepened 4 3/4" hole from 3,210</li> <li>Washed open hole 3,035'-3,780</li> <li>Acidized open hole 3,035'-3,780</li> <li>Acidized open hole 3,035'-3,780</li> <li>RIH with 5 1/2" x 2 3/8" Baker 1</li> <li>Set packer and test annulus to 5</li> <li>Shut well in.</li> </ol>	ork). SEE RULE 1103. For one of the control of the	or Multiple Completions: Attorned April 1985	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix  s with inhibited packer fluid.  chart for NMOCD.
<ol> <li>Describe proposed or comp of starting any proposed we or recompletion.</li> <li>Objective: Deepen well to 3,70</li> <li>MIRU Pulling Unit.</li> <li>POOH with 2 3/8" IPC tubing: 3. RIH with 4 3/4" bit &amp; 6 3 1/2" dr</li> <li>Deepened 4 3/4" hole from 3,210</li> <li>Washed open hole 3,035'-3,780</li> <li>Acidized open hole 3,035'-3,780</li> <li>Acidized open hole 3,035'-3,780</li> <li>RIH with 5 1/2" x 2 3/8" Baker 1</li> <li>Set packer and test annulus to 5</li> <li>Shut well in.</li> </ol>	ork). SEE ROLE 1103. For one of the control of the	state all pertinent details, and or Multiple Completions: Attoom 3,035' to 3,780' (Jalmat & Jodel AD-1 tension packer. String. th drill collars and 4 ¾" bit. water using Perf-Clean Tool. NEFE HCl acid. Tool. er to 2,995'; circulate annulus d not hold – casing leak. Pull to the best of my knowledge guidelines □, a general permit □	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix)  s with inhibited packer fluid.  chart for NMOCD.  and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan
13. Describe proposed or compost of starting any proposed we or recompletion.  Objective: Deepen well to 3,70  1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing: 3. RIH with 4 ¾" bit & 6 3 ½" dr 4. Deepened 4 ¾" hole from 3,214 5. Washed open hole 3,035'-3,78 6. Acidized open hole 3,035'-3,78 7. POOH with 2 7/8" work string 8. RIH with 5 ½" x 2 3/8" Baker 19 9. Set packer and test annulus to 5 10. Shut well in.	o', washed and acidized from the state of th	or Multiple Completions: Attorned Multiple Complete Mul	and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE_1/26/05_
13. Describe proposed or compost of starting any proposed we or recompletion.  Objective: Deepen well to 3,70  1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing and a starting any proposed we or recompletion.  1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing and a starting are starting as a starting and a starting are starting as a starting and a starting are starting and a starting are starting as a starting and a starting are starting and a starting are starting and a starting are starting and a starting and a starting are starting and a starting and a starting are starting are starting and a starting are starting are starting and a starting are starting are starting and a starting are starting are starting and a starting are starting are starting are starting and a starting are starting are starting are starting and a starting are s	o', washed and acidized from the state of th	or Multiple Completions: Attorned Multiple Complete Mul	and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE_1/26/05_
13. Describe proposed or compost of starting any proposed we or recompletion.  Objective: Deepen well to 3,70  1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing: 3. RIH with 4 ¾" bit & 6 3 ½" dr 4. Deepened 4 ¾" hole from 3,214 5. Washed open hole 3,035'-3,78 6. Acidized open hole 3,035'-3,78 7. POOH with 2 7/8" work string 8. RIH with 5 ½" x 2 3/8" Baker 19 9. Set packer and test annulus to 5 10. Shut well in.	o', washed and acidized from the state of th	or Multiple Completions: Attorned Multiple Complete Mul	and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan  DATE_1/26/05_
13. Describe proposed or compost of starting any proposed we or recompletion.  Objective: Deepen well to 3,70  1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing and a starting any proposed we or recompletion.  1. MIRU Pulling Unit. 2. POOH with 2 3/8" IPC tubing and a starting are starting as a starting and a starting are starting as a starting and a starting are starting and a starting are starting as a starting and a starting are starting and a starting are starting and a starting are starting and a starting and a starting are starting and a starting and a starting are starting are starting and a starting are starting are starting and a starting are starting are starting and a starting are starting are starting and a starting are starting are starting are starting and a starting are starting are starting are starting and a starting are s	o', washed and acidized from the control of the con	or Multiple Completions: Attorned Multiple Complete Mul	d give pertinent dates, including estimated date tach wellbore diagram of proposed completion  Langlie Mattix)  s with inhibited packer fluid.  chart for NMOCD.  and belief. I further certify that any pit or belowor an (attached) alternative OCD-approved plan



