State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERVAT	TION DIVISION		14.10025 27 2007
DISTRICT I	1220 South St. Francis Dr. Santa Fe, NM 87505		WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240			30-025-05490	
DISTRICT II 1301 W. Grand Ave, Artesia, NM 88210			5. Indicate Type of Lease STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	122
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			NORTH HOBBS (G/SA) UNIT	
	APPLICATION FOR PERMIT" (Form C-101	Section 24 8. Well No. 341		
1. Type of Well: Oil Well X	Gas Well Other	0. Well 110. 341		
2. Name of Operator		9. OGRID No. 157984		
Occidental Permian Ltd.			10 P 1 W/11	Troppe (G/GA)
3. Address of Operator	NM 88240 505/397-i	8200	10. Pool name or Wildcat	HOBBS (G/SA)
1017 W. Stanolind Rd., HOBBS, NM 88240 505/397-8200 4. Well Location				
Unit Letter O: 330	Feet From The SOUTH	2310 Fe	et From The EAST	Line
		Range 37-	E NMPM	LEA County
Section 24	Township 18-S 11. Elevation (Show whether DF, RKB,		E MAI M	LEA County
	3655' GR	, ,		
Pit or Below-grade Tank Application	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK	PLUG AND ABANDON F	REMEDIAL WORK	ALTERING	3 CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	PNS. PLUG & A	ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEME	NT JOB	
OTHER:		OTHER: Return to p	roduction. Acid Treat	X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any				
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
1. RUPU. 2. Drill out CIBP @3870'.				
3. Stimulate perfs 4224-58 w/1260 g 15% NEFE HCL acid.				
4. RIH Reda ESP equipment on 131 jts 2-7/8" tbg w/drain valve. Intake set @4158'.				
5. Install QCI wellhead connection6. RDPU. Clean Location.				
6. RDPU. Clean Location.				
Rig Up Date: 12/15/2004				
Rig Down Date: 12/18/2004				
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be				
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved				
closed according to NWOCD guideling	, a general permit	plan	ve OCD-approved	
SIGNATURE KAPUT	Gillut	TITLE Workover Con	npletion Specialist DAT	E 12/29/2004
TYPE OR PRINT NAME Robert Gil	pert E-mail address:	robert gilbert@oxy.com	TELEPHONE NO.	-
For State Use Only				
APPROVED BY		TITLE PE	TROLEUM ENGINEEDA	TE
CONDITIONS OF APPROVAL IF ANY:	al fileson		A A Section of the Control of the Co	"FE B () 7 2005

CONDITIONS OF APPROVAL IF ANY: